5/001/034 Milford Copper Tailings

ANALYTICAL RESULTS

ESSEX COPPER PROCESSING PLANT

BEAVER COUNTY, UTAH EPA ID 988066064





ANALYTICAL RESULTS REPORT

ESSEX COPPER PROCESSING PLANT

Beaver County, Utah UTD988066064

Utah Department of Environmental Quality
Division of Environmental Response and Remediation
Prepared By: Jason L. Knowlton

Draft 3/29/93

Final 9/22/93

TLK

TABLE OF CONTENTS

1.0	INTR	ODUCT	TON	. 1
2.0	OBJE	CTIVES	S	. 1
3.0	SITE 3.1		IPTION	
	3.1	Operati	tional History and Waste Characteristics	. 5
	3.3	Dravio	us Investigations	. 6
	5.5	3.3.1	Site Visit Report	. 8
			Preliminary Assessment	
4.0	FIEL	D ACTIV	VITIES	. 8
7.0	4.1	Sample	e Collection and Field Observations	
	4.2	Quality	y Assurance/Quality Control	. 10
5.0	WAS	TE/SOU	JRCE CHARACTERISTICS	. 11
	5.1	Source	e Descriptions	. 11
		5.1.1	Ore/Tailings Pile	. 11
		5.1.2	Evaporation Ponds	. 13
		5.1.3	Drums	. 13
		5.1.4	Transformers	. 13
		5.1.5	Contaminated Soil	. 16
	5.2	Sample	le Locations	. 16
		5.2.1	Ore/Tailings Pile	16
		5.2.2	Evaporation Ponds	20
		5.2.3	Drums	20
		5.2.4	Transformers	20
		5.2.5	Contaminated Soil	21
	5.3	Analyt	rtical Results	21
		5.3.1	Ore/Tailings Pile	21
		5.3.2	Evaporation Ponds	21
		5.3.3	Drums	22
		5.3.4	Transformers	22
		5.3.5	Contaminated Soil	22
	5 4	Concl	lusions	

6.0	GROU	UND WATER PATHWAY	24
	6.1	Hydrogeology	24
	6.2	Targets	24
	6.3	Sample Locations	26
	6.4	Analytical Results	26
	6.5	Conclusions	28
7.0	SURF	FACE WATER PATHWAY	28
	7.1	Hydrology	. 28
	7.2	Targets	. 28
	7.3	Sample Locations	. 30
	7.4	Analytical Results	. 30
	7.5	Conclusions	. 31
8.0	SOIL	EXPOSURE AND AIR PATHWAYS	. 31
9.0	SUM	IMARY AND CONCLUSIONS	. 31
10.0	REFE	ERENCES	. 33

LIST OF FIGURES, TABLES AND ATTACHMENTS

FIGURES

Figure 1.	Site Location
Figure 2.	Detailed Site Location
Figure 3.	Site Sketch
Figure 4.	Source Locations
Figure 5.	Container and Transformer Locations
Figure 6.	Aerial Photograph
Figure 7.	Sample Locations
Figure 8.	Four Mile Radius of Influence
Figure 9.	Ground Water Sample Location
Figure 10.	Upstream Drainage Area

TABLES

Table I.	Sample Containers
Table II.	Container Summary
Table III.	Transformer Summary
Table IV.	Sample Summary
Table V.	Pond Water Field Measurements
Table VI.	Drum Contents
Table VII.	Ground Water Field Measurements

ATTACHMENTS

Appendix A.	Site Inspection Data Summary
Appendix B.	Beaver County Recorder, Anyox Property
Appendix C.	Site Photographs
Appendix D.	Signed Consent for Access to Property Form
Appendix E.	Sample Collection Documentation
Appendix F.	Analytical Results Summary
Appendix G.	Versar Analytical Results and Quality Assurance Summary
Appendix H.	Utah State Health Laboratory Analytical Results
Appendix I.	Dow Chemical Material Safety Data Sheets
Appendix J.	American Cyanamid Material Safety Data Sheets
Appendix K.	Ground Water Utilization Printouts
Appendix L.	Utah Div. of Water Rights, Selected File Information

1.0 INTRODUCTION

The Essex Copper Processing Plant is an abandoned copper ore processing facility located near the town of Milford, in Beaver County, Utah. Sampling was conducted at the site by the Utah Division of Environmental Response and Remediation (DERR) on June 1 through June 3, 1992. A Sampling Plan, dated March 26, 1991, was prepared for the site which outlined the procedures to be followed for sampling this site. This report documents and describes the field procedures, and presents the analytical results from the sampling effort. A Site Inspection Data Summary form is included as Appendix A.

The sampling activities were undertaken as part of a focused Site Inspection under authority of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA, commonly known as Superfund), and in accordance with applicable provisions of the National Oil and Hazardous Substance Pollution Contingency Plan (NCP). The purpose of the Site Inspection is to gather data to support a site decision regarding the need for further Superfund action. DERR conducts these activities under agreement with the U.S. Environmental Protection Agency (EPA).

2.0 OBJECTIVES

The scope of sampling involved the collection of: 9 soil samples, 7 of which were collected from a large ore and tailings pile; 6 sediment samples, 4 from adjacent drainages and 2 from on-site processing ponds; 2 aqueous pond samples; 1 ground water sample from an off-site domestic well; and 3 high concentration source characterization samples, 2 of which were from electrical transformers and 1 was from a drum located on-site. A trip blank was also collected for quality control purposes.

The objectives of sampling, as specifically stated in the Sampling Plan, were as follows:

- The ore and tailings materials deposited on-site will be characterized, and drum, container and transformer contents will be identified, to determine whether the source materials present a significant hazard via the soil exposure pathway and whether hazardous materials on-site have a potential to release via the air migration pathway.
- Sediments, and surface water if present, in the Big Wash and in on-site pond areas will be characterized to further assess the on-site exposure hazards and to determine the nature of leachates in the water and their potential to migrate off-site via the surface and ground water migration pathways. Field observations of the drainage basin will be made to determine if surface water can migrate off-site, cross the levee, or otherwise release into the Big Wash drainage.

- o Ground water monitoring wells will be constructed, and ground water sampled, to determine whether hazardous constituents from the site have contaminated the Milford area aquifer.
- Other location specific information, such as demographic analysis and water use survey, needed to effectively score the site under the revised HRS will be obtained during the sampling event. Waste characteristics, especially waste quantity and waste containment, will be evaluated for each waste source. Potentially impacted sensitive environments will also be identified.

Sampling objectives relating to ground water and source characterization were changed prior to the sampling event in compliance with recent EPA guidance which limits the scope of focused Site Inspections¹². Ground water monitoring wells were not constructed, as called for in the Sampling Plan. Instead, a sample was collected from an existing off-site well. Characterization of transformer and container contents was limited to 3 samples, with more reliance on drum labels and information about the nature of operations to preliminarily determine container contents.

The sampling team consisted of the following UDERR personnel:

Jason Knowlton Project Manager

Michael Storck Health and Safety Officer

J. D. Keetley Sampler


3.0 SITE DESCRIPTION


3.1 Site Location and Description

The Essex Copper site is located approximately 3 miles northwest of Milford, Utah along the north side of State Highway 2l, as indicated on Figure 1. The site consists of 142.7 acres; 72.7 acres on the south side owned by Anyox Metals, Ltd, and 70 acres on the north owned by Beaver County³. Figure 2 shows the site location in greater detail. A copy of the property boundary survey for the Anyox property, on file with the Beaver County Recorder, is attached as Appendix B.

The site is in the northern portion of the Escalante Desert in a fairly remote semi-arid area in the western portion of south-central Utah.

Sixty-four acres of copper ore and/or mill tailings and approximately 150 to 200 drums are present on-site. Many of the drums are full, corroded and/or leaking. There are several large storage tanks on-site, most of which contain only a small amount of solid material in their bottoms, and a few with unknown contents. One of these for liquid storage is marked "ACID". Numerous electrical transformers are present which may contain PCBs, many of which appear to be leaking. Several evaporation ponds are present on-site, constructed atop apparent tailing







UTAH DEPARTMENT OF HEALTH

BUREAU OF ENVIRONMENTAL RESPONSE AND REMEDIATION


Figure 1

SITE LOCATION

Essex Copper Processing Plant Beaver County, Utah

Scale Date By 1:100000 9/19/90 JLK

USGS Topo. Base. Wah Wah Mts. South. 30 x 60 minute series, metric.





UTAH DEPARTMENT OF HEALTH

BUREAU OF ENVIRONMENTAL RESPONSE AND REMEDIATION

Figure 2

DETAILED SITE LOCATION

Essex Copper Processing Plant Beaver County, Utah

Scale Date Ву 1:24000 9/19/90 JLK

USGS Topo. Base. Milford Quad. 7.5 minute series

materials. Blue to green colored standing water has been observed in these ponds during wet periods^{18,20,22}.

Typical Basin and Range geology hosts the features present in the area on a regional scale. The Escalante Desert lies to the south and east of the site. To the west are the foothills and draws of the San Francisco Mountains. The Rocky Range and the mines of the Rocky Range Mining District are approximately two miles north¹³.

Quaternary lake sediments underlie the site to depths of about 480 feet where granite bedrock is encountered. Above these sediments are sands and gravels of the gently sloping alluvium of The Big Wash drainage. The first clay layer is encountered at a depth of ll0 feet and is a mixture of clay and gravel⁷.

The ephemeral Big Wash drainage flows east along the northern portion of the site. It flows only during periods of snowmelt or intense rain⁷. A large levee extends north-south across the Big Wash to the east of the site, which impounds all surface water from the drainage and prevents further downstream flow^{13,18}.

Average annual precipitation in Milford is 8.6 inches. Mean annual temperature is 48.3 degrees Farenheit. Average annual pan evaporation for April through October is 87 inches, largely due to wind. Net precipitation, based on monthly gross precipitation minus monthly pan evaporation, is 0.43 inches⁸. Inclusion of transpiration would undoubtedly lower this value further. Average monthly precipitation exceeds evaporation only in January. Two year, 24 hour rainfall data is not currently known, however, the daily maximum rainfall measured at Milford is about 2 inches⁵.

3.2 Operational History and Waste Characteristics

The site first came into private ownership as a patented claim by the Birch Ranch and Oil Company and has since undergone numerous changes in title and in operators. Arrangements were made in 1960 for the renovation of a 350 ton/day floatation mill for the processing of copper ore taken from the Rocky Range Mining District²⁹. It is believed that this is the mill located on the Essex Site. The period of time for which tailings were dumped at the site prior to 1960 is not currently known. At the cease of operations in 1973 or 1974, the mill site was owned by the Shield Development Company of Toronto, Ontario and was operated on lease by Essex International, Inc.²⁹. Sometime after mill operations ceased, a company known as CMI came onto the property and put up a sign showing their company logo. CMI's exact onsite operations are unknown²².

Current ownership of the site is divided: Anyox Metals, Ltd. bears title to 72.7 acres on the south, acquired from Shield Development; Beaver County owns 70 acres on the north, acquired through a tax sale from Essex International. The site is bounded on all sides by public land administered by the Bureau of Land Management^{2,3}. Bene Johnson of Milford, Utah, is the caretaker of the mill site under the employ of the Shield Development Company, Ltd.

Ore and/or mill tailings, ranging in size from silt to small gravel, cover approximately 64 acres of the site^{10,18}. Figure 3 is a site sketch which shows the on-site features. Pond areas have been formed on top of these tailings in several locations. Some of these ponds in the southwest portion of the site are lined with deteriorated plastic. These "evaporation ponds" contain fine-grained sediments, and periodically contain bluish to greenish colored water^{18,22}.

The ore/tailings support little or no vegetation in contrast to off-site heavily vegetated ground²⁰. Some of the coarser ore/tailings have been transported off-site for use as road gravels, and it has been alleged that they kill the surrounding vegetation when they get wet²².

The mill and processing area are located in the central portion of the site. Most of the structures are still standing but in disrepair, and debris is scattered about. Several large storage tanks, either mostly empty or with unknown contents, are located within the processing area. One large tank near the mill building which apparently has leaked, or is leaking, is marked "ACID". An underground storage tank is also suspected to be present on-site, evidenced by what appears to be a stand-pipe located south of the maintenance building in the vicinity of the oil shack 18,20.

Present in outside drum storage and disposal areas, at 2 locations near the south side of the tailings pile, are 125-150 drums. Several drums are full and many of these are corroded and leaking. An estimated 50 drums are also scattered about in different locations throughout the site²². The drums mostly contain process chemicals including acids, dithiophosphate salts, and cresol¹. Some of the drums with identifiable labels read, Van Waters and Rogers - "Silicate of Soda", American Cyanamid Co. - "Aerofloat 25 Promoter," "Aero 412 Promoter," and DOW Chemical Co. - "Dowfroth 250 Floatation Frother¹⁸."

A number of electrical transformers, some of which contain polychlorinated biphenyls (PCBs), are located around the site. Several of these show indications of leakage¹⁸.


Occasional use of the site is apparent in the vandalism of on-site structures and through reports of off-road-vehicles (ORVs) and observed ORV tracks on-site^{6,18,20,22}.

Except for the containers themselves, i.e., tanks, drums and transformer boxes, virtually no containment structures are present for any of the on-site sources. No secondary containment provisions are present for the tanks or containers¹⁸.

Off-site, a large levee extends NE-SW across the Big Wash to the east of the site. This impounds all surface water from the site and from The Big Wash drainage^{13,18}. The only apparent outflow from this pond is through percolation to groundwater or evaporation.

3.3 Previous Investigations

Information from 2 DERR previous investigations has been utilized in the preparation of this report. The first of these is a Site Visit Report²² for a site visit conducted April 27, 1988. The other is a Preliminary Assessment Report²⁰ dated December 5, 1989.





By: JLK, 3/26/93. Scale: approx. 1:10,000

DIVISION OF ENVIRONMENTAL

RESPONSE AND REMEDIATION

ESSEX COPPER PROCESSING PLANT FIGURE 3 SITE SKETCH

3.3.1 Site Visit Report

A site visit was conducted by DERR representatives on April 27, 1988 to inspect the site, in response to a complaint of abandoned drums and turquoise colored water at the site. The Site Visit Report identifies several potential sources of contamination and describes the site in fair detail. The report includes a site sketch and photographs.

3.3.2 Preliminary Assessment

A Preliminary Assessment, completed December 5, 1989, confirmed the findings of the previous site visit and evaluated the potential exposure pathways through hypothesized releases to the air, surface water and ground water pathways, site physical characteristics, and potentially affected targets. The Preliminary Assessment indicated potential ground water contamination to be the main concern at the site. The site sketch prepared during the previous site visit was also revised for the Preliminary Assessment.

4.0 FIELD ACTIVITIES

4.1 Sample Collection and Field Observations

Sampling was conducted in accordance with methods outlined in the DERR CERCLA Quality Assurance Project Plan (QAPP)²¹ of November, 1989. An adequate quantity of disposable or previously decontaminated sampling equipment was supplied in order to avoid the need for field decontamination.

Water, soil and sediment samples, and one barrel sample, were shipped via Airborne Express to Skinner and Sherman Laboratory for analysis of total metals and cyanide under EPA's Contract Laboratory Program (CLP) Routine Analytical Services (RAS). The source characterization samples were hand-delivered to the Utah State Health Laboratory for PCB analyses of the transformer oil samples, and for organics and PCB analyses for the drum sample.

Field notes and photographs were taken throughout the sampling event to document sample locations, sampling methods, and field observations. Several of these photographs are included as Appendix C. The remainder of the photographs, and the field notes, remain in the DERR file for the Essex site, or in the possession of the Project Manager.

All samples were preserved as per the DERR QAPP, and cooled with ice to 4 degrees Celsius. Only certified CLP sample containers were used. The appropriate sample containers for each specific media and respective analyses are listed in Table I. The containers were provided by I-Chem Research and Eagle-Picher.

The weather during the sampling event was clear, hot and dry, with strong gusty winds. At one point during the sampling event, a large "dust devil" occured on-site, kicking up a large amount

Table I Sample Containers

Water Samples

Total Metals -- One - 1 liter plastic bottle per sample, preserved

with nitric acid to a pH < 2.

Cyanide -- One - 1 liter plastic bottle per sample, preserved

with sodium hydroxide to a pH > 12.

Soil and Sediment Samples

Total Metals and

Cyanide

One - 8 ounce wide-mouth glass bottle per

sample.

Source Characterization Samples

All Parameters One - 8 ounce wide-mouth glass bottle per

sample.

of dust, tearing off and carrying with it, siding from the buildings, and other large objects high in the air. The owner of the nearest residence, and the ground water well which was sampled, stated that dust is commonly blowing off the ore/tailings pile towards the north.

Permission for access to evaluate and sample the site was given verbally by the site caretaker prior to going on-site, and the combinations for the 2 locks on the cable gates were given to the site Project Manager to allow for unlimited access. Split samples were offered and refused. A Consent for Access to Property form was signed on June 2, 1992, and is included here as Appendix D.

As with many ore processing facilities in Utah, the Essex site appeared to have been abandoned with the intention of starting back up should economic conditions make this viable. A large amount of equipment and supplies were left on-site, as well as paperwork. Catalogues, assay reports, equipment specifications, process diagrams and flowcharts, and other reports were present in the maintenance building offices.

The Project Manager investigated allegations of off-site utilization of the ore/tailings material. An area was noted on-site with yellow-brown gravel which appeared to have been a location of ore/tailings excavation. These allegations were further confirmed through a discussion with the person responsible for the off-site distribution of this material, who stated that most of the gravel removed from the site goes to roads and driveways in nearby Beaver City. This person was informed by the Project Manager that although the hazardous nature of the Essex gravel was not

fully known, the State was concerned that the material may contain "potentially hazardous" concentrations of heavy metals³⁰.

A representative from Utah Power and Light Company inspected the site for live electrical power sources, and determined that all the power lines on the site were dead, except for one wire along the north part of the site. He also stated that he was vaguely familiar with the past site operations, and he recalled very large quantities of acid being utilized by the facility for their process.

Several dead and partially decomposed predatory birds, about the size of a raven or small hawk, were present in the bottom of a large open tank located at the south side of the processing facility. It is not known whether the cause of death was chemically related, or from human activity. Spent shotgun shells were present at several locations throughout the site. A live raven was also present inside the mill building which may have been nesting nearby. This raven would not move from it's perch on a tank access ladder, even when approached by the sampling team to within a few feet.

The accessible tanks on-site contained only small amounts of solid material in their bottoms. The contents of inaccessible tanks remain undetermined. The contents and quantity of material in a liquid storage tank marked "ACID" also remain undetermined. A sulfur-like precipitate was present beneath this tank which had a pH of less than 2, when wetted.

The apparent underground storage tank filler pipe was determined to be plugged at a depth of about 12 inches. No organic vapors could be detected with a photoionization detector, placed near the top of the pipe. The possible presence of an underground storage tank remains unconfirmed.

4.2 Quality Assurance/Quality Control

Air monitoring instruments were calibrated each day prior to their use. Water monitoring instruments were calibrated according to manufacturers instructions immediately prior to the collection of water samples. Field monitoring equipment consisted of a pH/temperature/conductivity/oxidation-reduction-potential meter, for water sampling, and a photoionization detector and an oxygen/combustible gas/carbon monoxide meter for air monitoring.

Documentation procedures included the completion of all CLP forms and tags for RAS inorganic analyses. Strict Chain of Custody was maintained and Chain of Custody forms were filled out to accompany each shipment. Copies of these forms are included as Appendix E. Samples for RAS metals and cyanide analyses were shipped to Skinner and Sherman Laboratory of Waltham, Massachusetts. Source characterization samples were hand-delivered to the Utah State Health Laboratory in Salt Lake City.

Validation of the analytical results was conducted by Versar Architects and Engineers, Inc. under contract with DERR. Most data were deemed acceptable, however, several problems were discovered resulting in: "J" and "UJ" qualified, or estimated and estimated/undetected, respectively, data for several analytes in water and soil samples; and "R," or rejected data for antimony, arsenic, barium, chromium, lead, selenium and vanadium in water samples. The data tables of Appendix F reflect these qualifications. Appendix G presents the data validation report submitted by Versar, along with the validated CLP Data Sheets.

Due to the limited number of environmental water samples collected, only one field quality assurance sample was collected. This sample, EC-PW-03, consisted of store bought distilled water, added to a sample container, and preserved in the same manner as the environmental samples. The sample was collected to determine whether sample preservation, handling or shipping may have added contamination to the samples. Only aluminum and magnesium were detected in this sample, and these were at concentrations below the CLP Contract Required Detection Limit.

5.0 WASTE/SOURCE CHARACTERISTICS

Five well-defined sources have been recognized at the Essex Copper site, along with several other lesser sources or potential sources. These 5 sources potentially exhibit acute and chronic toxicity, and carcinogenic characteristics, if an individual were exposed, and consist of both liquid and solid media. No significant containment features are known to be present for any of the sources. Source locations are delineated on Figure 4.


5.1 Source Descriptions

5.1.1 Ore/Tailings Pile

Approximately 64 acres of the site are covered with ore/tailings to an undetermined depth, most of which appear to have been deposited directly into the Big Wash drainage^{10,13}.

In the western portion of the site, the ore/tailings consists of orangish-brown to gray-brown coarser grained material. A network of impoundment-forming berms have been constructed atop the pile in the northwest portion of the site, and several pond depressions have been constructed in the southwest portion, also atop the pile. The berms have been severely breached by large gullys flowing northward off the site toward the Big Wash. An alkali surface is present in several locations atop the tailings¹⁸. The physical characteristics of the material to the west of the mill buildings give the impression that this may be the ore utilized in the floatation recovery process.

In the east portion of the site the material in the pile consists of sharply defined areas with; dark-gray, yellowish-brown, and reddish-brown fine grained material. The color appears to be related to the degree of oxidation of the material¹⁸. This material may be the spent tailings from the recovery process.







ESSEX COPPER PROCESSING PLANT FIGURE 4

DIVISION OF ENVIRONMENTAL RESPONSE AND REMEDIATION

SOURCE LOCATIONS

By: JLK, 3/26/93. Scale: approx. 1:10,000

Aeolean erosional and material transport characteristics are prevalent over the entire waste pile. Large dunes and smaller ripple structures are present over the western portion of the pile. The surface of the eastern portion of the pile has several textural characteristics resembling a blowout depression¹⁸. A large aeolean deposited "plume" is apparent to the north of the tailings area on the aerial photographs of the site¹⁰.

5.1.2 Evaporation Ponds

Several pond depressions have been constructed atop approximately 9 acres of the pile in the southwest portion of the site which appear to be evaporation processing ponds. Four of the larger ponds are present along the south site boundary, the 3 westernmost of which contained clear blue to green water during the sampling event. The sediment in these ponds was brownish-gray with a bluish color at the surface in some locations¹⁸. A deteriorated plastic lining was apparent at the edges of some ponds^{18,22}. Several smaller ponds are also present along the north side of the 4 large ponds and along the southern edge of the site adjacent to the larger ponds^{10,18}.

5.1.3 Drums

Contents of the drums were estimated by labels, sampling data, and similarity in appearance, for 58 40-gallon and 55-gallon drums located on-site, in an effort to define this source of contamination. Twenty-six of these are located in the mill building, and 32 are located in the drum storage area. Several other drums and other containers are also located at these areas, and other locations throughout the site, which have not been characterized with regard to their contents^{18,22}. Figure 5 shows the location of these containers, keyed to container descriptions of Table II.


The 26 drums in the mill building are in a semi-confined room on a concrete floor. The drums are extremely corroded and leaking. The partially legible labels indicate that the material ins from the American Cyanide Company. Four 55-gallon drums read "AEROFLOAT 25," and 22 40-gallon drums read "AERO 412." A very strong "inorganic" odor permeated the room¹⁸.

Most of the 32 55-gallon drums present in the drum storage area were bulged, corroded, and/or leaking. Soil contamination was also apparent in this area. Three of these drums had yellow tops and were labeled "DOWFROTH 250." The other 29 drums were very similar in outward appearance, and in appearance and physical character of their "tarry" contents¹⁸.

A drum disposal area in the southeast portion of the site contains several empty, or nearly empty, drums, most of which bear the label, "DOWFROTH 250¹⁸."

5.1.4 Transformers

Electrical transformers and capacitors are present at several locations at the site which potentially contain PCBs, as shown on Figure 5 and summarized on Table III. The total volume of oil on-



NORTH

Location identifiers, 1, 2, 3, ... A, B, C,keyed to Tables 2 & 3



ESSEX COPPER PROCESSING PLANT FIGURE 5

CONTAINER AND TRANSFORMER LOCATIONS

DIVISION OF ENVIRONMENTAL

RESPONSE AND REMEDIATION

By: JLK, 3/26/93. Scale: approx. 1:5000

Table II Container Summary

	Quantity/			
Location Capacity		Description		
1: Maintenand	ce			
Building	1/55 gal.	Oily material		
•	3/5 gal.	Grease		
	5/1 gal.	"Nalco Activator"		
	4/1 gal.	"Toluene Solvent"		
	2/3 gal.	"Nordbak Resin" grout mixture?		
	2/90 lb.	"DOW" powder in bags		
	1/7 gal.	"Amoniated Cleaner"		
	1/5 gal.	"Quick Drying Aluminum Formula"		
	1/55 gal.	Unknown		
	6/5 gal.	Oil or grease		
	2/80 lb.	"Calcium Chloride" in bags		
	7/1 gal.	Unknown		
2: Oil Shack	_	"Chevron Vistac Oil"		
3: Mill	•			
Building	3/55 gal.	"Texaco Transformer Oil"		
	4/55 gal.	"American Cyanamid - Aerofloat 25 Promoter"		
	22/40 gal.	"American Cyanamid - Aero 412 Promoter"		
	5/5 gal.	"Texaco Crater 2" oil or grease?		
	2/55 gal.	Unknown		
	1/120 lb.	"Pinion Grease"		
4: Drum Stor	age			
Area	1/55 gal.	Brown oil		
	1/55 gal.	"Sinclair Oil"		
	7/55 gal.	Unknown		
	29/55 gal.	Brown to black oil and sludge with tarry material on lids		
	3/55 gal.	"Dowfroth 250"		
	1/55 gal.	"Silicate of Soda"		
	1/40 gal.	white powder with pH > 12		
5: Drum Disp	oosal			
Area	Several empt	y or mostly empty "Dowfroth 250," and other, 55 gallon		
	drums. A sn	nall pit is also present in this area in which several		
	buried drums	were observed partially protruding from the soil.		
6: Assay				
Office	Several small containers of various chemicals.			

Table III Transformer Summary

Location	Quantity/ Capacity	Description
A: Maintena	nce	
Building	3/200 gal.	"Gregory Electric" transformer
		- pad mounted
	1/30 gal.	"General Electric Spirakore
	Ŭ	Transformer" - loose
	30/1.3 gal.	"General Electric Pyranol
	C	Capacitors" - loose
B: Mill		-
Building	3/150 gal.	transformer - pole mounted
_	3/200 gal.	transformer - pole mounted
C: Control	_	_
Building	3/200 gal.	unlabled transformer - pad mounted
	1/20 gal.	"Zinsco" transformer - loose

site in this abandoned electrical equipment is estimated at approximately 2340 gallons. Two 55-gallon drums labeled "transformer oil" are also located in the mill building¹⁸.

5.1.5 Contaminated Soil


A large area of apparent wind deposited soil extends north of the east side of the site, as shown on the aerial photograph of Figure 6. The total extent of this off-site soil contamination is not well known, and several other areas of soil contamination are likely to be present.

5.2 Sample Locations

Table IV summarizes the sample locations and briefly describes the sampled material. Figure 7 shows the sample locations.

5.2.1 Ore/Tailings Pile

Seven soil samples were collected from the waste pile at locations shown on Figure 7. The samples were collected with a stainless steel spoon from the soil surface, and these were all collected as "grab samples," except sample EC-SO-03. Sample EC-SO-03 was composited from



NORTH




Source: USDA-ASCS, 1978. enlarged 200%

DEPARTMENT OF ENVIRONMENTAL QUALITY
DIVISION OF ENVIRONMENTAL
RESPONSE AND REMEDIATION

ESSEX COPPER PROCESSING PLANT FIGURE 6 AERIAL PHOTOGRAPH

Table IV Sample Summary

Sample Number	Sample	Sample
Number	<u>Location</u>	Description
EC-SO-01	Background	Medium-brown poorly-sorted sand
EC-SO-02	West pile	Dark-gray-brown silt with alkali surface
EC-SO-03	South base of west	Composite medium-brown fine to medium-
	pile	grained silt, dark-gray-brown silt, and
EC-SO-04	Excavation area	medium-brown poorly-sorted sand Yellow-brown gravel
EC-SO-05	North-central pile	Red-brown silt with alkali surface
EC-SO-06	East of mill area	Dark-gray to black fine-grained sand
EC-SO-07	Northeast pile	Yellow-brown, gray and brown fine-grained sand and silt
EC-SO-08	Southeast pile	Red-brown and yellow-brown fine grained sand and silt
EC-SO-09	North of site	Medium-gray-brown silty-sand
EC-SE-01	Upstream Big Wash	Tan to brown sandy-silt
EC-SE-02	Drainage ditch from mill area	Red-brown very-fine-grained sand and silt
EC-SE-03	Downstream Big	Light-gray-brown silty sand
20 32 03	Wash	Digit gray-blown sitty sailu
EC-SE-04	Probable point of	Yellow-brown fine-grained sand and silt
	Entry	_
EC-PS-01	East pond	Brown to gray silt with blue surface
EC-PS-02	West pond	Dark-brown to gray sandy silt with black specks
EC-PW-01	East pond	Clear blue to turquoise water
EC-PW-02	West pond	Clear green to blue-green water with very-dark
		syrupy appearance
EC-PW-03	Trip blank	Store-bought distilled water
EC-GW-01	Off-site well	Clear colorless water
EC-SC-01	Drum # 13	Thick black oil with strong organic odor
EC-SC-02	Control Building	Light-brown transformer oil; HNu reading of 20
EC-SC-03	Maintenance Building	Light-brown transformer oil; HNu reading of 1



■ = Soil Sample

= Sediment Sample

🕽 = Pond Sediment Sample

▲ = Pond Water Sample

= Source Characterization Sample

NORTH



DEPARTMENT OF ENVIRONMENTAL QUALITY
DIVISION OF ENVIRONMENTAL
RESPONSE AND REMEDIATION

ESSEX COPPER PROCESSING PLANT FIGURE 7 SAMPLE LOCATIONS

By: JLK, 3/26/93. Scale: approx. 1:10,000

3 different soil types exhibited within a very short distance from each other, near the base of a large hill forming the boundary between the apparent ore stockpile and evaporation pond area. Samples EC-SO-01 through EC-SO-05 were collected from the west side and consisted of the coarser grained "ore" material. Samples EC-SO-06 through EC-SO-08 were collected from the east side of the site, from "tailings" of fine-grained, distinctive areas of dark gray, yellow-brown, and red-brown, respectively.

5.2.2 Evaporation Ponds

Two pond water samples, EC-PW-01 and EC-PW-02, and 2 pond sediment samples, EC-PS-01 and EC-PS-02, were collected from near the southern bank of 2 of the larger ponds of the evaporation pond area. The water samples were collected by submersing silicone tubing into the ponds and pumping the water through a peristaltic pump into the containers, with care taken not to disturb the sediments below. Sediment samples were collected with a stainless steel spoon after procurement of respective water samples.

Samples EC-PW-01 and EC-PS-01 were collected from the east-central pond. The sediment was a brown-gray silt with a blue color at the surface, and the water was blue to turquoise and had a pH of 2.3. Samples EC-PW-02 and EC-PS-02 were collected from the westernmost pond of the 4 large ponds. The sediment was a dark gray-brown sandy-silt with black specks, and the water was green to blue-green with a dark "syrup-like" appearance and a pH of 2.7.

All water samples were preserved with nitric acid and sodium hydroxide for respective metals and cyanide portions.

5.2.3 Drums

Only 1 drum source characterization sample, EC-SC-01, was collected from one of the several on-site drums. This sample was collected from an unlabled drum, marked in the field as #13, which was thought to be representative of 28 other unlabled drums in the south drum storage area, based on drum appearance and character of the contents - a black oil, thin near the top and thick and sludgy at the base of the drum, with a strong cresol odor, and with a coating of thick, black, tarry material on top of the drums. HNu photoionization detector measurements elevated above background to about 5 parts per million (ppm) as the probe was placed through the bung opening. The sample was collected with a thin glass tube and placed in an 8-ounce glass jar.

5.2.4 Transformers

Two transformer oil, source characterization samples, EC-SC-02 and EC-SC-03, were collected from the drain valves of 2 transformers located on-site. Sample EC-SO-02 was collected from the northernmost transformer of a group of 3 unlabled transformers near the east side of the control building. An HNu measurement of 20 ppm was obtained when the probe was placed near the mouth of the sample container during sample collection. Sample EC-SC-03 was collected from a group of 3 "Gregory Electric" transformers located near the northwest corner of the

maintenance building. The HNu measured less than 1 ppm when the probe was held above this sample during collection.

5.2.5 Contaminated Soil

Soil sample EC-SO-09 was collected from the soil surface approximately 600 feet north of the eastern portion of the tailings pile. A review of aerial photographs conducted after the sampling event revealed an apparent aeolean surface deposit or "plume" extending from the site through the area from which this sample was collected. The soil surface was very soft and the sample consisted of fine grained sand.

5.3 Analytical Results

Validated analytical results for soil and water samples are tabulated and presented in Appendix F. A sample validation report, prepared by Versar, is included as Appendix G, and includes the raw data tables received from Skinner and Sherman Laboratory, with qualifications noted in the margins. Analytical results for the higher concentration, drum and transformer samples, submitted to the Utah State Health Laboratory, are presented as Appendix H.

5.3.1 Ore/Tailings Pile

Arsenic, chromium, copper, silver and zinc were elevated in the ore/tailings pile at concentrations exceeding 3 times that of respective background soil concentrations of sample EC-SO-01 (Appendix F). Copper and silver are the most consistently present hazardous substances in the waste pile, being elevated in all ore/tailings samples. Arsenic was elevated in all samples except EC-SO-04, collected from the apparent excavation area for off-site use of the material. Cadmium, lead and mercury were also present at elevated concentrations in the ore/tailings, compared to background, but their concentrations were well within normal soil levels.

Several other metals; calcium, iron, magnesium and sodium; were also elevated with respect to background. The most significant of these is iron, elevated in all samples except sample EC-SO-03, composited from near the base of the ore pile in the western portion of the site.

5.3.2 Evaporation Ponds

Analytical results of the pond water samples (Appendix F), EC-PW-01 and EC-PW-02, show aluminum, cadmium, cobalt, copper, manganese, nickel, thallium and zinc to be of concern for this source. Beryllium and mercury were also detected and may be of concern. A large portion of the data - 7 analytes, including arsenic - for the water samples was rejected, however, due to quality control considerations. Calcium and magnesium were also present at high concentrations. Sediment samples, EC-PS-01 and EC-PS-02, show elevated concentrations of copper, and slightly elevated arsenic and silver, to be of concern.

Field measurements for pH, temperature and oxidation/reduction potential were collected for the pond water samples. Results of these are presented in Table V.

Table V Pond Water Field Measurements

Sample #	Temperature	рН	Oxidation/ Reduction Potential
EC-PW-01	19.7° C.	2.3	317 mV
EC-PW-02	19.5° C.	2.7	325 mV

5.3.3 Drums

Several toxic and/or incompatible/reactive constituents are present in high concentrations in the on-site drums. Table VI lists the constituents present, based on analytical results for sample EC-SC-01, and Material Safety Data Sheets (MSDSs), and summarizes the concerns over the drum contents. Table II also lists and describes several other drums and containers which are present on-site, and for which detailed information is not available. MSDSs from Dow Chemical and American Cyanamid, for the products mentioned earlier, are presented as Appendices I and J, respectively.

5.3.4 Transformers

Analytical results for the transformer samples indicate that PCBs are present on-site in transformer oil at potentially hazardous concentrations. PCBs were undetected in sample EC-SC-02, but were present at 1900 ppm, as aroclor 1260, in EC-SC-03, as shown on the laboratory forms of Appendix H.

5.3.5 Contaminated Soil

Arsenic, copper, lead, silver and zinc were elevated greater than respective background levels in off-site soil of sample EC-SO-09 (Appendix F), indicating a windborne migration of contaminants to the north. The lead value, however, was well within normal levels for soil, and the degree of contamination by silver is questionable due to qualification of the background data for quality control problems.

Table VI Drum Contents

<u>Description</u>	Hazardous Compound	Concentration
29 - 55 gallon unmarked drums (See sample EC-SC-01)	Benzoic acid 4-Chloro-3-methyl phenol 2,4-Dinitrophenol 2-Methyl naphthalene 2-Methyl phenol (o-cresol) 3-Methyl phenol (m-cresol) 4-Methyl phenol (p-cresol) Phenol	912,000 ppb 26,300,000 ppb 23,500,000 ppb 160,000 ppb 1,150,000 ppb 284,000 ppb 366,000 ppb 226,000 ppb
22 - 40 gallon drums marked "AERO 412 Promoter." Generically, Alkyl dithiophosphate. pH = 13 (See MSDS).	Decomposition Products: Hydrogen sulfide Carbon monoxide	N/A N/A
4 - 55 gallon drums marked "AEROFLOAT 25 Promoter." Generically, Aryl dithiophosphoric acid. Reacts with water to form hydrogen sulfide (See MSDS).	Cresylic acid (cresol) Decomposition Products: Hydrogen sulfide Carbon monoxide	15 % N/A N/A
3 - 55 gallon drums marked "DOWFROTH 250 Floatation Frother," (See MSDS).	Polypropylene glycol methyl ether Decomposition Products: Carbon monoxide	98 % N/A

5.4 Conclusions

Hazardous constituents are present in each of the sources described above. Since each of these sources are essentially uncontained, these constituents appear to be available for potential release to surface water, ground water, and air, and subsequent off-site migration. Potential direct exposure to toxic and/or carcinogenic materials, by persons visiting the site, is also possible due to the open access of the site.

Several other potential sources of contamination may also be present, including: other uncharacterized tanks, containers, and impoundments, both partially full and full; soil near drums, tanks, and transformers; an on-site slag disposal and scrap iron pile; soil and partially full drums in a drum disposal area and disposal pit located in the southeast portion of the site; sediments

deposited behind the levee crossing the Big Wash, downstream of the site; and a potential underground storage tank¹⁸.

6.0 GROUND WATER PATHWAY

6.1 Hydrogeology

Unconsolidated alluvium and Quaternary lake sediments underlie the site to depths of approximately 480 feet, with the upper 110 feet being comprised of mostly sand and gravel, below which clay and gravel is encountered⁷.


The site is located in an area of ground water recharge for the Milford area aquifer⁷. In the valley to the east the aquifer can be divided into 3 interconnected high permeability layers separated by 3 low permeability layers. The March, 1972 depth to the water table at the site was 240 feet with an aquifer thickness of about 100 feet. Flow direction is east of southeast towards the town of Milford. Near the Beaver River, approximately 3 1/2 miles to the east, the flow changes towards a northeast direction⁷.


Subsurface inflow from The Big Wash drainage accounts for nearly 4% of the total inflow to the Milford area aquifer⁷. At the Essex Copper Site, The Big Wash flows through the tailings on the north side and has its overland flow terminated at a levee near the east edge of the site^{13,18}. Here the water is ponded and allowed to percolate through sediments derived from the tailings area.

6.2 Targets

The town of Milford, with a 1990 population of 1107^{26} , lies almost wholly between the 3 and 4 mile target distance limits from the site and is almost directly downgradient to the ground water flow. The town relies exclusively on ground water from the principal aquifer for their municipal supplies⁷. The nearest residences to the site include 3 homes which draw water from the aquifer for domestic purposes, and are located approximately one mile downgradient from the site¹⁸. A few rural residences are located in the area to the south and east of the site. Water from the aquifer also contributes heavily to irrigation and stockwater supplies^{7,24}.

Within a 4 mile radius from the site, there are 42 wells, most of which are downgradient from the site; 7 of these are for municipal supply; 12 are used for domestic purposes; 24 are for irrigation, and 17 are for stock water²⁴. Appendix K contains a map showing well locations and utilization, and printouts from the Utah Division of Water Rights and the Utah Division of Drinking Water. Note that some of these wells have multiple uses. Figure 8 shows a 4 mile radius from the site.





UTAH DEPT. OF HEALTH Bureau of Solid and Hazardous Waste

Four Mile Radius of Influence

ESSEX COPPER PROCESSING PLANT
BEAVER COUNTY, UTAH

by	date	SCALE
JLK	11/29/89	1:62500

USGS topo. base, Milford, 15' series

6.3 Sample Locations


One of 3 domestic wells located near a cluster of residences 1 mile east of the site was sampled. Figure 9 shows the location of this well. Attachment L contains specific information regarding the well. Ground water sample EC-GW-01 was collected after purging approximately 286 gallons from the well. The well is screened from 224 to 304 feet below the ground surface²³. The field parameters, pH, temperature, and specific conductivity, were tested during purging and immediately prior to sampling. The results of these are given on Table VII. The ground water sample was preserved with nitric acid, for the metals portion, and sodium hydroxide, for the cyanide portion.

Table VII Ground Water Field Measurements

<u>Time</u>	Quantity <u>Purged</u>	Temperature	<u>pH</u>	Oxidation/ Reduction Potential	Specific Conductivity
10:42	start pump				
10:47	18.7 gallons	23.3° C.	6.5	181 mV	1152 uS
10:54	66.3 gallons	22.4° C.	7.1	120 mV	1114 uS
11:02	116 gallons	23.0° C.	7.3	86 mV	1033 uS
	202 gallons		7.4	86 mV	1012 uS

6.4 Analytical Results

Validated analytical results are included in Appendix D. No background sample was collected of ground water and therefore, the results must be evaluated on their own merit. No major contamination was detected based on the data received, however, results for antimony, arsenic, barium, chromium, lead, selenium and vanadium were rejected due to quality control considerations. Zinc concentrations in the sample, although not hazardous and probably not of concern, were greater than the geometric mean for surface water and ground water published by the Agency for Toxic Substances and Disease Registry¹¹ (ATSDR). No indication could be found in the ATSDR document as to what the geometric mean specifically accounts for.



NORTE

RESPONSE AND REMEDIATION

ESSEX COPPER PROCESSING PLANT FIGURE 9
GROUND WATER SAMPLE LOCATION

Source: USGS 7.5 min. topo. base

6.5 Conclusions

Resampling of the ground water downgradient of the Essex Copper site, especially for arsenic, chromium and lead, which are present at elevated concentrations on-site, is strongly warranted. The significance of the zinc in the ground water, mentioned above, is that zinc is also elevated in the source and may be an indicator for a potential ground water release.

Other constituents present in the on-site sources which may also be indicators of a release, in addition to zinc, and which were also not rejected, were not at significant concentrations in ground water. These constituents include calcium, iron, magnesium and sodium. Copper and silver, consistently present on-site, were not detectable in ground water.

A potential exists that hazardous materials originating at the Essex Copper Processing Facility have leached or are leaching into the principal aquifer of the Milford area. The Utah Bureau of Drinking Water and Sanitation is currently developing policy for the delineation of Wellhead Protection Areas (WHPA) and has indicated that the Essex site will likely be within the WHPA for the Milford aquifer¹⁶.

7.0 SURFACE WATER PATHWAY

7.1 Hydrology


The Big Wash, which flows east through the northern portion of the site, drains an area to the west of the site, shown on Figure 10, in excess of 55 square miles¹⁵. It is ephemeral and flows only during periods of snowmelt or intense rain. A large levee extends north-south across the Big Wash, east of the site, which impounds all surface water from the drainage. The pond formed by this levee dries relatively quickly, indicating substantial percolation, and/or evaporation. Only during the most torrential precipitation events would potentially contaminated surface waters have even a remote possibility of migrating past the levee¹⁸.

Visual evidence is present to support an observation of contaminant migration to the Big Wash. Large gullies cut into the waste pile along the northeast portion of the site, and anomolous yellow-brown patches of sediment are present immediately downstream of the site in the Big Wash¹⁸.

Several evaporation ponds are present on-site. Blue colored standing water was observed in one of these ponds during an April, 1988 site visit. It appeared that the ponds had been lined in the past with a black plastic material. At the time of the DERR site visits, this lining was almost completely deteriorated. These ponds are discussed above as a source of hazardous materials.

7.2 Targets

Since surface water does not flow far from the site, no targets have been formally evaluated for this Site Inspection.



7.3 Sample Locations

Four sediment samples were collected to evaluate whether contaminants have migrated off-site via surface water overland flow. Three of these were collected from the center of the Big Wash. The fourth was collected from the bank of a ditch leading from the mill to the Big Wash. Sample locations are shown on Figure 7. All sediment samples were collected from the surface with a stainless steel spoon. No water was present in the Big Wash at the time of sampling.

Sample EC-SE-01 was collected in the Big Wash approximately 300 feet west of the road forming the western site boundary, upstream of any potential surface water flow from the site, to determine background concentrations in sediment. The sample consisted of tan to brown sandy-silt.

Sample EC-SE-02 was collected from the east bank of a ditch leading northward from the mill area to the Big Wash, approximately 500 feet north of the mill. The sample consisted of reddish-brown very-fine-grained sand and silt. The bank material sampled appears to have been dredged from the ditch.

Sample EC-SE-03 was collected downstream of the site west of the levee. The sample consisted of light gray-brown sandy-silt, and was collected from a location which appeared to be representative of sediment "settled out" in the pond environment formed behind the levee.

Sample EC-SE-04 was collected at the most downstream probable point of contaminant entry from the tailings pile to the Big Wash, approximately 500 feet downstream from the northeast corner of the pile in the center of the channel. The sample consisted of yellow-brown fine sand and silt, and was collected from an area of anomolous yellow-brown sediments amidst naturally appearing light gray silt.

7.4 Analytical Results

Validated analytical results for the surface water pathway are summarized in Attachment F. The downstream sample, EC-SE-03, collected behind the Big Wash levee, exhibited the highest degree of contamination, with elevated arsenic, cadmium, copper, iron, silver and zinc, greater than 3 times that of respective background concentrations in sample EC-SE-01. Manganese was slightly elevated in this sample also.

Arsenic, copper and silver were elevated greater than 3 times that of respective background concentrations, in the yellow-brown soil collected for sample EC-SE-04, at the probable point of entry. However, the arsenic value, and the silver in the background sample, were qualified as "estimated" due to quality control considerations.

The sample collected from the mill ditch, EC-SE-02, exhibited arsenic and iron concentrations greater than 3 times background. The arsenic value was qualified as an estimate.

7.5 Conclusions

Analytical results for the sediment samples indicate that contamination is migrating by surface water from the site to the impoundment behind the Big Wash levee. However, the potential surface water exposure presents a low direct threat to human health or the environment due to the short distance of off-site contaminant migration, and the lack of targets within this distance. Potential spread of contamination from surface water to ground water resulting from percolation of the ponded water behind the levee appears to be a greater concern.

8.0 SOIL EXPOSURE AND AIR PATHWAYS

No direct sampling was conducted for the air and soil exposure pathways due to a relatively low significance of these pathways with regard to the Hazard Ranking System of the NCP, resulting from low human and environmental targets in close proximity to the site. The site is somewhat isolated, with the nearest residence being about one mile east^{13,18}. Although of low significance for potential scoring purposes, these pathways are still of major concern due to: 1) a very high likelihood of contaminant release to the air pathway and the resultant spread of contaminated soil, coupled with the potential for the contamination in soil to migrate to other pathways; and 2) high toxicity of on-site contaminants and the potential for direct exposure associated with occasional recreation use of the site.

Release of contaminants to the air is also a concern at the Essex site. Dust and other materials from the site have been observed blowing off the site on several occasions¹⁸. Various aeolean erosion, transport and deposition structures are apparent on and off-site, including: blowout depressions, wind ripples, and dune structures evident on-site; and a very large aeolean "plume" extending north of the site evident on aerial photography of the site¹⁰, and confirmed by the collection of soil sample EC-SO-09 (Appendix F).

Direct exposure to on-site contaminants may also present a significant threat. Materials in drums, tanks and other containers, including transformers, are toxic, reactive, and/or carcinogenic^{1,4,27}. In addition, several potential sources have not been adequately evaluated, and several physical hazards are also present. Access to the site is unrestricted except for a cable which crosses the main entrance. Vandalism of the structures and evidence of off-road-vehicle use were apparent during DERR site visits.

9.0 SUMMARY AND CONCLUSIONS

The Essex Copper site, located approximately 3 miles northwest of Milford, Utah along the north side of State Highway 21, is an abandoned ore processing facility with several acres of ore/tailings material, pond impoundments, drums, tanks and other containers, and contaminated soil. A large portion of the process supplies and machinery appear to have been left in place at the cease of operations. The site is in the northern portion of the Escalante Desert in a fairly remote semi-arid area in the western portion of south-central Utah.

Hazardous constituents are present in several on-site sources, all of which are essentially uncontained. Constituents from these sources appear to be available for potential release to surface water, ground water, and air. Potential direct exposure to toxic and/or carcinogenic materials, by persons visiting the site, is also possible due to the open access of the site.

Analytical results from sampling conducted in June, 1992, reveals elevated concentrations of several heavy metals in the ore/tailings material, as compared to background soil concentrations. The most notable, and consistently elevated constituents were copper, up to 16,500 ppm, silver, 32.9 ppm, and arsenic, 363 ppm. Corrosive and/or toxic materials are also present in on-site drums and tanks.

A potential exists that hazardous materials originating at the Essex Copper Processing Facility have leached or are leaching into the principal aquifer of the Milford area. One ground water sample was collected from a domestic well located approximately 1 mile downgradient of the site. Analytical results from this sample did not indicate contamination, but values for several analytes were rejected due to quality control considerations. Re-sampling of ground water may be warranted. The Milford Area Aquifer, underlying the site, is the sole source of potable water for the town of Milford, and vicinity.

The Big Wash drainage is located adjacent to the north edge of the ore/tailings piles. Analytical results for the sediment samples indicate that contamination is migrating by surface water from the site to an impoundment formed behind a levee in the Big Wash less than 1000 feet downstream of the site. However, the potential surface water exposure presents a low direct threat to human health or the environment due to the short distance of off-site contaminant migration, and the lack of targets within this distance. Potential spread of contamination from surface water to ground water resulting from percolation of the ponded water behind the levee appears to be a greater concern.

Release of contaminants to the air is also a concern at the Essex site. Dust and other materials from the site have been observed blowing off the site on several occasions. Various aeolean erosion, transport and deposition structures are apparent on and off-site, including: blowout depressions, wind ripples, and dune structures, evident on-site; and a very large aeolean "plume" extending north of the site, evident on aerial photography of the site.

Direct exposure to on-site contaminants may also present a significant threat. Materials in drums, tanks and other containers, including transformers, are toxic, reactive, and/or carcinogenic. In addition, several potential sources have not been adequately evaluated, and several physical hazards are also present. Access to the site is unrestricted except for a cable which crosses the main entrance. Vandalism of the structures and evidence of off-road-vehicle use were apparent during DERR site visits.

10.0 REFERENCES

- 1. American Cyanamid Company. Material Safety Data Sheets for products AERO® 412 Promoter, Aqueous, and AEROFLOAT® 25 Promoter.
- 2. Beaver County Recorder's Office. August, 1992. Beaver County Index, No. 2645, property boundary description.
- 3. Beaver County Recorder's Office. May, 1989. Telephone communication with Bruce Brown, County Recorder.
- 4. Dow Chemical Company. December, 1992. Material Safety Data Sheet for product DOWFROTH® 250 Floatation Frother.
- 5. Eubank, Mark. 1979. Utah Weather.
- 6. Johnson, Bene, caretaker. May, 1989. Personal communication.
- 7. Mower, R. W. and R. M. Cordova. 1974. <u>Water Resources of the Milford Area with Emphasis on Ground Water</u>. Utah Department of Natural Resources, Division of Water Resources. Technical Publication #43,
- 8. Stevens, Dale J., R. Clayton Brough, Rodney D. Griffin, E. Arlo Richardson. 1983. <u>Utah</u> Weather Guide.
- 9. The Shield Development Company, Ltd. 1992. Telephone communications with Pat Sheridan, owner, and representative for Anyox Metals, Ltd. (416) 363-4477. 150 York Street, Suite 1614, Toronto, Ontario, M5H3S5.
- 10. United States Department of Agriculture, Agricultural Stabilization and Conservation Service. September, 1967 and October, 1978. Aerial Photographs, Roll #'s DRZ-1HH and 40 49001 178, respectively.
- 11. United States Department of Health and Human Services, Agency for Toxic Substances and Disease Registry. February, 1993. Draft <u>Toxicological Profile for Zinc</u>. page 81.
- 12. United States Environmental Protection Agency. September, 1992. Interim Final Guidance for Performing Site Inspections Under CERCLA.
- 13. United States Geological Survey. 1978. Milford, Utah, 7.5 Minute Topographic Quadrangle.

- 14. United States Geological Survey. 1958. Milford, Utah, 15 Minute Topographic Quadrangle.
- 15. United States Geological Survey. 1980. Wah Wah Mountains, South, Utah, 30 by 60 Minute Topographic Quadrangle, Metric.
- 16. Utah Department of Environmental Quality, Division of Drinking Water. June, 1989. Personal Communication with Gayle Smith, Director.
- 17. Utah Department of Environmental Quality, Division of Drinking Water. May, 1989. Municipal Well Printout.
- 18. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. June, 1992. Focused Site Inspection field observations.
- 19. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. March, 1991. <u>Sampling Plan, Essex Copper Processing Plant, Beaver County, Utah.</u>
- 20. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. December, 1989. <u>Preliminary Assessment of a Potential Hazardous Waste Site, Essex Copper Processing Plant, Beaver County, Utah.</u>
- 21. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. November, 1989. Quality Assurance Project Plan.
- 22. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. April, 1988. <u>Site Visit Report.</u>
- 23. Utah Department of Natural Resources, Division of Water Rights. File review File # 71 3785.
- 24. Utah Department of Natural Resources, Division of Water Rights. May, 1989. Water Rights Point of Diversion Printout.
- 25. Utah Office of Planning and Budget, State Data Center. July, 1991. Utah Data Guide. Volume 10, Number 3. Table 2, 1980 and 1990 Population, Households and Housing Units by County.

- 26. Utah Office of Planning and Budget, State Data Center. January, 1991. Utah Data Guide. Volume 10, Number 1. Table 2, <u>Utah Population by County and City, 1990 Final</u> Census Counts.
- 27. Utah State Health Laboratory. July, 1992. Analytical results for oil samples collected from the Essex Copper Processing Plant, June 3, 1992.
- 28. Versar Architects and Engineers, Inc. October, 1992. <u>Draft Letter Report, Essex Copper Data Validation, Inorganic Analysis, EPA Case #18254.</u>
- 29. Whelan, J. A.. November, 1982. Utah Geological and Mineral Survey. Special Studies #57, Geology, Ore Deposits and Mineralogy of the Rocky Range, Near Milford, Beaver County, Utah.
- 30. Whitman, Wayne. June, 1992. Personal communication regarding the off-site utilization of gravel from the Essex Copper Processing Plant.

Appendix A.
Site Inspection Data Summary

SITE INSPECTION DATA SUMMARY

Site	Name:	ESSI	EX CO	PPER	PRO	CESS	ING	PLANT	•		EP.	A l	Region:	8	Da	te:	3/	12/93
Stat	e Offic	e or	Cont	racto	or N	ame	and	Addre	ess:	UTAH	DEQ		DERR,	150	NORT	н 19	50 ·	WEST,
SALT	LAKE C	ITY,	UTA	H 8411	16													
				GE	ENE	ERA	L	SIT	E	INFO	ORM	'A	TION					
1.	CERCLIS	ID	Numb	er:	UTDS	880	6606	54_										
	Address	: _3	MIL	ES WES	ST C	F M	ILFO	ORD					City	<u>M</u> :	ILFOR	D		
	County:	BE	EAVER				St	ate: <u></u>	<u>UT</u>	Zip Co	ode:	_8	4751	(Cong.	Dis	t.:	01
2.	Owner N	ame :	: AN	YOX MI	ETAI	s, آ	LTD.	•										
	Owner A	ddre	ess:	150	YORI	K ST	REE'	T, SUI	TE :	1614	Ci	ty	: TORC	NTO,	ONT	ARIO	S	tate:
	Operato	r Na	me:	ESSE	II X	<u>ITERI</u>	TAV	IONAL,	INC	·								
	Operato	r Ad	dres	s: <u>U</u>	NKNC	NWC		<u>, </u>			_ Ci	ity	':				Sta	te:
3.	Type of	Own	nersh	ip (cl	heck	c al	l th	nat app	ply)	:								
	X Pri	vate	€	1	Muni	cipa	al	X	_ Cc	ounty	_		State					
	Fed	eral	L/Age	ncy Na	ame:	:							Other	:				
													Ref	erer	ces:	2,	3,	9, 20
4.	Approxi	mate	siz	e of 1	Prop	ert	Y: _	147	a	cres.			Ref	erer	ces:	_3		
5.	Latitud	le: _	<u>38</u> •	<u>25</u> ′.	03.	<u>. 0</u> "												
	Longitu	de:	<u>113</u> •	04′	0.8	3.0	11						Ref	erer	ces:	20		
6.	Status:		Ac	tive		<u>C</u> I1	nact	cive		_ Unkno	own		Ref	erer	ces:	18,	20	, 22
7.	Years o	f Op	perat	ion:	Fro	: mc	1960	<u> </u>	o: _	1974	_		Ref	erer	ces:	29		
8.	Previou	s In	vest	igati	ons	:												
	TYPE	1		AG	ENC	Y/ST	ATE	/CONTR	RACTO	<u>OR</u>			DATE					
	SITE V	ISIT	<u>r </u>	TAH D	ERR							4	/27/88	. Re	efere	nces	: _2	22
	PA			TAH D	ERR							1	2/5/89	. Re	efere	nces	: <u> </u>	20
		_	_		_					·		_		. Re	efere	nces	: _	
									_			_		. Re	efere	nces	: _	
												_		Re	efere	nces	: _	
														R	efere	nces	: _	
								<u> </u>				_		Re	efere	nces	: _	

WASTE SOURCE INFORMATION

1.	Waste source types (check all that apply):
	Constituent Wastestream (type):
	Landfill X Tanks or non-drum containers (type): TANKS
	X Drums X Pile (type): MINING WASTE
	X Contaminated Soil X Surface Impoundment
	Land Treatment Surface Impoundment (backfilled)
	X Other: ELECTRICAL TRANSFORMERS
	References: 18, 20, 22
2.	Types of wastes (check all that apply):
	X Organic Chemicals X Inorganic Chemicals Municipal Wastes
	Pesticides/Herbicides X Metals Solvents
	RadionuclidesOther:
	References: <u>1, 4, 27, 28</u>
3.	Summarize history of waste disposal operations:
	THE SITE FIRST CAME INTO PRIVATE OWNERSHIP AS A PATENT BY THE BIRCH RANCH AND OIL
	COMPANY AND HAS UNDERGONE SEVERAL CHANGES IN TITLE. A 350 TON/DAY FLOATATION MILL,
	APPARENTLY THE ON-SITE FACILITY, WAS RENOVATED IN 1960 FOR THE PROCESSING OF COPPER
	ORE FORM THE ROCKY RANGE. MINING OPERATIONS CEASED AT THE SITE IN 1974 AND THE
	SITE WAS ABANDONED. AERIAL PHOTOGRAPHS OF THE SITE FROM 1967 AND 1978 SHOW A
	SUBSTANTIAL INCREASE, ALMOST 2-FOLD, IN THE AREA OF THE WASTE PILE. THE WASTE PILE
	COVERS APPROXIMATELY 64 ACRES. SURFACE IMPOUNDMENTS HAVE BEEN CONSTRUCTED OVER
	9 OF THE 64 ACRES OF THE WASTE PILE. SEVERAL DRUMS, TANKS, AND OTHER CONTAINERS
	WERE LEFT ON-SITE WHEN THE SITE WAS ABANDONED, MANY OF WHICH ARE FULL, PARTIALLY
	FULL, BULGED, CORRODED, AND/OR LEAKING. SEVERAL ELECTRICAL TRANSFORMERS AND
	CAPACITORS WERE LEFT ON-SITE, MANY SHOWING SIGNS OF LEAKAGE.
	·

SI FORM - PAGE 2

References: 10, 18, 29

•	Source characterization (At	tach pages to show quantity	and calcu	ulation	ns):
	Source 1 name: ORE/TAILING	S PILE	_ Source	Type:	PILE
	Describe Source: ORE AND/O	R TAILINGS PILE OF UNDETERMI	NED DEPT	H	
	Ground water migration cont	ainment: NO CONTAINMENT			
	Surface water migration con	tainment: NO CONTAINMENT			
	Air migration (gas and migra	ation) containment: NO CONT	AINMENT -	OBSERV	ED RELEASE
	Physical State of Wastes:				
	X Solid Liquid	Sludge/Slurry Gas	Unkne	own	
	Constituent Quantity of Haz	ardous Substances:	<u></u>	(speci	fy units).
	Wastestream Quantity Contai	ning Hazardous Substances:		(speci	fy units).
		Area of Sour			
	Hazardous substances associ				
	ARSENIC 363 PPM	MAGNESIUM 25,900 PPM			·
	CHROMIUM 111 PPM				
	COPPER 16,500 PPM				
			Referenc	ces: <u>1</u>	8, 28
	Source 2 name: <u>LEACHATE PO</u>	NDS	Source	Type:	IMPDMT
	Describe Source: SEVERAL P	ONDS COVER 9 ACRES OF THE P.	ILE		
	Ground water migration cont	ainment: <u>NO CONTAINMENT - I</u>	DETERIORA	TED LI	NING
	Surface water migration con	tainment: <u>NO CONTAINMENT</u>			
	Air migration (gas and migr	ation) containment: NO CON	PAINMENT		
	Physical State of Wastes:				
	X Solid X Liquid	Sludge/Slurry Gas	Unkn	own	
	Constituent Quantity of Haz	ardous Substances:		(speci	ify units).
	Wastestream Quantity Contai	ning Hazardous Substances:		(spec	ify units).
		Area of Sour			
	Hazardous substances associ				
	ALUMINUM 1,140,000 ug/L	COPPER 10,100,000 ug/L	TALLIU	M 11.1	ug/L
	CADMIUM 713 ug/L	MANGANESE 430,000 ug/L	ZINC 7	5,600 ı	ıg/L
		NICKEL 5490 ug/L			
			Referenc	ces: <u>1</u>	8, 28

Source 3 name: DRUMS		Source	Type:	DRUMS
Describe Source: SEVERAL S	55 AND 40 GALLON DRUMS			· · · ·
Ground water migration cont	ainment: <u>NO CONTAINMEN</u>	Т		
Surface water migration cor	ntainment: <u>NO CONTAINME</u>	NT		
Air migration (gas and migr	cation) containment: NO	CONTAINMENT		
Physical State of Wastes:				
X Solid X Liquid X	<pre>Sludge/Slurry G</pre>	as Unkn	own	
Constituent Quantity of Haz	zardous Substances: 253	0 GALLONS	(speci	fy units).
Wastestream Quantity Contain	ining Hazardous Substanc	es: <u>2695 GAL</u>	(speci	fy units).
Volume of Source (yd3):	Area of	Source (ft ²):		
Hazardous substances associ	iated with source 3:			
BENZOIC ACID	2-METHYLNAPTHALENE	ALKYL	DITHIOF	HOSPHATE
4-CHLORO-3-METHYL PHENOL	CRESOL	ARYL DITH	IOPHASE	HORIC ACID
2, 4-DINITROPHENOL	PHENOL POL	YPROPYLENE GL	YCOL ME	THYL ETHER
		Referenc	ces: <u>1</u> ,	4, 18, 27
Source 4 name: TRANSFORMER	RS	Source	Type:	TANKS
Describe Source: SEVERAL I	ELECTRICAL TRANSFORMERS			
Ground water migration cont	cainment: <u>NO CONTAINMEN</u>	T		
Surface water migration con	ntainment: <u>NO CONTAINME</u>	NŢ		
Air migration (gas and migration	ration) containment: <u>NO</u>	CONTAINMENT		
Physical State of Wastes:				
Solid <u>X</u> Liquid	Sludge/Slurry G	as Unkn	own	
Constituent Quantity of Ha:	zardous Substances: <u>UNK</u>	NOWN	(speci	fy units).
Wastestream Quantity Conta	ining Hazardous Substanc	es: <u>2340 GAL</u>	(speci	fy units).
Volume of Source (yd³):	Area of	Source (ft ²):		
Hazardous substances assoc	iated with source 4:			
AROCLOR 1260 - 1900 PPM				
		Referenc	res: 1	8. 27

Source 5 name: CONTAMINATED SOIL	Source	Type: _S	OILS
Describe Source: AEOLEAN DEPOSITED SOIL NORTH OF THE E	AST TAILI	NGS PILE	
Ground water migration containment: NO CONTAINMENT			·
Surface water migration containment: NO CONTAINMENT			
Air migration (gas and migration) containment: NO CONT	AINMENT		
Physical State of Wastes:			
X Solid Liquid Sludge/Slurry Gas	Unkno	own	
Constituent Quantity of Hazardous Substances: <u>UNKNOWN</u>		(specify	units).
Wastestream Quantity Containing Hazardous Substances: _		(specify	units).
Volume of Source (yd³): Area of Source	ce (ft ²):		
Hazardous substances associated with source 5:			
ARSENIC 71.8 PPM ZINC 272 PPM			
COPPER 3880 PPM			
LEAD 141 PPM			
	Peferenc	es. 18	28

5.Description of removal or remedial activities: If Removal has occurred, identify the removal authority and describe the activities. Specify the date(s) of the removal. NO REMOVAL OR REMEDIAL ACTIVITIES HAVE OCCURRED TO DATE.

References:

GROUND WATER INFORMATION

1. Ground water drinking water use within 4 miles of site sources:
Municipal Private _X Both No Drinking Water Use
References: 17,24
2.Is ground water contaminated?
YesNo _X Uncertain but likely Uncertain but not likely
X Additional sampling required
Is analytical evidence available? X Yes No References: 18, 28
3. Is ground water contamination attributable to the site?
Yes No X Additional sampling required References: 18, 28
CONTAMINATED SURFACE WATER IS PONDED NEAR THE SITE AND ALLOWED TO PERCOLATE
THROUGH THE GROUND. NO MONITORING WELLS ARE PRESENT. A NEARBY DOMESTIC WELL
WAS SAMPLED AND SHOWS NO SIGN OF CONTAMINATION, HOWEVER, A SIGNIFICANT PORTION
OF THE DATA WAS REJECTED.
4.Are drinking water wells contaminated?
Yes No Uncertain but likely X Uncertain but not likely
X Additional sampling required
Is analytical evidence available? X Yes No References: 18, 28
5.Net precipitation (HRS Section 3.1.2.2): 0.43 inches.
6.County average number of persons per residence:
2.95 people. References: <u>25</u>
7.Discuss general stratigraphy underlying the site. Attach sketch of stratigraphic column.
UNCONSOLIDATED ALLUVIAL AND QUATERNARY LACUSTRAL DEPOSITS UNDERLIE THE SITE TO
DEPTHS OF APPROXIMATELY 480 FEET, WITH THE UPPER 110 FEET BEING COMPRISED MOSTLY
OF SAND AND GRAVEL. SKETCHES OF THE STRATIGRAPHIC COLUMN, BASED ON DATA FROM
WELL LOGS FOR 2 ON-SITE WELLS, ARE ATTACHED. DEPTH TO GROUND WATER IS
APPROXIMATELY 280 FEET.
References: 7

8.Using Table GW-1, summarize geology underlying the site (starting with formation #1 closest to ground surface). Indicate if formation is interconnected with overlying formation.

TABLE GW-1: SITE GEOLOGY

NAME OF FORMATION	INTER- CONNECT? (yes/no)	TYPE OF MATERIAL		HYDRAULIC CONDUCTIVITY (cm/sec)	USED FOR DRINKING WATER?
1. UNCONSOLIDATED		SND, GVL	>100	3.5E-2	YES
2.					
3.					
4.					
5.					

			erences: 7				
9.Does a karst aquifer	underlie any site so	ource?					
Yes <u>X</u> No		Ref	Terences: 7				
10.Depth to top of aqui	ifer: 240 feet						
Elevation: 4960 feet References: 7							
11.In the table below, located within 4 miles sheets. Key aquifer to	of the site. For ea	ach aquifer, attach p	nking water from wells population calculation				
POPULATION SERVED BY W	ELLS WITHIN DISTANCE	CATEGORIES BY AQUIF	ER				
DISTANCE OF WELL(S) FROM SITE SOURCES	AQUIFER A: INCLUDES FORMATIONS 1	AQUIFER B: INCLUDES FORMATIONS	AQUIFER C: INCLUDES FORMATIONS				
% mile or less	0						
>1/4 to 1/2 mile	3						
>½ to 1 mile	9						
>1 to 2 miles	0						
>2 to 3 miles	0						
>3 to 4 miles	1107						
		Refere	ences: 24, 26				
12.Is ground water from	m multiple wells ble	nded prior to distri	bution?				
Yes N/A No References: 24							
13.Is ground water ble	nded with surface wa	ter?					
Yes N/A No References: 24							
Briefly Describe: GROU	ND WATER FROM THE MI	LFORD AREA AQUIFER I	S THE SOLE SOURCE OF				
CULINARY WATER IN THE	AREA.						

14.Distance from any incompletely contained source available to ground water to nearest drinking water well (HRS Section 3.3.1):
<u>4100</u> feet References: <u>24, 13</u>
15.Briefly describe standby drinking water wells within 4 miles of sources at the site:
ALL MUNICIPAL WELLS SERVING THE TOWN OF MILFORD ARE LOCATED BETWEEN 3 AND 4 MILES
FROM THE SITE. INDIVIDUAL DISCUSSION OF STANDBY WELLS IS IRRELEVANT.
References: 24
16.Ground water resources within 4 miles of site sources (HRS Section 3.3.3):
X Irrigation (5-acre minimum) of commercial food or commercial forage crops.
X Commercial livestock watering.
Ingredient in commercial food preparation.
Supply for commercial aquaculture.
Supply for major or designated water recreation area, excluding drinking water use.
Water usable for drinking water but no drinking water wells are within 4 miles.
None of the above.
References: <u>7, 17, 24</u>
18.Wellhead protection area (WHPA) within 4 miles of site sources (HRS Section 3.3.4):
Source with non-zero containment factor value lies within or above the WHPA.
Observed ground water contamination attributable to site source(s) lies within the WHPA.
WHPA lies within 4 miles of site sources.
<u>X</u> None
References: 16
Additional ground water pathway description:
References:

SURFACE WATER INFORMATION

COMPLETE A COPY OF THIS SECTION OF THE DATA SUMMARY FOR EACH WATERSHED

1. Describe the surface water migration path from site sources to at least 15 miles downstream. Attach a sketch of the surface water migration route. SURFACE WATER FLOWS FROM THE SITE TO THE BIG WASH, AN EPHEMERAL STREAM IN WHICH THE NORTH SIDE OF THE SITE IS LOCATED. ALL WATER IN THE BIG WASH IS IMPOUNDED LESS THAN 1,000 FEET DOWNSTREAM. References: 10, 13, 18 2. Is Surface Water Contaminated? X Yes ____ No ___ Uncertain but likely ____ Uncertain but not likely ___ Additional sampling is required Is analytical evidence available? X Yes No References: 28 3.Is surface water contamination attributable to the site? X Yes ___ No ___ Additional sampling required References: 28 4.Floodplain category in which site sources are located (check all that apply): X 1-year X 10-year X 100-year X 500-year None References: 18, BEST PROFESSIONAL JUDGEMENT 5.Describe flood containment for each source (HRS Section 4.1.2.1.2.2): Flood Containment NO CONTAINMENT Source #1 ORE/TAILINGS Flood Containment NO CONTAINMENT Source #2 EVAP. PONDS Source #3 DRUMS Flood Containment NO CONTAINMENT Source #4 TRANSFORMERS Flood Containment NO CONTAINMENT Source #5 SOIL CONTAM. Flood Containment NO CONTAINMENT References: 18 6. Shortest overland distance to surface water from any source (HRS Section 4.1.2.1.2.1.3): References: 10, 13, 18 7.Size of drainage area (HRS Section 4.4.3): References: 15 2.4E6 acres 8.Describe the predominant soil group within the drainage area (HRS Section 4.1.2.1.2.1.2): COARSE TO MEDIUM TEXTURED SOILS; SILT, SAND AND GRAVEL; ARE PRESENT ON-SITE

References: 18

.2-year 24-hour Rain	nfall (HRS Sec	tion 4.1.2.1	.2.1.2):		
92 inches				References: 5	· · · · · ·
0.Elevation of the	oottom of near	est surface	water bod	γ:	
200 feet above sea	a level			References: 7	, 13
1.Elevation of top	of uppermost a	quifer:			
960 feet above sea	a level			References: 7	
2.Predominant type of earest drinking water		etween proba	ble point	of entry to surface	e water a
River Lak	e			References:	
3.Identify all drin 5 miles downstream. TARGET NAME/TYPE	WATER BODY TYPE	DISTANCE	FLOW (CFS)	TARGET CHARACTERISTICS*	TARGET
None	BODI TIPE	FROM PPE	(CFS)	CHARACTERISTICS	SAMPHED
Notice					
arget is a fishery	y, provide sper r year). If	ecies and a target is a	nnual pro	f people served by oduction of human specify wetland fr	food cha contage (
	9J. 9J	111.1	4_ 94.	References:	
4.Is surface water	drinking water	prended br	or to dis		
Yes No		TOUMTETER	HOD MILE	References:	
O SURFACE WATER TAR	GETS HAVE BEEN	IDENTIFIED	FOR THIS	INVESTIGATION.	

15.Describe any standby drinking water intakes within 15 miles downstream:
NO SURFACE WATER TARGETS HAVE BEEN IDENTIFIED.
References:
16.Surface water resources within 15 miles downstream (HRS Section 4.1.2.3.3):
Irrigation (5 acres minimum) of commercial food or commercial forage crops
Commercial livestock watering
Ingredient in commercial food preparation
Major or designated water recreation area, excluding drinking water use
Water designated by the state for drinking water use but is not currently used
Water usable for drinking water but no drinking water intakes within 15 miles downstream
X None of the above
References:

SOIL EVALUATION

1.Is surficial or	soil contamination p	resent at the	site?	
X Yes No	O Uncertain b	ut likely	Uncertain but	not likely
Additional sar	mpling required			
Is analytical evid	dence available? X	Yes No	References	s: <u>AR</u>
2.Is surficial or	soil contamination a	ttributable to	the site?	
X Yes No	Additional	Sampling Requi	ired	
	ontamination on the enter, or workplace?	property and	within 200 feet o	f a residence,
Yes _X No	O Uncertain b	out likely	Uncertain but	not likely
Additional sar	mpling required			
Is analytical evid	dence available?	Yes No	References	3:
4. Total area of s	urficial contaminatio	n (HRS Section	n 5.2.1.2):	
square	feet		References	5:
5.Attractiveness/a 5.2.1.1). Check a	accessibility of the all that apply:	areas of obs	erved contamination	on (HRS Section
Designated rec	reational area			
Used regularly	, or accessible and u	nique recreat	ional area	
X Moderately acco	essible with some use	•		
Slightly access	sible with some use			
Accessible with	h no use			
Inaccessible w	ith some use			
Inaccessible w	ith no use		References	s: <u>18</u>

6.Population within 1-mile travel distance from site.

DISTANCE FROM SITE SOURCES	POPULATION	
1/4 mile or less	0	
>¼ to ½ mile	0	
>½ to 1 mile	12	

References: 13, 25

AIR INFORMATION

1.Is air contamination present at the site?
X Yes No Uncertain but likely Uncertain but not likely
Additional sampling required
Is analytical evidence available? Yes X No References: 18
2.Is air contamination attributable to the site?
X Yes No Additional sampling required
3.Are populations, sensitive environments, or wetlands exposed to airborne hazardous substances released from the site?
Yes No Uncertain but likely X Uncertain but not likely
Additional sampling required
Is analytical evidence available? Yes X No References:
4. Evidence of biogas release from any of the following source types at the site:
Below-ground containers or tanks Landfill
Buried surface impoundment References:
5.Particulate migration potential factor value: 17 (HRS Figure 6-2)
6.Particulate mobility factor value:002 (HRS Figure 6-3)
7.Distance from any incompletely contained source to nearest residence or regularly occupied area:
0.75 miles References: 13

8. Population within 4 miles of site sources.

DISTANCE FROM SITE SOURCES	POPULATION		
0 (within sources)	0		
1/4 mile or less	0		
>1/4 to ½ mile	0		
>½ to 1 mile	12		
>1 to 2 miles	0		
>2 to 3 miles	0		
>3 to 4 miles	1107		

References: 13, 18, 24, 26

9.Resources within 1/2 mile of site sources (HRS Section 6.3.3):				
Commercial agriculture				
Commercial silviculture				
Major or designated recreation	area			
$\overline{\mathrm{X}}$ None of the above				
		Referen	ces:	
0.Sensitive environments and wetl	ands within 4 m	niles of the site:		
NAME/DESCRIPTION/LOCATION OF SENSITIVE ENVIRONMENT OR WETLAND	DISTANCE FROM SITE (MILES)	TYPE OF SENSITIVE ENVIRONMENT	WETLAND SIZE (ACRES)	
		Referen	ces:	

ADDITIONAL INFORMATION/COMMENTS

LIST OF REFERENCES


- 1. American Cyanamid Company. Material Safety Data Sheets for products AERO® 412 Promoter, Aqueous, and AEROFLOAT® 25 Promoter.
- 2. Beaver County Recorder's Office. August, 1992. Beaver County Index, No. 2645, property boundary description.
- 3. Beaver County Recorder's Office. May, 1989. Telephone communication with Bruce Brown, County Recorder.
- 4. Dow Chemical Company. December, 1992. Material Safety Data Sheet for product DOWFROTH® 250 Floatation Frother.
- 5. Eubank, Mark. 1979. <u>Utah Weather</u>.
- 6. Johnson, Bene, caretaker. May, 1989. Personal communication.
- 7. Mower, R. W. and R. M. Cordova. 1974. <u>Water Resources of the Milford Area with Emphasis on Ground Water</u>. Utah Department of Natural Resources, Division of Water Resources. Technical Publication #43,
- 8. Stevens, Dale J., R. Clayton Brough, Rodney D. Griffin, E. Arlo Richardson. 1983. <u>Utah Weather Guide</u>.
- 9. The Shield Development Company, Ltd. 1992. Telephone communications with Pat Sheridan, owner, and representative for Anyox Metals, Ltd. (416) 363-4477. 150 York Street, Suite 1614, Toronto, Ontario, M5H3S5.
- 10. United States Department of Agriculture, Agricultural Stabilization and Conservation Service. September, 1967 and October, 1978. Aerial Photographs, Roll #'s DRZ-1HH and 40 49001 178, respectively.
- 11. United States Department of Health and Human Services, Agency for Toxic Substances and Disease Registry. February, 1993. Draft <u>Toxicological Profile for Zinc</u>. page 81.
- 12. United States Environmental Protection Agency. September, 1992. Interim Final <u>Guidance for Performing Site Inspections Under CERCLA</u>.
- 13. United States Geological Survey. 1978. Milford, Utah, 7.5 Minute Topographic Quadrangle.
- 14. United States Geological Survey. 1958. Milford, Utah, 15 Minute Topographic Quadrangle.

- 15. United States Geological Survey. 1980. Wah Wah Mountains, South, Utah, 30 by 60 Minute Topographic Quadrangle, Metric.
- 16. Utah Department of Environmental Quality, Division of Drinking Water. June, 1989. Personal Communication with Gayle Smith, Director.
- 17. Utah Department of Environmental Quality, Division of Drinking Water. May, 1989. Municipal Well Printout.
- 18. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. June, 1992. Focused Site Inspection field observations.
- 19. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. March, 1991. <u>Sampling Plan, Essex Copper Processing Plant, Beaver County, Utah</u>.
- 20. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. December, 1989.

 Preliminary Assessment of a Potential Hazardous Waste Site, Essex Copper Processing Plant, Beaver County, Utah.
- 21. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. November, 1989. <u>Quality Assurance Project Plan</u>.
- 22. Utah Department of Environmental Quality, Division of Environmental Response and Remediation. April, 1988. <u>Site Visit</u> Report.
- 23. Utah Department of Natural Resources, Division of Water Rights. File review File # 71 3785.
- 24. Utah Department of Natural Resources, Division of Water Rights. May, 1989. Water Rights Point of Diversion Printout.
- 25. Utah Office of Planning and Budget, State Data Center. July, 1991. Utah Data Guide. Volume 10, Number 3. Table 2, 1980 and 1990 Population, Households and Housing Units by County.
- 26. Utah Office of Planning and Budget, State Data Center. January, 1991. Utah Data Guide. Volume 10, Number 1. Table 2, <u>Utah Population by County and City, 1990 Final Census Counts</u>.
- 27. Utah State Health Laboratory. July, 1992. Analytical results for oil samples collected from the Essex Copper Processing Plant, June 3, 1992.

- 28. Versar Architects and Engineers, Inc. October, 1992. <u>Draft Letter Report, Essex Copper Data Validation, Inorganic Analysis, EPA Case #18254</u>.
- 29. Whelan, J. A.. November, 1982. Utah Geological and Mineral Survey. Special Studies #57, Geology, Ore Deposits and Mineralogy of the Rocky Range, Near Milford, Beaver County, Utah.
- 30. Whitman, Wayne. June, 1992. Personal communication regarding the off-site utilization of gravel from the Essex Copper Processing Plant.

Appendix B.
Beaver County Recorder, Anyox Property



Appendix C. Site Photographs

ESSEX COPPER SITE INSPECTION PHOTOGRAPHIC LOG


June 2 & 3, 1992

- 1. View northeast to sample collection for EC-SO-01, background.
- 2. View southwest to sample location EC-SO-02.
- 3. View north to large gully eroding through pile north of sample location EC-SO-02.
- 4. View west from top of pile in west portion of site.
- 5. View east to depression at base of west hill, and sample location for EC-SO-03.
- 6. View east to sample collection for EC-SO-03, composited from 3 locations in photo: light soil at left, alkali at center, and dark soil at right.
- 7. View east of northeast to apparent gravel excavation area and sample location EC-SO-04.
- 8. View northwest to sample collection for EC-SO-04.
- 9. View northwest to sample collection for EC-SO-05.
- 10. View east of southeast to sample collection for EC-SO-06.
- 11. View west of southwest toward mill area. Sample location EC-SO-06 at right center.
- 12. View west of northwest to sample location EC-SO-07.
- 13. View north to sample location EC-SO-07 in upper left. Note "blowout" soil surfce characteristic.
- 14. View southwest to sample location EC-SO-08.
- 15. Label on one of three transformers located on pad at northwest corner of maintenance building, location of sample EC-SC-03, which contains polychlorinated biphenyls at 1900 parts per million.
- 16. View east of northeast at transformers at northwest corner of maintenance building. Sample EC-SC-03 collected from northwest (near left) transformer. Note spillage at base of south (right) transformer.
- 17. View west to oil shack. Note oil stained soil.
- 18. Corroded and leaking drums located inside west portion of mill building.

ESSEX COPPER SITE INSPECTION PHOTOGRAPHIC LOG (Continued)


- 19. View west to transformers, location of sample EC-SC-02, located at east side of control building.
- 20. View northwest of sample collection for EC-PS-01.
- 21. View northeast of pond in which samples EC-PS-01 and EC-PW-01 were collected.
- 22. View northwest of pond in which samples EC-PS-02 and EC-PW-02 were collected.
- 23. View east along south portion of site from near the southwest corner, showing sample location EC-PS-02/EC-PW-02.
- 24. View northeast to shed, with pumphouse attached to south side, at well location for offsite ground water sample EC-GW-01.

1.)















5 1 7 1 6 1





















18










24 1







21 † 23 ↓ 22 †














ESSEX COPPER SITE INSPECTION PHOTOGRAPHIC LOG (Continued) North and west panorama from tank catwalk in south central portion of site











Appendix D.
Signed Consent for
Access to Property Form

M002/002

Utah Division of Environmental Response and Remediation CERCLA Branch

CONSENT FOR ACCESS TO PROPERTY

Name, Title Bene Johnson

Address or Coordinates of Property Essex Copper Processing Plant (Shields Developme ~ 3 miles West of Miltord, UT, on North side of State Road 21

I am the record owner, title holder or authorized agent) for the record owner, of the property described above (Property), and after receiving reasonable advance notice, I hereby give my consent and grant access for ingress and egress to the Property to officers, employees, and authorized representatives of the Utah Division of Environmental Response and Remediation × EICU) 1 the following purposes:

- The contents of environmental and source characterization samples; and
- 2. Other such actions related to the collection of the above samples or to the assessment of this site as may be necessary.

I have been informed and understand that these actions by UDERR are undertaken pursuant to the authorities proin the Comprehensive Environmental Response, Compensation and U.S.C.A. 9601. In consideration for this grant of access, I assume Liability Act (Supt no liability for injure, . damage incurred by UDERR while on the Property.

This consent and grant of access is given voluntarily with knowledge of my right to refuse access. I further acknowledge that no other promises, representations or claims of any kind, either written or oral, have been made by UDERR to induce my consent.

I have been informed of my right to obtain splits of all samples collected on the Property and have waived that right.

(Signature) Bene Johnson (Date) 6-2-92

Appendix E. Sample Collection Documentation

REGION VIII, ONE DENVER PLACE 999 18TH. STREET DENVER, CO. 80202-2413

PROJ. NO. PROJECT NAME	_			/ / / /		
Essex Copp	per Processing Plant	•	///	' / / /		
	<u> </u>	NO.	' / \"/ /		/	
SAMPLERS: (Signature)	.TV	OF	\ x \/ /	/ / / /		
Jason Know/t	on thatter		\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			REMARKS .
	Sterry	CON- TAINERS				
	STATION LOCATION		X ₀ V ₀	/ / /		
STAT. NO. DATE TIME O	STATION LOCATION		/ ^x /	//	1. #	T #
6/2 (1 1 '	le#	<u> </u>
EC-50-016/2/12 1130	Backsround			MHX		8-26225
EC. 50. 02 5/2/92 155 V	W. Pile			////////		26226
EC-50-03 6/2/92 1210 V	Base of Hill		VV	MHX	766	26227
EC.50-04 63/92 125	V Excavation	1	VV	MHX	967	26228
EC-50-05 42/92 1225	V N. Central Pile	1	VV	MHX	768	26229
EC-50-06 42/92/320	/ Mill Area	1	VV	MHX	769	26230
EC:50-07 6/2/92 1230	V NEPile	1		MHX	770	26231
EC-50-08 \$2/92 1340	/ ARD SE Pile	/		MHX	97/	26232
FC-50096/3/92 1220	/ N. Off-site	1		MHX	972	26233
EC-SE-0163/92 1030	Vostream	1	VV	MHX	923	26234
EC-SE-02 63/92 1055	V Mill Ditch	1	VV	MHX	974	26235
EC.SE.03 6/3/92 1/20	V Downstream	1		MHX		26236
EC-SE-045362 1205	1 Downstream PPE	1	VV	MHX		26237
EC-PS-01 8/2/92 0930 L	/ E Pond	,		MHX		26238
EC-PS-02 95/92 0945	V W, Pand	1		MHX		26239
Relinquished by: (Signature)	Date/Time Received by: (Signature)	· · · · · · · · · · · · · · · · · · ·	Relinquished by: (Signatu		Date/Time	Received by: (Signature)
Jankitter.	6/9/92 400				:	
Jasapille.	6/7/92	<u>.</u>			<u> </u>	5
Relinquished by: (Signature)	Date/Time Received by: (Signature)		Relinquished by: (Signatu	re)	Date/Time	Received by: (Signature)
Relinquished by: (Signature)	Date/Time Received for Laboratory	by:	Date/Time	Remarks		
	(Signature)		1.			,
				Spiit Samples:		
Distribution: Original Accompanies S	Shipment: First Copy to Coordinator Field Files: Second Copy to Re	epresentative of	Inspected Facility	Accepted Decil	ned	Signature .

J.S. ENVIRONM Environd	ENTAL PRO nental Servi				СН	AIN OF CUS	TODY	/ RF(CORI)		99	EGION VIII, ON 99 18TH. STREE ENVER, CO. 803	T	
PROJ. NO.	PROJEC Esse	TNAN	1E	<u></u>	3117			1120			//	//	/////	<u>.uz-z</u>	710
SAMPLERS: (S	ignature)		· ⁄	JZK	hulle	NO.		/.	/ X ^e /	//	//,	/,			REMARKS
V950		<u> </u>		Jack	hullen	CON- TAINERS	/	\ \ \ \		v /	/ /				TEMATINO
STAT. NO. DAT	E TIME	COMP.	GRAB	STATIO	ON LOCATION		\sqrt{x}	X ° C	× ×				Sample # MHX 979		795 # 8-26240 26241
EC-PW-0103/	12 0930			E Pond		2	/	/					MHX 979)	8-26240 26241
EC-PN-02 /3/	92 0945		V	W Pond	,	2	/	/				1	MHX 980		8-26242 26243
EC-PN-03/3/	92 1000		1	5 fond	•	2	/	/					MHX981		8-26244 26245
EC-GW-016/3	1110			Off-sit	e Well	2	/	/					7HX 982		8-26246 26247
		-					<u> </u>					-	····		······································
		-					<u> </u>						*		
Relinquished by	: (Signature)		6/	Date/Time 5/92/1400	Received by: (Signatu	re)	Reli	nquist	ned by	r: (Sign	ature)		Date/Tim	e	Received by: (Signature
Relinquished by	r: (Signature)			Date/Time	Received by: (Signatu	re)	Relin	quish	ed by	(Signa	ature)		Date/Tin	ne	Received by: (Signature)
Relinquished by	: (Signature)			Date/Time	Received for Laborate (Signature)	ory by:		I	Date/I	ime	Rema	arks			
Distribu	tion: Original Acc	ompanie	s Shipm	ent: Firet Copy to Coordin	ator Field Files; Second Copy	to Representative of	Inapacte	d Facili	ty			Samples oepted	: Dealined		Signature

\$EPA		Contract La	ed States boratory P PO Box 8 703-55	rogram 18 Ale	Sam xandria	oloclio ple Ma a, VA 2 557-249	nagem 2313	icy ent Office	(For	· CL	Traffic LP Use Or	Heport	18254	tiAti No. (il applicable)	
1. Type of Activity ENF NPI ER O&! ESI PA	.D RA		STSI		2. Reg Samp	jion Nu 8 Ier (Nai	mber ne)	Sampling Co. VOERR wlton	4. Date Shipped Of 6/9/92 Airbill Number 387827	410	Borne	1. Surface 2. Ground 3. Leacha			
Non-Superfund P					3. Ship	o To:	· + ·	Sherman d Ave	Double volume req spike/duplicate aqu	uired	for matrix	4. Rinsate 5. Soil/Se 6. Oil (SA	diment		
Site Name Essex Ca City, State	pper	Proc	essin	g Plant Spill ID	Wa	1+4	am	MA 02254	Ship medium and is samples in paint can See reverse for add	ıns.			(SAS) (SAS) <i>(Specii</i>	<i>'y)</i>	
Milford	Utak (A)	(B)	(C)		(D)			(E)	(F)	,,,,,,,,	(G)	(H)	<u> </u>		
CLP Sample Number (From labels)	Sample Descrip- tion (From box 5)	Concentration L=low M=med H=high	List Preserv- ative Used/Vol	or Ned	Cyanide Cyanide			Special Handling	Station Location	:	ate/Time of Sample Collection	Corresponding Organic Sample Number			
MHX964	2	4	none	1	/				EC-50-01	6/2	2 1/30	N/A			
MHX965	5	4			1				EC-50-02	1	1/55				
M4×966	3	4			/				EC-50-03	Ш	1210				
MHX967	5	4		1	V				EC-50-04		1215		_		
MX468	5	4		$\sqrt{}$	V				EC-50-05		1725				
MHX 969	5	7		V	V.				EC-50-06		1320				
M#X970	5	1		V	V				EC-50-07	V	1330				
MHX971	5	1		V	V	ļ			EC-50-08	6/1	1340		_		
MHX972	5	4			V				EC-50-09	6/3	3 1220				
MHX 973	5	4		V	V				EC-SE-01	6/	3 1030				
MHX 974	5	4		V	/				EC-SE-02	Ł	1055				
MHX 975	5	4		V	V				EC-SE-03		1120				
MHX976	5	4		. /	$\sqrt{}$				EC-SE-09		1205				
MHX 977	5-	4							ECAS-01	1 1	0930				
MHX 978	5	1	none	$\sqrt{}$					EC-PS-02		0945				
MX 979	1	4	HNO2 NaOH		V				EC-PW-01		0930				
1741980	1	4			V				EC-PW-02		0945				
M4×981	1	1	1						EC-PN-03	Γ	1000				
MHX982	2	,	HNON						EC-BW-01			V			

EBA Parma 0440 4774 000 D. L. EDA Parma 0076 C. L. L. L. L. C.

THE STATE OF THE STATE OF THE STATE OF

FROM (COMPANY NAME)		ORIGIN AIRBILL NUMBER	L 7.	/IIRBORINE	1
UTAH DEPARTMENT OF		SLC AU I HE I H	IAIT AHIMREDS	EXPRESS	+*
ADDRESS ENVIRONMENTAL QUALIT	ry j			•	
288 N 1460 W		SENDER 67413	935	EXECUTIVE OFFICES	
CITY STATE Z	P CODE (REQUIRED)			P.O BOX 662, SEATTLE, WA 98111	
SALT LAKE CITY UTL	84116	RECEIVER			•
SENT BY (NAME/DEPT) PHONE		METHOD OF PAYMENT (ASSUMED SENDER UNLESS OTHERWISE NOT	ED)	of France of	
Jason L. Knowlton (801).	536-4100	BILL BILL RECEIVER		が一個	
2/10		AIRBORNE ACCOU	ON TAL	· Matel	
Skinner + Sherman		BILL 3rd PARTY			
		CHECK NO / AM	OUNT		
300 Second Avenue	8 10 P 0. BDA	ADVANCE .		USE THIS AIRBILL FOR SHIPMENTS WITHIN THE U.S. &	
CITY STATE Z	IP CODE (REQUIRED)	BILLING REFERENCE (WILL APPEAR ON	INVOICE)	TO AND FROM PUERTO RICO. ARSENT A HIGHER SHIPMENT	
Waltham MA	02254	FNV RESP/REMED	TATION	VALUATION CAPPIED'S HARRITY	
Wall Man		6 NO OF PACKAGES WEIGHT (LBS.)	CHECK IF	POUND PER PIECE. SPECIAL	
Jeff Depado (617) 890	0-7200	SUBJECT TO CORRECTION	LETTER EXPRESS	OR CONSEQUENTIAL DAMAGES ARE NOT RECOVERABLE. SEE	
NETT HEPAOLO (BUT) OF	1200	SPECIAL INSTRUCTION		TERMS AND CONDITIONS ON REVERSE SIDE OF THIS	
4240 -10		SATURDAY HOLD AT LAB DELIVERY EXPRESS PACK		NON-NEGOTIABLE AIRBILL SCAC AIRB FED ID NO 91-0837469	•
LOW ORG ACT 4840 768	PREPRINT FORMAT NO	THANK YOU FOR		DROP OFF LOCATION	
S A L CELLOR OF COR		SHIPPING WITH AIRBORNE EXPRESSI		DIREORNE TERMINAL	
P I FULL ASSURANCE	2548845 AIRBORNE MENATURE	DATE TIME	ROUTE	F DROP BOX	
3 SENDER SIGNATURE DATE	AIRBORINE SIGNATIONS	(1/2/02	57/	No.	
1 1 6/4/9Z	(J.)	Y19195		140	
-	- ZENDER	YS COPY			i

CHAIN OF CUSTODY RECORD

proj #	proj # proj name Essex Copper samplers Jasen Know I ton bureau/company DERR																				1 1	State of Utah Department of H Division of Labo 46 Medical Driv Salt Lake City,	ratory S		5						
bureau/con	npany	<u></u>	ER,	R						╬	 	T	Т	<u> </u>	Γ				T	ī				[₂	—	П		7	lab ur	a only	7
address /9	50	W	<u> N. Te</u>	<u> </u>	<u>e</u> ph	ione 🕹	5 <u>36</u>	-41	00	- J F		SEI		'	Nag.				3	ន្ត	g	ଞ୍ଚ	2022	291-69							
cty/st/zip	S. 1	L.C.	<u>, v</u>	<u> </u>		841	16			Containers	Chemistry	Total Metals	Nutrient	ВОД	Oil & Grease	Cyanide	Sulfide	Phenol	Method 624	Method 625	Method 608	Method 8150	Method 502.2	Method 601-602	ğ	Other	TAG NUMBERS	T		AB BERS	
ID#	D	Т	Туре	-		Station		-		<u> </u>	ď	ğ	Ž	28	<u> </u> ලි	8	ङ्ग	Ě	×	Σ	ž	ž	×	ž	Other	ō					
EC-SC-01	6/3/	#20	l!	W.	Dru	<u>ک</u> سر	stor	29€	2	1									X	\times	\times								7203	227	
EC-SC-02	13/2	1520	1	W. E. W,	Tra	יא זאין	Lon	me	<u></u>	1											X								9203	3428	
EC-SC-02 EC-SC-03	6/3/	1535	1	W.	ア	an.	5/0	m	er	117											X							T	9203	6Z9	
										1								\prod			1										
				 						1			 					\Box													
										1			 					\Box										1			
										╫	 													\Box				1	130/200		
				 						╁		\vdash			H													1	10204	<u> </u>	
				-						╁	 	-						\Box					\sqcap	\sqcap				+		<u> </u>	
	<u> </u>		<u>'</u>	 				 		╢	 		 -			-	H	\sqcap	H	\vdash	H	-	$\mid - \mid$		\sqcap			+		<u>. Cara</u> Agrikari	
	 '	-		+						╢-	 		-	-	-	H	H			\vdash		$\mid - \mid$	\vdash	\vdash				+-	1 5.00 Mg		
		-	 '	┼						╢	 	 '	 	1	!	H		\vdash	₩'			\vdash	H	H		H			1, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7, 7,		
	<u> </u>	\vdash	 '							-	<u> </u> '	<u> </u>	 	\sqcup	 	\sqcup				<u> </u> '	\vdash			H	\vdash	$\left - \right $		┿	12.54 1		
	 '	igspace	 '	—						-⊩	 	<u> </u>	 	$\perp \!\!\!\! \perp \!\!\!\! \! \!\!\! \! \! \! \! \! \! \! \! \! \!$	<u> </u> -		\sqcup	\vdash	ļ!	'	\sqcup	\sqcup		H	\vdash	\parallel				dia man	
	<u> </u>	igsqcup	 '	 						╢	<u> </u>	<u> '</u>	<u> </u>	11	<u> </u>			\sqcup	<u> </u>	<u> </u>					\vdash		[1		91. 9W1.	
	<u> </u>		<u> </u>			·						<u> </u>	<u></u>	<u> </u> '	<u> </u>																L
Rel. By (st	gnature		4	H	20	372	Rel.	By (sig	gnature)				}	D	⊢ P	tel. B	By (sigi	natur	e)				D	•	- R∈	el By	y (signature)			D	
	/		w			1220							-	T	+.								T		+					T	
Rec. By (signature) D Rec. By (signature)						}	D T	- ^к	lec. B	By (sig	natur	e)				D T		Sp	oill Sa	amples (signature	:):		D								
Relinquished by (signature) D Custody Officer Lab (signature)			alure'	(d/11	0/2		+,	Remar		—							Т_					Т									
Kemiquisii	ou by (Signatu	ne)		<u> </u>	r	Bi	رقد	Ba	Jai	E	12:	147 25	T	┦ "	Cinai	KS.														

Appendix F.
Analytical Results Summary

TABLE F-1
ESSEX COPPER PROCESSING PLANT, BEAVER COUNTY, UTAH
ANALYTICAL RESULTS - SOIL SAMPLES (mg/kg)

LOCATION:	BACKGROUND	WEST PILE	BASE OF HILL	EXCAVATION	NORTH CENTRAL PILE	MILL AREA	NORTHEAST PILE	SOUTHEAST PILE	north of Site
SAMPLE #	EC-S0-01	EC-SO-02	EC-SO-03	EC-S0-04	EC-S0-05	EC-S0-06.	EC-S0-07	EC-SO-08	EC-SO-09
TRAFFIC #	мнх964	MHX965	MHX966	MHX967	MHX968	MHX969	MHX970	MHX971	WHX972
Aluminum	7980	8750	6070	4570	6090	668	9870	2640	4300
Antimony	3.2UJ	4.1UJ	3.7UJ	3.3UJ	5.7UJ	3.1UJ	4.3UJ	4.2J	3.8UJ
Arsenic	6.5J	104J	47.1J	8.7J	363J	21.9J	85.2J	202J	71.8J
Barium	108	183	87.3	34.2B	87.6	2.5U	182	44.4	97.6
Beryllium	0.63B	0.35B	0.35B	0.34B	0.51B	0.19B	0.79B	0.29B	0.36B
Cadmium	0.41U	0.51U	0.46U	0.41U	0.72U	0.38U	0.53U	1.4	0.74B
Calcium	13100J	42100J	20300J	4470J	29500J	13900J	21400J	51000J	17900J
Chromium	8.8	9.8	6.5	8.4	111	6.3	9.9	7.5	9.7
Cobalt	6.6B	12.9	9.3B	3.7B	6.4B	14.9	14.7	16.7	8.3B
Copper	189J	2780J	6270J	1150J	2120J	5370J	16500J	10300J	3880J
Iron	12900	47100J	27500	90500	96300	61300	54300	55700	24100
Lead	12.2J	197	45.9J	24.3J	152J	6.3J	62.1J	22.1J	141J
Magnesium	6820	25900	12500	4570	10700	1250	16700	5870	5910
Manganese	400J	854J	492J	98.2J	525J	1040J	748J	2910J	776J
Mercury	0.09U	0.14	0.1U	0.16	0.17U	0.09U	0.15	0.11U	0.11U
Nickel	9.2	5.4J	5.8J	3.3U	3.1U	3.2U	10.3J	5.2J	5.2J
Potassium	2800	3280	1750	5660	2430	57.2U	2460	539B	1540
Selenium	4.2UJ	0.99UJ	0.96UJ	0.83UJ	7.1UJ	R	1.1UJ	4.7U	0.96UJ
Silver	1.4J	32.9	10.5	8.9	25	14.6	15.1	10.6	6.6
Sodium	90.4J	448J	308J	1670	710J	12.9J	183J	32.8J	72.2J
Thallium	0.42U	0.5U	0.48U	0.41U	0.71UJ	0.4U	0.56U	0.44U	0.48U
Vanadium	15.4	16.5	11.9	32.7	32.7	4.7B	23.4	7.7B	14.6
Zinc	45.9	189	117	32.4	117	32	288	449	272
Cyanide	0.53U	0.63U	0.58U	0.56U	0.92U	0.51U	0.67U	0.56U	0.58U

TABLE F-2
ESSEX COPPER PROCESSING PLANT, BEAVER COUNTY, UTAH
ANALYTICAL RESULTS - SEDIMENT SAMPLES (mg/kg)

LOCATION: SAMPLE # TRAFFIC #	UPSTREAM EC-SE-01 MHX973	MILL DITCH EC-SE-02 MHX974	DOWNSTREAM EC-SE-03 MHX975	PPE EC-SE-04 MHX976	EAST POND EC-PS-01 MHX977	WEST POND EC-PS-02 MHX978
Aluminum	13700	5310	7020	6960	6860	4920
Antimony	4.1UJ	3.9UJ	3.9UJ	3.9UJ	3.9UJ	4UJ
Arsenic	10.4J	78.9J	148J	36.1J	22J	31.5J
Barium	214	125	57.9	112	85.2	52.6
Beryllium	0.88B	0.41B	0.65B	0.34B	0.47B	0.29B
Cadmium	0.52U	0.49U	3	0.49U	0.49U	0.49U
Calcium	36900J	17400J	74200J	6760J	32100J	11700J
Chromium	13	19.2	18.8	13.9	11	4.8
Cobalt	8.2B	3.1B	19.9	6.9B	7.2B	8.1B
Copper	91.3J	229J	17400J	1310J	3740J	3970J
Iron	15900	48100	56100	34200	27900	30700
Lead	110J	47.5J	90.6J	40.3J	50.1J	31J
Magnesium	9980	4330	13000	5690	6610	8740
Manganese	508J	90.7J	3420J	368J	334J	417J
Mercury	0.11U	0.11U	0.13U	0.11U	0.11U	0.13U
Nickel	13.5	5.1J	8.7J	7.4J	6.4J	4.7U
Potassium	4720	4480	793B	2650	1990	1430
Selenium	5UJ	0.9UJ	2.6J	0.98UJ	4.8UJ	0.99UJ
Silver	1.4J	4.1J	24.4	5.2	5.4	7
Sodium	219J	806J	72.2J	108J	1010J	167J
Thallium	0.5U	0.45U	0.53U	0.49U	0.48U	0.49U
Vanadium	25.6	16.4	17	19.9	13.9	10B
Zinc	. 124	37.6	1040	103	73.3	71.1
Cyanide	0.67U	0.6U	0.66U	0.65U	0.6U	0.67U

TABLE F-3
ESSEX COPPER PROCESSING PLANT, BEAVER COUNTY, UTAH
ANALTTICAL RESULTS - WATER SAMPLES (ug/L)

LOCATION: SAMPLE # TRAFFIC #	EAST POND EC-PW-01 MHX979	WEST POND EC-PW-02 MHX980	TRIP BLANK EC-PW-03 MHX981	OFF SITE WELL EC-GW-01 MHX982
Aluminum	1140000	760000	28.8B	21U
Antimony	R	R	R	R
Arsenic	R	R	R	R
Barium	R	R	R	R
Beryllium	382B	255B	1U	1U
Cadmium	713	537	1 U	1UJ
Calcium	507000	535000	28U	45300
Chromium	R	R	R	R
Cobalt	6360	4230	2U	SN
Copper	8210000	10100000	11.1U	6.4UJ
Iron	29000J	76400J	25UJ	447J
Lead	R	R	R	R
Magnesium	3140000	2070000	96.5B	11500
Manganese	430000	190000	1 U	26.4U
Mercury	1J	0.77J	0.2UJ	0.2UJ
Nickel	5490	3380	5U	5U
Potassium	314B	743B	194U	3110B
Selenium	R	R	R	R
Silver	300U	300U	3U	3U
Sodium	50200	9900	UJ	39500
Thallium	11.1J	8.5J	1U	5UJ
Vanadium	R	R	R	R
Zinc	75600	53300	80	207
Cyanide	10UJ	10UJ	10UJ	10UJ

Appendix G. Versar Analytical Results and Quality Assurance Summary DRAFT
LETTER REPORT
ESSEX COPPER
DATA VALIDATION
INORGANIC ANALYSIS
EPA CASE #18254

OCTOBER 28, 1992

Prepared For

UTAH DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF RESPONSE AND REMEDIATION SALT LAKE CITY, UTAH

Prepared By

VERSAR A & E, INC.
734 EAST UTAH VALLEY DRIVE
SUITE 100
AMERICAN FORK, UTAH 84003

TABLE OF CONTENTS

<u>Pag</u>	<u>e</u>
Introduction	1
Samples Analyzed	1
Statement of Work, Functional Guidelines	1
Evaluation Criteria	1
General Case Assessment	2
Problems and Actions	3
Attachment I - Data Assessment Summary	
Attachment II - Data Qualification Key and List of Acronyms	
Attachment III - Sample Compound Qualifications and Other Corrections	

INTRODUCTION

This report summarizes the findings of Versar A & E, Inc., in the validation of Inorganic Analyses performed by EPA contracted laboratories. The validation was completed by a Versar team following the Functional Guidelines used by the U.S. EPA Hazardous Site Evaluation Division.

One hundred percent of the reported test data and no less than 10% of the raw calculations within the sample groups were examined to check for accuracy. This work was performed as directed by the Utah Division of Environmental Response and Remediation (UDERR).

Validation was performed on all samples within EPA Case Number 18254. Included in this case were two Inorganic Sample Delivery Groups, SDG Number MHX 964 and MHX 979.

SAMPLES ANALYZED

Inorganic Sample Delivery Group (SDG) Number MHX 964 contained 15 soil samples for full Inorganic validation. Inorganic SDG Number MHX 964 contained 4 water samples, also for full Inorganic validation. Samples included in the SDGs were samples MHX 964 through MHX 979.

All samples from both Sample Delivery Groups were tested by Skinner and Sherman Labs of Waltham, Massachusetts. Sample data for this case was delivered to Versar A & E through the Utah Division of Environmental Response and Remediation (UDERR).

STATEMENT OF WORK, FUNCTIONAL GUIDELINES

The testing laboratory followed the protocol in the U.S. EPA Statement of Work (SOW) dated 3/90 for the Inorganic testing. The validation team used the same SOW during the validation, and no problems were encountered. One item of note is that the U.S. EPA Functional Guidelines for Evaluating Inorganic Analyses used by the validation team was dated 7/88 and was based on the 7/87 SOW for Inorganics. Limits and criteria found in these guidelines were checked against corresponding limits and criteria in the 3/90 SOW to ensure accurate and complete validation of EPA limits and criteria. Any differences between the 7/88 Functional Guidelines and 3/90 SOW were corrected according to the 3/90 SOW criteria.

EVALUATION CRITERIA

The evaluation of data was based on compliance of data with criteria given in the 3/90 SOW for the categories on the following page.

Inorganic Analysis Criteria

- 1. Holding Times
- 2. Calibration
- 3. Blank Analyses
- 4. ICP Interference Check Sample Results
- 5. Lab Control Sample Results
- 6. Duplicate Sample Results
- 7. Matrix Spike Sample Results
- 8. Furnace Atomic Absorption
- 9. ICP Serial Dilution Results
- 10. Sample Result Verification
- 11. Field Duplicates
- 12. Overall Assessment of Data

GENERAL CASE ASSESSMENT

In all cases, the data contained in the two sample delivery groups complied with the EPA Functional Guidelines or was qualified due to minor problems (See Attachment I for a complete listing of Regional Data Assessments and Attachment III for sample compound qualifications). Although most of the data was rated as acceptable, several problems were discovered.

The SDG MHX 964 containing EPA forms I-XIV and the associated raw data was found to be complete with all necessary data to perform the validation. Minor problems resulting in the qualification of data were detected in the evaluation of Blanks, Interference Check Samples, Duplicates, Matrix Spikes, and Furnace Atomic Absorption.

The presence of analytes in blanks resulted in the qualification of Nickel, Barium, and Potassium as undetected $(Z)^U$ in some samples. (See Problems and Actions section of this report for a list of specific samples qualified.) Analysis of Interference Check Samples (ICS) also revealed analytes not originally present in the ICS solution. This required the qualification as estimated (J) or estimated/undetected (UJ) of Sodium in all samples except MHX 967, Silver in MHX 964, 973, and 974, and Nickel in all samples except MHX 964 and MHX 973. Arsenic, Calcium, Copper and Lead in all samples were qualified as estimated (J) or estimated/undetected (UJ) because control limits were exceeded in the Duplicate Sample Analysis. Copper, Antimony, Manganese and Selenium were qualified as estimated (J) or estimated/undetected (UJ) due to Matrix Spike Recoveries being The analytes Selenium and Thallium did not meet outside limits. Furnace Atomic Absorption criteria in some samples and are qualified as J or UJ in a number of samples. One sample, MHX 969, had a low enough Furnace Post Digestion Spike recovery in the analysis for Selenium to require qualification as unusable (R) for that analyte. One transcription error was found in the validation process. It is shown corrected at the end of Attachment III.

The data package corresponding to SDG Number MHX 979 appeared complete and in order. While holding times from the sampling date to the beginning of analysis were not exceeded, it appears that the samples to be tested for cyanide were not preserved to the proper pH of 12 or greater. As a result, the cyanide results for all samples are qualified as estimated (J) or estimated/undetected (UJ), depending on the reported sample The analytes Cadmium, Copper, Manganese and concentration. Sodium were qualified as undetected (U) in one or two of the four samples because of their presence in blanks. Cadmium in MHX 982 and Sodium in MHX 981 were qualified as estimated (J) because of problems with the Interference Check Samples (ICS). Duplicate Sample Analysis showed that Arsenic, Chromium, Iron, and Mercury did not meet the required criteria and were qualified as estimated (J) or estimated/undetected (UJ). Additionally, Arsenic and Chromium did not meet the minimum criteria for the Matrix Spike Sample Analysis, nor did the analytes Antimony, Barium, Lead, Selenium, and Vanadium. The spike recovery was poor enough (less than 10% recovery) to qualify the results of these seven analytes as unusable (R) in all samples. Selenium, Lead and Thallium did not meet the Furnace Atomic Absorption criteria in some of the samples. Thallium was qualified as estimated (J) or estimated/undetected in three samples while the Arsenic, Selenium, and Lead results were already qualified as unusable (R), as noted previously. the results of many analytes in the four samples of this SDG were qualified, most qualifications applied to analytes found below Contract Required Detection Limits (CRDL).

PROBLEMS AND ACTIONS

SDG/MATRIX:
MHX 964/Soil

ANALYSIS: INORGANIC

SAMPLES VALIDATED: MHX 964-978

Holding Times: Holding times were found to be within limits prescribed for water samples except for those samples used for cyanide analysis which exceeded by one day the limits set for water samples. However, as no standard has been established for soil samples such as those in this SDG, no qualifications were made.

Blank Analyses: Nickel was qualified as undetected (U) in samples MHX 967, 968, 969, and 978, and Barium and Potassium were qualified as undetected (U) in MHX 969 because of their presence in similar quantities in the blank.

ICP Interference Check Sample (ICS): The following list of analytes were qualified in the samples indicated because of concentrations similar to those found in the ICS:

<u>Analyte</u>	Samples Qualified	Qualification
Na Ag	All Samples except MHX 967 MHX 964, 973, 974	J, UJ J
Ni	All Samples except MHX 964, 9	73 J

<u>Duplicate Samples</u>: The results for Arsenic, Calcium, Copper and Lead were qualified as estimated (J) or estimated/undetected (UJ) in all samples because the relative percent difference was outside the required limits for duplicate samples.

<u>Matrix Spike Samples</u>: The results of Antimony, Copper, Manganese and Selenium were qualified as estimated (J) or estimated/undetected (UJ) in all samples due to spike recoveries below the specified limits.

<u>Furnace Atomic Absorption</u>: Post Digestion Spike Recoveries below required levels caused the following samples to be qualified:

<u>Analyte</u>	Samples Qualified	Qualification
Se	MHX 969	R
Se	MHX 964, 965, 970, 972, 976, 977, 978	J, UJ
Tl	MHX 968	J, UJ

SDG/MATRIX:	ANALYSIS:	SAMPLES VALIDATED:	ł
MHX 979/Water	INORGANIC	MHX 979-982	

<u>Holding Times</u>: All Cyanide results were qualified estimated (J) or estimated/undetected (UJ) because the Cyanide samples were not preserved to the proper pH of 12 or greater.

Blank Analyses: Cadmium in MHX 982, Copper in MHX 981 and 982, Manganese in MHX 982, and Sodium in MHX 981 were qualified as undetected (U) because they were found in similar quantities in blanks.

ICP Interference Check Sample (ICS): Cadmium and Copper in MHX 982 and Sodium in MHX 981 were additionally qualified as estimated (J) because of similar concentrations found in the ICS.

<u>Duplicate Samples</u>: The results for Arsenic, Chromium, Iron, and Mercury were qualified as estimated (J) or estimated/undetected (UJ) in all four samples because the relative percent difference was outside the specified ±20% limit for duplicate samples.

Matrix Spike Samples: Very poor spike recoveries (below 10% recoveries) necessitated that results for Antimony, Arsenic,

Barium, Chromium, Lead, Selenium, and Vanadium be qualified as unusable (R) in all samples.

<u>Furnace Atomic Absorption</u>: Post Digestion Spike Recoveries below required levels caused the following samples to be qualified:

<u>Analyte</u>	Samples Qualified	Qualification
As	MHX 979, 980	U, UJ
Se	MHX 979, 980, 982	ບ, ບຸງ
Pb	All Samples	ບຸ່ ບຸງ
Tl	MHX 979, 980, 982	ບ. ບຸ

ATTACHMENT I DATA ASSESSMENT SUMMARIES

INORGANIC REGIONAL DATA ASSESSMENT

CASE	NO. 18254	SITE ES	SEX COPPER			
	DRATORY: SKINNER & SHERMAN LABS	NO. OF SAMPLES/				
	(SKINER)	MATRIX	15 / SOIL			
SDG	#MHX 964	REVIEW	ER (IF NOT E	SD) <u>VERSAR</u>		
	# 3/90	REVIEW	ER'S NAME_	T. YORGASC)NN	
	ACTIONFYI	COMPLE	ETION DATE_	OCTOBER 20	5, 1992	
		•				
	DATA ASSESSM	IENT SUMM	ARY			
		ICP	AA	Hg	CYANIDE	
1.	HOLDING TIMES	_0	_0	0	0	
2.	CALIBRATIONS	_0	_0	_0	_0	
3.	BLANKS	0	0	_0	0	
4.	ICS	0				
5.	LCS	0	_0			
6.	DUPLICATE ANALYSIS	_0	_0	_0	O	
7.	MATRIX SPIKE	0	_0	_0	<u> </u>	
8.	MSA		_O			
9.	SERIAL DILUTION	0				
10.	SAMPLE VERIFICATION	0	_0	_0	_0	
11.	OTHER QC	0	_0	_0	_0	
12.	OVERALL ASSESSMENT	0	_0	_0	_0	
	 O = Data had no problems/or qualified due to minor problems. M = Data qualified due to major problems. Z = Data unacceptable. X = Problems, but do not affect data. 					
ACTI	ON ITEMS: Oualifications were made because mino	r problems w	ere found with	Blanks, ICS,		
<u>Dupli</u>	cate Analysis, Matrix Spike Analysis, and Furnace A	A. Except as	noted below, r	nost ·		
qualif	ications were applied to results less than CRDL.					
AREA	AS OF CONCERN: Problems with Duplicate Sample	Analysis req	uired qualificat	ion of results	-	
<u>above</u>	CRDL for As, Ca, Cu and Pb.			······		
NOT	ABLE PERFORMANCE:					
1401	IDDI I DRI ORIMINOD.					

INORGANIC REGIONAL DATA ASSESSMENT

CASE	E NO. 18254	SITE_ES	SEX COPPER	.			
	ORATORY: SKINNER & SHERMAN LABS	NO. OF	NO. OF SAMPLES/				
	(SKINER)	MATRIX	4 / WATI	ER			
SDG	# MHX 979	REVIEW	ER (IF NOT	ESD) <u>VERSAI</u>	3		
	# 3/90	— REVIEW	ER'S NAME_	T. YORGASO	NC		
	ACTION FYI	— COMPLI	ETION DATE	OCTOBER 2	7, 1992		
D1 0.							
	DATA ASS	ESSMENT SUMM	ARY				
		ICP	AA	Hg	CYANIDE		
1.	HOLDING TIMES	_0	0	0	<u> </u>		
2.	CALIBRATIONS	_0	0	0	_O		
3.	BLANKS	0	0	0	<u> </u>		
4.	ICS	_0					
5.	LCS	_0	_0				
6.	DUPLICATE ANALYSIS	_0	0	<u> </u>	_O		
7.	MATRIX SPIKE	0	0	0	0		
8.	MSA		0				
9.	SERIAL DILUTION	_0					
10.	SAMPLE VERIFICATION	_0	_0	_0	_0		
11.	OTHER QC	_0	0	_0	_0		
12.	OVERALL ASSESSMENT	0	0	0	<u> </u>		
	 O = Data had no problems/or qualified due to minor pro M = Data qualified due to major problems. Z = Data unacceptable. X = Problems, but do not affect data. 						
	ION ITEMS: Only minor qualification of result			or qualification	s to results less		
<u>than</u>	CRDL.						
ARE	AS OF CONCERN:						
-							
	CARLE DEDECORMANCE.						
NOT	ABLE PERFORMANCE:						

ATTACHMENT II DATA QUALIFICATION KEY & LIST OF ACRONYMS

DATA OUALIFICATION KEY

- A Acceptable data.
- J The associated numerical value is an estimated quantity.
- R Reject data due to quality control criteria. The data is unusable (compound may or may not be present). Resampling and reanalysis is necessary for verification.
- U The compound was analyzed for, but was not detected. The associated numerical value is the sample quantitation limit.
- UJ The compound was analyzed for, but was not detected. The sample quantitation limit is an estimated quantity.

INORGANIC ANALYSIS QUALIFIERS

C (concentration) qualifier - either B or U. B indicates that sample result is less than CRQL, but is greater than IDL. U indicates that sample result was below the IDL.

Q qualifier - Given in a column on Form I. Entered by the laboratory and indicates specific problems with quality control. Specific entries and meanings can be found on page B-20 of the 3/90 Inorganics Statement of Work.

M (method) qualifier - Given in a column on the right side of Form I. Indicates the analysis method used and reported on Form I. Specific entries and meanings can be found on page B-20 of the 3/90 Inorganics Statement of Work.

LIST OF ACRONYMS

AA Atomic Absorption

BNA Base/Neutral/Acid Compounds - compounds

analyzed by semivolatile technique

CRDL Contract Required Detection Limit

CRQL Contract Required Quantitation Limit

GC/MS Gas Chromatograph/Mass Spectrometer

ICP Inductively Coupled Plasma

TCS Interference Check Sample

IDL Instrument Detection Limit

Initial Calibration The establishment of a calibration curve

with the appropriate number of standards

and concentration range. The

calibration curve plots absorbance or

emission versus concentration of

standards.

IS Internal Standards - Compounds added to

> every VOA and BNA standard, blank, matrix spike duplicate, and sample extract at a known concentration, prior to instrumental analysis. standards are used as the basis for

quantitation of the target compounds.

MS Matrix Spike - introduction of a known

concentration of analyte into a sample to provide information about the effect of the sample matrix on the digestion

and measurement methodology.

MS/MSD Matrix Spike/Matrix Spike Duplicate

m/z The ratio of mass (m) to charge (z) of

ions measured by GC/MS.

%D Percent Difference

Pest Pesticides

Post digestion Spike The addition of a known amount of

standard after digestion. (Also identified as analytical spike, or

spike, for furnace analyses.)

Quality Control - Routine application of QC

procedures for controlling the

monitoring process.

Relative Percent Difference (between RPD

matrix spike and matrix spike

duplicate).

Relative Response Factor RRF

RRF Average Relative Response Factor

Relative Retention Time (with relation RRT

to internal standard).

RSD Relative Standard Deviation

Retention Time RT

Serial Dilution A sample run at a specific dilution to

determine whether any significant

chemical or physical interferences exist due to sample matrix effects (ICP only).

Sample Delivery Group - Defined by one SDG

of the following, whichever occurs

first:

° Case of field samples

Each 20 field samples within a Case

 Each 14-day calendar period during which field samples in a Case are received, beginning with receipt of the first sample in the SDG. (For VOA contracts, the calendar period is 7-

day.)

Statement of Work SOW

SV Semivolatile analysis - Method based on

analysis by GC/MS for BNA organic

compounds.

TCL Target Compound List

TIC Tentatively Identified Compound - A

compound not on the TCL.

VOA Volatile Organic Analysis - Method based

on the purge and trap technique for

organic compound analysis.

ATTACHMENT III SAMPLE COMPOUND QUALIFICATIONS AND OTHER CORRECTIONS

INORGANIC ANALYSIS DATA SHEET

EFA SAMPLE NO.

MHX964

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

rix (soil/water): SOIL

el (low/med): LOW

Lab Sample ID: 06107-01S

Date Received: 06/10/92

olids:

94.0

					
CAS No.	 Analyte		Q	M I	
7429-90-5	Aluminum	7980.00		IP !	
• 1		3.20:0:	_N		<u> </u>
	Arsenic	6,50!	*	!E	
17440-39-3		108.00		¦P ;	
7440-41-7		Ø.63¦B¦		{P	
7440-43-9		Ø.41¦U¦		P	
7440-70-2	Calcium	13100.00;	*	<u> </u>	1
7440-47-3		8.80		P	
7440-48-4	Cobalt	6.60¦B¦		(P	
17440-50-8	Copper	189.00	*N	<u> </u>	<u> </u>
7439-89-6		12900.00;		(P)	
7439-92-1		12.20	*	<u>IF</u>	J_
7439-95-4		6820.00		P	
7439-96-5			<u>N</u>	<u> </u>	
7439-97-6		0.09{U		(cv)	
7440-02-0		9.20		P	
7440-09-7		2800.00		{P }	
7782-49-2		4.20 U	MN	<u>IF I</u>	<u> </u>
17440-22-4		1.40¦B		<u> </u>	<u>j</u>
7440-23-5	Sodium	90.40 B		!F!_	J_
7440-28-0		Ø.42¦U;		{F {	•
17440-62-2		15.40		P	
17440-66-6	Zinc	45.90		¦₽ ;	
1	Cyanide	0.53\U		CA	
1	1	! {		_!!	
· · · · · · · · · · · · · · · · · · ·	- · 				

mments: ROCKS						
lor After:	BROWN	•	Clarity	After:	Artifacts:	YES
lon Before:	BROWN		Clarity	Before:	Texture:	FINE

INORGANIC ANALYSIS DATA SHEET

EPA SAMPLE NO.

MHX965

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

ix (soil/water): SOIL

Lab Sample ID: 06107-02S

1 (low/med): LOW

Date Received: 06/10/92

lids:

74.0

CAS No. Analyte Concentration C Q M	_i
8750 00! P	_
7429-90-5 Aluminum 8750.00 P	
17440-36-0 Antimony 4.10 U N P	
7440-38-2 Arsenic 104.00 * F	
7440-39-3 Barium 183.00 P	
7440-41-7 Beryllium 0.35 B P	
7440-43-9 Cadmium 0.51 U P	1
7440-70-2 Calcium 42100.00 * P	<u> </u>
7440-47-3 Chromium 9.80 P	
7440-48-4 Cobalt 12.90 P	
7440-50-8 Copper 2780.00 N* P	<u> </u>
7439-89-6 Iron 47100.00 P	
7439-92-1 Lead 197.00 * F	
7439-95-4 Magnesium 25900.00 P	
7439-96-5 <u> Manganese </u>	<u>. </u>
7439-97-6 Mercury 0.14	V: (
7440-02-0 Nickel 5.40 B P	
7440-09-7 Potassium 3280.00 P	
7782-49-2 Selenium 0.99 U WN F	1 0)
:7440-22-4 Silver 32.90 P	1
7440-23-5 Sodium 448.00 B P	
7440-28-0 Thallium 0.50 U F	•
7440-62-2 Vanadium 16.50 P	
7440-66-6 Zinc 189.00 P	
Cyanide	A
	_;

on	Before:	BROWN	Clarity	Before:	Texture:	FINE
or	After:	BROWN	Clarity	After:	Artifacts:	
net	nts:					

	•		
TNORGANIC	ANALYSIS	DATA	SHEET

EPA SAMPLE NO.

MHX966

Name: SKINNER & SHERMAN LABS. Contract: 68-00-0100

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX964

·ix (soil/water): SOIL

Lab Sample ID: 06107-03S

·1 (low/med): LOW

Date Received: 06/10/92

·lids:

79.7

					
CAS No.	 Analyte	Concentration C	Q 	_ m	
7429-90-5	Aluminum	6070.00		{P }	413
7440-36-0	Antimony	3.70 U	N	<u> P</u>	<u> </u>
17440-38-2	Arsenic	47.10		<u>IF</u> !	<u> </u>
7440-39-3	Barium	87.30	1	iP i	
17440-41-7	Beryllium	(0.35¦B		IP :	
7440-43-9	Cadmium	0.46¦U	1	18	,
7440-70-2	Calcium	20300.00	*	IP I	
7440-47-3		6.50	! !	P	
17440-48-4	Cobalt	9.30 8	•	{P	
7440-50-8	Copper	6270.00;	N*	IP !	
7439-89-6		27500.00	i	P	
7439-92-1	Lead	45.90	·	<u>if</u>	<u> </u>
17439-95-4	Magnesium	12500.00	: !	IP :	
• '	Manganese	492.00	N	IP	
7439-97-6	Mercury	0.10 U		(cv:	
• -	Nickel	5.80¦B	<u>. </u>	IP L	
7440-09-7	Potassium	1750.00	i i	{P	
7782-49-2	Selenium	0.96;U	<u> </u>	IF !	LU
7440-22-4		10.50	l	!P {	
	Sodium	308.00¦B	! !	<u> </u>	<u> </u>
7440-28-0		0.48¦U	! !	F	
•	Vanadium	11.90	! {	¦ የ ¦	
7440-66-5	Zinc	117.00	f I	IP !	
!	Cyanide	0.5810	ł i	:CA:	
! ———	1	ll	:	_:_:	
·					

'n	Before:	BROWN		Clarity	Before:	Texture:	FINE
)r	After:	BROWN	•	Clarity	After:	Artifacts:	
a e r	nts:						
_							

INORGANIC ANALYSIS DATA SHEET

EPA SAMPLE NO.

MHX967

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

rix (soil/water): SOIL

Lab Sample ID: 06107-045

Date Received: 06/10/92

el (low/med): LOW

olids:

89.6

Concentration Units (ug/L or mg/Kg dry weight): MG/KG

CAS No.	Analyte	Concentration	C	0	_ m	
7429-90-5	Aluminum	4570.00			{P {	
(, +=, ,	Antimony	3.30	U;	N	IP :	<u>UJ</u>
(,	Arsenic	8.70		*	!F!_	<u> </u>
1,446	Barium	34.20	B		P	
1,440 0, 0	Beryllium	·			P	
–	Cadmium	0.41			{P	_
1,440	•	4470.00		*	1P 1	<u> </u>
(, +	Calcium	8.40			P	
111111	Chromium	3.70			P	
() ++00	Cobalt	•		N*	P !	
7440-50-8	Copper	1150.00		IV	IP I	
17439-89-6	:Iron	90500.00		*	• •	1
7439-92-1	Lead	24.30		s*	<u> </u>	
	Magnesium	4570.00			P	١
•	Manganese	98.20	نسنا	N_	<u>P</u>	
• • • • •	Mercury	0.16	-		(CV	u
	Nickel	3.30	¦B.	l		<u>u</u>
	Potassium	5660.00	: :		F	
7782-49-2	•	0.83	U	N	<u>if</u>	UJ
7440-22-4		8.90	:] [{P	
7440-22-4		1670.00	1	: 1	P	_
· ·	Thallium	0.41			{F }	•
1,440	•	32.70			¦₽ ¦	
7440-62-2	¦Vanadium	32.40		!	!P !	
17440-66-6	Zinc	9.56			CA	
i	Cyanide	4.50	, 0	t f		
!		i	٠ ١	٠	''	

or Before: BROWN

Clarity Before:

Texture: COARSE

ior After:

BROWN

Clarity After:

Artifacts: YES

nments: ROCKS

H.S. EFA - CLP

. INORGANIC ANALYSIS DATA SHEET

EPA SAMPLE NO.

MHX968

Name: SKINNER & SHERMAN LABS. Contract: 68-00-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

ix (soil/water): SOIL

Lab Sample ID: 06107-05S

Date Received: 06/10/92

:1 (low/med): LOW

olids:

52.6

Concentration Units (ug/L or mg/Kg dry weight): MG/KG

					
CAS No.	: : Analyte	Concentration C	Q	M .	
7429-90-5	Aluminum	6090.00		!P :	
•	Antimony	5.70¦U		<u> </u>	<u> </u>
1	Arsenic	363.00	*	<u> </u> F :	<u> </u>
7440-39-3	Barium	87.60	! !	{P	
	Beryllium	0.51 B		{P {	
, ,	Cadmium	Ø.72¦U	;	¦P ¦	ā
	Calcium	29500.00	<u>*</u>	<u>ip i</u>	J
7440-47-3		111.00	!	IP !	
	Cobalt	6.40¦B		¦₽ ¦	
•	Copper	2120.00;	N*	IP I	<u>J.</u>
• • •	Iron	96300.00	ľ	{P }	•
• • -	Lead	152.00	<u> </u>	F	
	Magnesium	10700.00	! !	IP !	
7439-96-5		525.00	<u> N</u>	<u> </u>	
17439-97-6		0.17¦U		(cv)	
7440-02-0		3.10 8	<u> </u>	<u> IP</u>	<u>. U</u>
17440-09-7	Potassium		1	IP I	
7782-49-2	Selenium	7.10¦U	WN	<u> </u> F	<u>uj</u>
7440-22-4		25.00	1 (¦₽ ¦	
7440-23-5	Sodium	710.00 B		IP I	
7440-28-0	Thallium	<u>0.71¦U</u>	W	F	<u> </u>
7440-62-2	Vanadium	32.70	1	IP I	
7440-66-6	Zinc	117.00	¢ i	P	
!	Cyanide	; 0.92¦U	[CA	
!		[!	_!!	
·					

1	Ret	ore	•	BROWN	

Clarity Before:

Texture: COARSE

or After: BROWN , Clarity After:

Artifacts: YES

ments: ROCKS

0ô

	L		
INORGANIC	ANALYSIS	DATA	SHEET

EPA SAMPLE NO.

MHX969

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

ix (soil/water): SOIL

Lab Sample ID: 06107-063

1 (low/med): LOW

Date Received: 06/10/92

lids:

95.4

						-
CAS No.	: Analyte	 Concentration	С	Q	M	
7429-90-5	Aluminum	668.00	-:		P	
7440-36-0	Antimony	3.10	U¦	N	۱۳ ا	<u> </u>
7440-38-2	Arsenic	21.90			للكل	
7440-39-3	Barium	2.50	B		¦P '	U_
7440-41-7	Beryllium	0.19	U;		¦₽ ;	
7440-43-9		0.38	U		¦P ¦	
7440-70-2		13900.00		*	¦P :	<u> </u>
7440-47-3	Chromium	6.30	;		¦P	
7440-48-4	Cobalt	14.90	- {		{P }	
7440-50-8	Copper	5370.00		N*	iP_	7
7439-89-6	Iron	61300.00	1		P	
7439-92-1	Lead	6.30	1	*	IF !	<u>. J</u>
7439-95-4	Magnesium	1250.00	1		IP :	_
	Manganese			_N	ناهانا	
7439-97-6		0.09	U¦		CV	
7440-02-0	Nickel	3.20	B		IP !	U_
7440-09-7		57.20	В:		(P)	
7782-49-2		4.00	U	EN	¦F	R
7440-22-4		14.60	1		1P 3	
7440-23-5		12.90	U;		IP !	NI
7440-28-0		0.40	U¦		(F)	
7440-62-2	Vanadium	4.70	B		P	
7440-66-6	Zinc	32.00	:		{P }	
!	Cyanide	0.51	U¦		CA	
!	1		_:		_! ;	
·						

)'''					
1er	nts:						
'n	After:	BLACK	,	Clarity	After:	Artifacts:	
'n	Before:	BLACK		Clarity	Before:	Texture:	FINE

INORGANIC ANALYSIS DATA SHEET

EPA SAMPLE NO.

MHX970

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

rix (soil/water): SOIL

Lab Sample ID: 06107-07S

el (low/med): LOW

Date Received: 06/10/92

olids:

70.2

1	į	•		i	
Analyte	Concentration	C!	Q	{ M	
.]		_į.		_!!	
Aluminum		i		-	
Antimony	4.30	U¦.			<u>w</u>
Arsenic	85.20		<u>*</u>		
¦Barium	182.00	1		•	
Beryllium	·			{P	
Cadmium	0.53	U¦		¦P	١,
Calcium	21400.00		*		<u>. J</u>
Chromium	9.90	;		¦P	
Cobalt	14.70	1		IP :	
Copper	16500.00	:	N*	IP I	
Iron	54300.00	- {		{P }	
Lead	62.10	<u>:</u>	*	JF J	
Magnesium	16700.00	1		IP :	,
Manganese	748.00	- 1	N	IP_	J_
Mercury	0.15	ŧ		CV	•
Nickel	10.30	<u>B </u>		IP.	<u> </u>
Potassium	2460.00	ŧ			
Selenium	1.10	<u>u:</u>	WN		77
Silver	15.10	- [{P }	
Sodium	183.00	<u>B ¦</u>		P	<u> </u>
Thallium	0.56	U¦		if :	
Vanadium	23.40	1		IP I	
Zinc	288.00	ť		¦P ¦	
Cyanide	0.67	U¦		CA	
	ll .	_:		_11	
	Aluminum Antimony Arsenic Barium Beryllium Cadmium Calcium Chromium Cobalt Copper Iron Lead Magnesium Manganese Mercury Nickel Potassium Selenium Silver Sodium Thallium Vanadium Zinc	Aluminum 9810.00 Antimony 4.30 Arsenic 85.20 Barium 182.00 Beryllium 0.79 Cadmium 0.53 Calcium 21400.00 Chromium 9.90 Cobalt 14.70 Copper 16500.00 Iron 54300.00 Manganese 748.00 Mercury 0.15 Nickel 10.30 Potassium 2460.00 Selenium 1.10 Sodium 183.00 Thallium 0.56 Vanadium 23.40 Zanc 288.00	Antimony 4.30 U Arseric 85.20	Aluminum	Aluminum

.or	Before:	BROWN		Clarity	Before:	Texture:	COARSE
or	After:	BROWN	4	Clarity	After:	Artifacts:	
amei	nts:			•			

INORGANIC ANALYSIS DATA SHEET

EFA SAMPLE NO.

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

ix (soil/water): SOIL

el (low/med): LOW

Lab Sample ID: 06107-08S

Date Received: 06/10/92

olids:

83.0

CAS No. Analyte Concentration C G M							
7429-90-5 Aluminum 4,20 B N P 7440-36-0 Antimony 4,20 B N P 7440-38-2 Arsenic 202.00 S* F 7440-41-7 Beryllium 0.29 B P 7440-43-9 Cadmium 1.40 P 7440-47-3 Chromium 7.50 P 7440-47-3 Chromium 7.50 P 7440-50-8 Copper 10300.00 N* P 7439-92-1 Lead 22.10 S* F 7439-95-4 Magnesium 5870.00 P 7439-97-6 Mercury 0.11 U CV 7440-02-0 Nickel 5.20 B P 7440-02-0 Nickel 5.20 B P 7440-22-4 Silver 10.60 P 7440-22-4 Silver 10.60 P 7440-23-5 Sodium 7.70 B P 7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P	CAS No.	¦ Analyte	 Concentration 	c	Q)	M	
7440-36-0 Antimony 4,20 B N P 7440-38-2 Arsenic 202.00 S* F 7440-39-3 Barium 44.40 P 7440-41-7 Beryllium 0.29 B P 7440-43-9 Cadmium 1.40 P 7440-47-3 Chromium 7.50 P 7440-48-4 Cobalt 16.70 P 7440-50-8 Copper 10300.00 N* P 7439-92-1 Lead 22.10 S* F 7439-97-6 Manganese 2910.00 N P 7439-97-6 Mercury 7440-02-0 Nickel 5.20 B P 7440-09-7 Potassium 539.00 B P 782-49-2 Selenium 4.70 B N F 7440-22-4 Silver 10.60 P 7440-22-3 Sodium 7.70 B P 7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 20.20	7429-90-5	Aluminum	•			• • •	1
7440-38-2 Arsenic 202.00 S* F 7440-39-3 Barium 44.40 P 7440-41-7 Beryllium 0.29 B P 7440-43-9 Cadmium 1.40 P 7440-70-2 Cadmium 51000.00 * P 7440-47-3 Chromium 7.50 P 7440-48-4 Cobalt 16.70 P 7440-50-8 Copper 10300.00 N* P 7439-89-6 Iron 55700.00 P 7439-95-4 Magnesium 5870.00 P 7439-96-5 Manganese 2910.00 N P 7440-02-0 Nickel 520 B P 7440-09-7 Potassium 539.00 B P 7440-22-4 Silver 10.60 P 7440-23-5 Sodium 32.80 B P 7440-28-0 Thallium 0.44 U F 7440-66-6 (Zinc 449.00 P)							<u>-</u>
7440-39-3 Bartum 0.29 B P 7440-41-7 Beryllium 0.29 B P 7440-43-9 Cadmium 1.40 P 7440-70-2 Calcium 51000.00 * P 7440-47-3 Chromium 7.50 P 7440-50-8 Copper 10300.00 N* P 7439-89-6 Iron 55700.00 P 7439-95-4 Magnesium 5870.00 P 7439-96-5 Manganese 2910.00 N P 7440-02-0 Nickel 5.20 B P 7440-02-0 Nickel 5.20 B P 782-49-2 Selenium 539.00 B P 7440-22-4 Silver 10.60 P 7440-28-0 Thallium 0.44 U F 7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 7440-00 P 7440-66-6 Zinc 7440-00 P 7440-66-6 Zinc	7440-38-2	Arsenic	202.00		<u>s*</u>		ع د
7440-41-7 Beryllium 0.29 B P	7440-39-3	Barium	, , , , , , , , , , , , , , , , , , , ,			• :	
7440-43-9 Cadmium 1.40			•			• • • • • • • • • • • • • • • • • • • •	
7440-70-2 Calcium 7.50 P 7440-47-3 Chromium 7.50 P 7440-48-4 Cobalt 16.70 P 7440-50-8 Copper 10300.00 N* P 7439-89-6 Iron 55700.00 P 7439-92-1 Lead 22.10 S* F 9 9 9 9 9 9 9 9 9			1.40	;		• • •	١
7440-47-3 Chromium 7.50 P 7440-48-4 Cobalt 16.70 P 7440-50-8 Copper 10300.00 N* P 7439-89-6 Iron 55700.00 P 7439-92-1 Lead 22.10 S* F 7439-95-4 Magnesium 5870.00 P 7439-97-6 Manganese 2910.00 N P 7439-97-6 Mercury 0.11 U CV 7440-02-0 Nickel 5.20 B P 7440-09-7 Potassium 539.00 B P 7782-49-2 Selenium 4.70 B N F 7440-23-5 Sodium 32.80 B P 7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 7.70 B P 7440-66-6 Zinc 7.70 B P 7	7440-70-2	Calcium	51000.00	:_	*		
7440-48-4 Cobalt 16.70 P			•	1			
7440-50-8 Copper 10300.00 N* P 7439-89-6 Iron 55700.00 P 7439-92-1 Lead 22.10 S* F 7439-95-4 Magnesium 5870.00 P 7439-96-5 Manganese 2910.00 N P 7439-97-6 Mercury 0.11 U CV 7440-02-0 Nickel 5.20 B P 7440-09-7 Potassium 539.00 B P 7782-49-2 Selenium 4.70 B N F 7440-22-4 Silver 10.60 P 7440-23-5 Sodium 32.80 B P 7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 249.00 P Zinc Zin			16.70	;		•	1
7439-89-6 Iron 55700.00 P					_N*		
7439-92-1 Lead 22.10 S* F 3 7439-95-4 Magnesium 5870.00 P 7439-96-5 Manganese 2910.00 N P 7439-97-6 Mercury 0.11 U CV 7440-02-0 Nickel 5.20 B P 7440-09-7 Potassium 539.00 B P 7782-49-2 Selenium 4.70 B N F 7440-22-4 Silver 10.60 P 7440-23-5 Sodium 32.80 B P 7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 2.10 P 7440-66-6 Zinc 449.00 P 7440-66-6 Zinc 2.10 Zinc 2.10 Zinc Zinc 2.10 Zinc	, - ·		{ 55700.00¦	ť		•	,
7439-95-4 Magnesium 5870.00 P			22.10		<u>s*</u>		٠.
7439-96-5 Manganese 2910.00 N P			5870.00	:		•	. 1
7439-97-6 Mercury 0.11 U CV 7440-02-0 Nickel 5.20 B P		Manganese			N		<u>_</u>
7440-02-0 Nickel 5.20 B P 7440-09-7 Potassium 539.00 B P 7782-49-2 Selenium 4.70 B N F 7440-22-4 Silver 10.60 P 7440-23-5 Sodium 32.80 B P 7440-28-0 Thallium 0.44 U F 7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P P 7440-66-6 Zinc 449.00 P P 7440-66-6 Zinc 449.00 P P P P P P P P P			0.11	_			,
7440-09-7 Potassium 539.00 B P			5.20	<u>B¦</u>			لل
7782-49-2 Selenium 4.70 B N F			,			•	,
7440-22-4 Silver 10.60 P			4.70	Bi	_N		<u> </u>
7440-23-5 Sodium 32.80 B P N N N N N N N N N						• • •	,
7440-28-0 Thallium 0.44 U F							<u>. </u>
7440-62-2 Vanadium 7.70 B P 7440-66-6 Zinc 449.00 P			4			•	
7440-66-6 [Zinc 449.00] P			7.70	в;		• :	
	-					¦₽ {	
	1	¦Cyanide	0.56	υ¦		CA	
	!	. ,	1	_;			

	After:	BROWN	,	Clarity	After:	Artifacts:	
men	ts:						

INORGANIC ANALYSIS DATA SHEET

EPA SAMPLE NO.

MHX972

Name: SKINNER & SHERMAN LABS. Contract: 68-00-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

ix (soil/water): SOIL

Lab Sample ID: 06107-09S

Date Received: 06/10/92

1 (low/med): LOW olids:

80.3

				1 1	
CAS No.	 Analyte	 Concentration C 	Q	m	
7429-90-5	. Aluminum	4300.00		P	
•		3.80¦U¦	N	18 1	U_
7440-36-0	Antimony	71.80;	*	!F :	1
17440-38-2	Arsenic	97.60		:P :	
7440-39-3	Barium	0.74171		iP i	
17440-41-7				• •	
17440-43-9	:Cadmium	0.74 B	*	P	1
7440-70-2	Calcium_	17900.00		<u> </u>	J
7440-47-3	Chromium	9.70		IP 1	
7440-48-4	Cobalt	8.30¦B¦		{P	1
17440-50-8	Copper	3880.00	N*	<u> </u>	
7439-89-6	Iron	24100.00		{P {	
7439-92-1	Lead	141.00	*	<u>ie i</u>	<u> </u>
17439-95-4	Magnesium	5910.00;		{P {	
•	Manganese		N	1P 1	<u> </u>
1	Mercury	Ø.11¦U¦		(CV)	
17439-97-6	-	5.20 B		1P 1	ن ل
7440-02-0	Nickel	1212 221 1		IP :	
17440-09-7	Potassium	0.96¦U	WN	IF I	\mathcal{U}
7782-49-2		6.60		IP :	*
17440-22-4	Silver	72.20 B		iP i	1
7440-23-5	Sodium			F	``` ,
7440-28-0	¦Thallium	0.48 U		:P :	
7440-62-2	¦Vanadium	14.60			
17440-66-6	{Zinc	; 272.00		\P \	
	¦Cyanide	0.58¦U		CA	
!	1			_;;	
· · · · · · · · · · · · · · · · · · ·					

	 -					
or Before:	BROWN		Clarity	Before:	Texture:	FINE
or After:	BROWN	4	Clarity	After:	Artifacts:	
ments:						

	1		
INORGANIC	ANALYSIS	DATA	SHEET

EPA SAMPLE NO.

MHX973

Name: SKINNER & SHERMAN LABS. Contract: 68-00-0109

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX964

^ix (soil/water): SOIL

Lab Sample ID: 06107-10S

el (low/med): LOW

Date Received: 06/10/92

olids:

74.4

CAS No.	: Analyte		Q	M	
7429-90-5	Aluminum	13700.00		P	กา
7440-36-0	Antimony	4.10¦U¦	N	<u> </u>	
7440-38-2	Arsenic	10.40		<u> </u>	
7440-39-3	Barium	214.00		\P	
7440-41-7	Beryllium			P	
7440-43-9	Cadmium	0.52 U		18 1	1
7440-70-2		36900.00	<u>*</u>	<u> </u>	
7440-47-3		13.00			
7440-48-4	Cobalt	8.20 B		P	1
7440-50-8	Copper	91.30	N*	<u> </u>	
7439-89-6		15900.00		IP I	1
7439-92-1	Lead	110.00	<u>s*</u>	IF I	<u></u>
7439-95-4	Magnesium	9980.00		{P }	1
	Manganese	508.00:	<u>N</u>	<u>iP</u>	
7439-97-6		(0.11;U;		cv	
7440-02-0		13.50		IP !	
7440-09-7		4720.00		P	ບປ
7782-49-2	•	5.00 U		<u> </u>	
7440-22-4		1.40¦B;		<u> </u>	<u>. </u>
7440-23-5		219.00 B		<u> </u>	<u> </u>
7440-28-0		0.50;U;		{F }	
17440-62-2		25.60		IP I	
7440-62-2	Zinc	124.00		{P }	
1/446-00-0	Cyanide	Ø.67¦U	i	CA	
i	(

				
ments:				
or After:	BROWN ,	Clarity After:	Artiracts.	
or belove.	Britanii		Artifacts:	
or Before:	RPOWN	Clarity Before:	Texture:	FINE

	1		
INORGANIC	ANALYSIS	DATA	SHEET

EPA SAMPLE NO.

MHX974

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX964

rix (soil/water): SOIL

Lab Sample ID: 06107-11S

el (low/med): LOW

Date Received: 06/10/92

olids:

81.9

CAS No.	¦ Analyte	Concentration	C:	Q	_ m	
7429-90-5	Aluminum	5310.00	ť		!P !	
7440-36-0	Antimony	3.90	U	N_	<u> </u>	<u> </u>
7440-38-2	Arsenic	78.90		*	<u>IF</u> .	
7440-39-3	Barium	125.00	:		P	
7440-41-7		0.41	в;		¦₽ ¦	
7440-43-9		0.49	U¦		P	
7440-70-2	· ·	17400.00	- !	*	P	1
7440-47-3		19.20			P	
7440-48-4		3.10	В¦		P	
7440-50-8		229.00		N*	<u> </u>	
7439-89-6		48100.00	:		P	_
7439-92-1		47.50	1	s*_	IF !	
7439-95-4	Magnesium	4330.00	1		P	
•	Manganese		1	N	IP I	_4
7439-97-6		0.11	U¦		CV	
7440-02-0		5.10	B		IP 1	<u>. J</u>
	Potassium	4480.00	1		P	
7782-49-2	Selenium	0.90	U	N	<u> </u>	<u> </u>
7440-22-4		4.10			IP!	<u> </u>
7440-23-5	Sodium	806.00	В¦		<u> </u>	
7440-28-0	Thallium	0.45	U		{F {	•
7440-62-2	Vanadium	16.40	1 1		;P ;	
7440-66-6	Zinc	37.60	: :		P	
!	Cyanide	0.60	U¦		CA	
!		[-1		;;	
·						

mei	nts:						
or	After:	BROWN	•	Clarity	After:	Artifacts:	
or	Before:	RKOMIA	•	Clai It/			
	- 1	DDOUN!		Clarity	Refore:	Texture:	FINE

INORGANIC ANALYSIS DATA SHEET

EPA SAMPLE NO.

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX964

ix (soil/water): SOIL

Lab Sample ID: 06107-12S

:1 (low/med): LOW

Date Received: 06/10/92

olids:

75.5

•	1			: :
CAS No.	: : Analyte	Concentration C	Q	m
7429-90-5	Aluminum	7020.00		P
1,42, ,4	Antimony	3.90 U	N	(P : U)
17440-36-0	Arsenic	148.00		!F ! J
17440-38-2		57.90		!P !
7440-39-3		- (5151		; ; ;
(,	Beryllium			!P :
17440-43-9		3.00	*	P J
17440-70-2	:Calcium	74200.00		
7440-47-3	Chromium	18.80		P
17440-48-4	Cobalt	19.90		{P
7440-50-8	Copper	17400.00	N*	ip j
17439-89-6	Iron	56100.00		{P }
7439-92-1	Lead	90.60;	<u>s*</u>	iF i 1
7439-95-4	Magnesium	13000.00;		!P !
17439-96-5	Manganese	3420.00	N	IP! J
7439-97-6		0.13¦U¦		cv!
7440-02-0		8.70¦B¦		<u> P </u>
7440-09-7	Potassium	793.00 B		¦P ¦
7782-49-2	•	2.60	SN	<u> F </u>
17440-22-4	Silver	24.40;		{P
	Sodium	72.20 8		<u> </u>
17440-28-0	Thallium	0.53 U		F
7440-62-2	Vanadium	17.00		P
17440-66-6	Zinc	1040.00		{P {
1/448-00-0	Cyanide	0.66 U		[CA]
<u> </u>	Cyanice			
i	_			.,

יוני	Before:	BROWN		Clarity	Before:	Texture:	FINE
or	After:	BROWN	,	Clarity	After:	Artifacts:	
ner	nts:						

	1		
TNORGANIC	ANALYSIS	DATA	SHEET

EPA SAMPLE NO.

MHX976

Name: SKINNER & SHERMAN LABS. Contract: 68-00-0109

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX964

rix (soil/water): SOIL

Lab Sample ID: 06107-13S

Date Received: 06/10/92

el (low/med): LOW

14

olids:

75.1

					•
CAS No.	: Analyte		Q	M	
7429-90-5	Aluminum	6960.00		P	
17440-36-0	Antimony	3.90¦U¦	N _	IP I	<u> </u>
• • • • •	Arsenic	36.10;	*	F	J
17440-38-2	Barium	112.00		!P !	
17440-39-3	1	·		:P:	
7440-41-7	Beryllium	0.49\U		IP I	
7440-43-9	Cadmium		*	ip i	J
17440-70-2	Calcium	6760.00		IP I	
7440-47 - 3	Chromium	13.90		- :	
17440-48-4	Cobalt	6.90 B		IP I	1
17440-50-8	Copper	1310.00	<u>N*</u>	<u>IP</u>	<u>J</u> _
17439-89-6	:Iron	34200.00;		IP !	,
7439-92-1	Lead	40.30	s*	iF.i	J
7439-95-4	Magnesium			IP I	1
17439-96-5	Manganese	368.00	_N	نطب	7
7439-97-6	Mercury	0.11¦U¦		(CV)	
7440-02-0	Nickel	7.40¦B¦		<u>ip i</u>	<u> </u>
17440-09-7	Potassium	2650.00		IP :	
7782-49-2	Selenium	0.98¦U¦	WN	<u>if</u>	77
17440-22-4	Silver	5.20		{P }	
7440-23-5	Sodium	108.00 B		iP i	<u> </u>
7440-28-0	Thallium	0.49 U		IF I	•
7440-62-2	Vanadium	19.90		¦P ¦	
7440-66-6	Zinc	103.00;		P	
(,445,000	Cyanide	0.65¦U¦		CA	
·	!	[_;;	
I	-·- 				

nme	nts:						
.or	After:	BROWN	•	Clarity	After:	Artifacts:	
or	Before:	BROWN		Clarity	Before:	Texture:	COARS

	1		
TNORGANIC	ANALYSIS	DATA	SHEET

EPA SAMPLE NO.

MHX977

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX964

ix (soil/water): SOIL

Lab Sample ID: 06107-14S

≥1 (low/med): LOW

Date Received: 06/10/92

olids:

76.2

Concentration Units (ug/L or mg/Kg dry weight): MG/KG

				1 1	
CAS No.	Analyte		Q	M	
i	i	6860.00		P	
1/44/	Aluminum	3.90101	N	1P 1	\mathcal{M}
• • • •	Antimony	22.00	*	!F !	J
• •	Arsenic	85.20		IP :	
1/440 0: -	Barium	- 47171		P	
(/	Beryllium	Ø.47¦B¦		!P !	
7440-43-9	Cadmium	0.49\U	*	•	١
7440-70-2	Calcium	32100.00		<u> </u>	<u>J</u>
	Chromium	11.00		IP !	
7440-48-4		7.20 B		IP :	ı
7440-50-8	Copper	3740.00	N*	IP :	<u> </u>
7439-89-6	Iron	27900.00:		P	
17439-89-0	Lead	50.10	s*	if i	<u> </u>
•	Magnesium	6610.00;		IP :	
17439-95-4		77/ 001 1	Ν	IP :	<u> </u>
1,40,	Manganese	0.11¦U¦		[CV]	
7439-97-6	Mercury	6.40 B		!P !	7
1/440 0= -	Nickel			IP I	
: 7440-09-7	Potassium	4.80;0;	WN	iF i	NJ
7782-49-2			4414	!P !	
7440-22-4	Silver	5.40		P	١.
7440-23-5	Sodium	1010.00 B			 :
7440-28-0	¦Thallium	0.48 U		{F {	
7440-62-2	¦Vanadium	13.90		IP I	
7440-66-6	Zinc	73.301		P	
1	Cyanide	0.60¦U¦		CA	ı
!	!			_1 5	
· · · · · · · · · · · · · · · · · · ·	_ ·	•			

or Before: GREY Clarity Before:

Texture: COARSE

or After: GREY ' Clarity After:

Artifacts:

mε	'n	t	s	:	
----	----	---	---	---	--

	1		
TNORGANIC	ANALYSIS	DATA	SHEET

EPA SAMPLE NO.

MHX978

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX964

ix (soil/water): SOIL

Lab Sample ID: 06107-15S

:1 (low/med): LOW

Date Received: 06/10/92

olids:

74.3

7440-36-0 Arsenic 31.50	
7440-36-0 Antimony 4.00 U N P	11
7440-38-2 Arsenic 31.50	'n
7440-39-3 Barium	<u>J</u>
7440-41-7 Beryllium	
7440-70-2 Calcium 11700.00	
7440-70-2 Calcium 11760.00	
7440-47-3 Chromium	<u>J</u> _
7440-48-4 Cobalt 3970.00 N* P	
7440-50-8 Copper 3970.00 N* P	,
7439-89-6 1	<u>L</u>
7439-92-1 Lead 31.00	
7439-95-4 Magnesium 8740.00 P	1
7439-96-5 Manganese 417.00 N P	١
7439-97-6 Mercury 0.13 U CV	<u>J</u>
7440-02-0 Nickel 4.70 B	u
7440-09-7 Fotassium	<u>J</u> _
7782-49-2 Selenium	11
7440-22-4 Silver	17
17/4/0-23-5 (Sodium 1 10/100/0)	,
	7
!7440-28-0 Thallium 0.49 U	•
17440-62-2 Vanadium 10.00 B P	
17440-66-6 Zinc 71.10 P	
Cyanide 0.67 U CA	

_							
met ——	nts:						
or	After:	GREY	•	Clarity	After:	Artifacts:	
or	Before:	GREY		Clarity	Before:	Texture:	COARSE

13 PREPARATION LOG

Name: SKINNER & SHERMAN LABS. Contract: 68-00-0109

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX964

:hod: F

EPA !	Preparation :	Weight !	Volume :
Sample No.	Date :	(gram)	(mL)
LCSS	07/02/92	1.00	200
MHX964	07/02/92:	1.01	200
MHX964D	07/02/92:	1.06	200
MHX9645 !	07/02/92	1.07	200
MHX965	07/02/92	1.09	200
MHX966	07/02/92	1.05 0.25 ;	200
MHX967	07/02/92	1.08	200
MHX968	07/02/92:	1.07	200
MHX969	07/02/92:	1.04	200
MHX970	07/02/92:	1.02	200
MHX971	07/02/92	1.09	200
MHX972	07/02/92:	1.04;	200
MHX973	07/02/92	1.08	200
MHX974	07/02/92	1.09	200
MHX975	07/02/92	1.00	200
MHX976	07/02/92	1.09	200
MHX977	07/02/92	1.09	200
MHX978	07/02/92	1.09	200
PBS	07/02/92	1.00	200
			!
		· · · · · · · · · · · · · · · · · · ·	
		{	 !
i			 !
			 !
			{
]			!

FORM XIII - IN

ILM02.0

11.5. EPA - CLF

INORGANIC ANALYSIS DATA SHEET

EFA SAMPLE NO.

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109 |

MHX979

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX979

ix (soil/water): WATER

Lab Sample ID: 06109-01S

:1 (low/med): LOW

Date Received: 06/10/92

olids:

0.0

Concentration Units (ug/L or mg/Kg dry weight): UG/L

	1		- :		: :	
CAS No.	Analyte	Concentration	c	Q	M	
7429-90-5	:Aluminum	1140000.00			{P }	
7440-36-0		1100.00	Ul	N	JP_	R
7440-38-2		10.00	U!	WN*	!F !	<u> </u>
7440-39-3		5.00	ui	N	ip_i	<u>R</u>
7440-41-7		382.00	в¦		iP :	
7440-43-9		713.00	;		1P :	
7440-70-2	Calcium	507000.00	:		IP :	
17440-47-3	-	869.00		*N	IP i	<u> </u>
7440-48-4		6360.00			{P ;	
17440-50-8	Copper	8210000.00	1		1P :	
17439-89-6		29000.00		*	;P ;	<u> </u>
17439-89-0		19.00		WN	IF :	_R_
: 7439-92-1 ! 7439-95-4		7117700 001			;P ;	
	Manganese				1P 1	
		1.00		*	[CV	J
7439-97-6		5490.00			iP i	
7440-02-0					IP I	
17440-09-7	• •	40.00		WN	!F !	R
7782-49-2		300.00			18	
7440-22-4		50200.00			!Р :	
7440-23-5	_	11.10		W	F	J
7440-28-0		200.00		N	!P !	R
17440-62-2	Vanadium	75600.00			:P	
7440-66-6	{Zinc	10.00			•	0.7
!	Cyanide	10.00	7		<u> </u>	
1	_1	.i			-''	

or.	Before:	GREEN

Clarity Before: CLOUDY

Texture:

GREEN or After:

Clarity After: CLOUDY Artifacts:

ments:

INORGANIC ANALYSIS DATA SHEET

MHX980

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX979

rix (soil/water): WATER

Lab Sample ID: 06109-02S

/el (low/med): LOW

Date Received: 06/10/92

olids:

0.0

						-
CAS No.	: Analyte	Concentration	C:	Q	M	
7429-90-5	Aluminum	760000.00	_;		{P	! !
7440-36-0	Antimony	1100.00	U	N	IP :	R
17440-38-2	Arsenic	10.00		WN*	¦F ;	HA R
7440-39-3	Barium	5.00	U:	N	IP 3	R
7440-41-7	Beryllium	255.00	в¦		IP :	
7440-43-9	1 .	537.00	1		IP :	
17440-70-2	:Calcium	535000.00	1		1P :	
7440-47-3		737.00	B:	N*	IP.	X R
17440-48-4	Cobalt	4230.00			IP :	
7440-50-8	Copper	10100000.00	:		IP :	<u>.</u>
7439-89-6	Iron	76400.00		*	IP :	J
7439-92-1	Lead	9,50	U	WN	JE_	R
17439-95-4	Magnesium				IP :	
17439-96-5			:		IP :)
7439-97-6	Mercury	0.77	1	*	CV	<u>.</u>
7440-02-0	Nickel	3380.00	:		1P	
7440-09-7	!Potassium	743.00	в:		IP :	
7782-49-2	,,	20.00	U:	WN	iF.	R
17440-22-4	Silver	300.00	U!		IP :	
7440-23-5	Sodium	9900.00	1		IP :	
7440-28-0	:Thallium_	8.50	ВĽ		ַ£_ੂ	
7440-62-2	Vanadium	200.00	U¦	N	IP_	R
7440-66-6	Zinc	53300.00		,	{P }	•
1	Cyanide	10.00	U		CA	UJ
1	1	!				
	_ (··				

lon	Before:	GREEN		Clarity	Before:	CLOUDY	Texture:
lor	After:	GREEN		Clarity	After:	CLOUDY	Artifacts:
nmer	nts:		,				
							

1 INORGANIC ANALYSIS DATA SHEET

	EPA SAMPLE N

Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109

MHX981

Code: SKINER Case No.: 18254 SAS No.:

SDG No.: MHX979

rix (soil/water): WATER

Lab Sample ID: 06109-03S

el (low/med): LOW

Date Received: 06/10/92

olids:

0.0

CAS No.	 Analyte	Concentration	c Q	m	
7429-90-5	Aluminum	28.80	B	P	
17440-36-0	Antimony	11.00	U¦ N	<u> </u>	<u>_R</u>
17440-38-2	Arsenic	2.00		<u> </u>	WR
17440-39-3	Barium	5.00		!P!	R
17440-41-7	Beryllium			{P {	•
17440-41-7	Cadmium _	1.00	_	. ¦P ¦	•
17440-43-9	Calcium	28.00		IP !	
	Chromium		U! N*	P	DK R
17440-47-3		2.00		iP :	
17440-48-4	Cobalt	11.10		!P !	U.AU_
17440-50-8	Copper	25.00		!P !	UJ
17439-89-6	Iron	2.40		!F :	R
7439-92-1	Lead			IP I	
7439-95-4	Magnesium	4 001		iP i	
7439-96-5	Manganese			cv	VJ
 7439-97-6	Mercury	0.20		IP !	
17440-02-0	Nickel	5.00		• • • • • • • • • • • • • • • • • • • •	
17440-09-7	Potassium	194.00		;P ;	R
7782-49-2	Selenium		U! N	<u> </u>	
7440-22-4	Silver	3.00		P	(L)
7440-23-5	Sodium	191.00		<u> </u>	
7440-28-0	Thallium	1.00		IF :	
7440-62-2	Vanadium_		UIN	<u></u>	R.
7440-66-6	Zinc	8.00	U¦	{P	1
!	Cyanide	10.00	U	!CA!	<u>uJ</u>
1	!				
· I	_ '				

mer	nts:	,				
or	After:	COLORLESS	Clarity	After:	CLEAR	Artifacts
or	Before:	COLORLESS	Clarity	Before:	CLEAR	Texture:

INORGANIC ANALYSIS DATA SHEET

EPA	SAMPLE	NO.
!		
	MHX982	

b Name: SKINNER & SHERMAN LABS. Contract: 68-D0-0109 :

b Code: SKINER Case No.: 18254 SAS No.: SDG No.: MHX979

trix (soil/water): WATER

Lab Sample ID: 06109-04S

Date Received: 06/10/92

vel (low/med): LOW

Solids:

0.0

CAS No.	: Analyte	Concentration C	Q	_ m	
7429-90-5	Aluminum	21.00 U		P	_
7440-36-0	Antimony	11.00¦U¦	<u>N</u>	<u> </u>	<u> R</u>
7440-38-2	Arsenic	5.80 B	N*	<u> </u>	<u>X</u> R
7440-39-3	Barium	109.00 B	_N	<u> </u>	<u>R</u>
7440-41-7	Beryllium			{P {	
7440-43-9	Cadmium	1.00¦B;		IP	<u>UU</u>
17440-70-2	Calcium	45300.00;		IP :	
17440-47-3		5.00 U	N*	IP !	DU R
17440-48-4	Cobalt	2.00;0;		P	
7440-50-8	Copper	6.40 B		IP :	77
17439-89-6	Iron	447.00	*	IP!	J
17439-92-1	Lead	1.90¦U¦	WN	IF !	R
17439-95-4	Magnesium	11700 001 1		{P {	
17439-96-5	:Manganese			IP 1	u
17439-97-6	Mercury	0.20¦U¦	*	CVI	N)
17440-02-0	Nickel	5.00¦U¦		iP i	
17440-02-0	Potassium	'		IP :	
7782-49-2	*	4.00:01	WN	JF I	R
17440-22-4	Silver	3.00{U		P	
17440-23-5	Sodium	39500.00		P	
17440-28-0	:Thallium_	5.00:01	W	IF !	<u> </u>
• • •	Vanadium	7.60¦B;		1P 1	R.
17440-62-2	Zinc	207.001		¦P ¦	
17440-66-6	Cyanide	10.00:0		CAL	01
	1 Chailine	!		! !	
, i		· · ·			

					· · · · · · · · · · · · · · · · · · ·	
mer	nts:	•				
or	After:	COLORLESS	Clarity	After:	CLEAR	Al Lilderi.
			• .	A & B	CLEAR	Artifacts:
on	Before:	COLORLESS	Clarity	Before:	CLEAR	Texture:

Appendix H.
Utah State Health Laboratory
Analytical Results

Cost Code:

EPA METHOD 625 (GC/MS)

set # # 003827

Base Neutral/Acid Extractables

Send Report To: DEQ-DERK

Attn: Jason Knowlton
1950 W. W. Temple
5.L.C. UT 84116

Utah State Dept of Health 44 Medical Drive Salt Lake City, UT 84113

Field # EC-SC-O/ Date/Tim	ne Collected 6/3	192 1420 Sample Matrix O, 1 Ite Essex Copper Norm Storage Rec 6/10/92	
Exact Description of Sampl	ing Point W. /	Orum Storage Res Colleges	
=======================================		Ext: 6/16/92	
Analyst (\cdot\cdot\cdot\cdot\cdot\cdot\cdot\cdot	ce Rec'd	Date Analyzed 7/20/90	= = =
Aliquot Sample Extracted _	0,59	Final Extract Volume 10m0	
(MDI based on 1 I common	\mathcal{Q}	Great de la la	
(MDL based on 1 L. extract	ed, I mi final		•
	in ug/L ug/k MDL/Results	in ug/L u	== 7
X Name	MDL/Results 4	Name MDL/Resul	13/4
Acenaphthene	$\rightarrow \bullet \cup A G (G X X X X X X X X X X X X X X X X X $	Naphthalene 1.0 47	$\overline{\overline{\infty}}$
Acenaphthylene	2.0	2-Nitroaniline 16.U	匸
Anthracene	3.U	3-Nitroaniline 16.U 4-Nitroaniline 31.U	
Aniline	4.0	Nitrobenzene 3.U	+
	32.0	2-Nitrophenol 4.U	\top
Benzo(a)anthracene Benzo(b)fluoranthene	7.0	4-Nitrophenol 18.U	
Benzo(k)fluoranthene	4.0	n-Nitrosodimethylamine 8.U n-Nitrosodiphenylamine 4.U	₩.
	1.0	n-Nitrosodiphenylamine 4.U n-Nitrosodinpropylamine 6.U	+
Benzo(ghi)perylene l	3.0	Pentachlorophenol 29.0	+-
Benzylbutylphthalate	7.0	Phenanthrene 1.0	4
	17.0 V	Phenol -3.0 Z	76,8
Bis(2-chloroethyl)ether		Pyrene 4.U x 1,2,4-Trichlorobenzene 2.U	(200
Bis(2-chloroethoxy)metha	ne 3.0	2,4,6-Trichlorophenol 4.U	+
Bis(2-chloroisopropyl)et	her 3.U	2,4,6-Trichlorophenol 4.U	7
Bis (2-emyl Hexyl) Phthelate	10. y		
4-Bromophenyl phenyl eth 4-Chloraniline	ner 6.U	TENTATIVELY IDENTIFIED COMPOU	
2-Chloronaphthalene	2.0 \	Name Scan # Resul	LLS
4-Chloro-3-methyl phenol		<u>m.</u>	
2-Chlorophenol	2.0 x 700	00	
4-Chlorophenyl phenyl et Chyrsene		UTAH DEPARTMENT OF	
Dibenz(a,h)anthracene	3.0	ENVIRONMENTAL QUALITY	
Dibenzoturan	2.0		
Di-n-butyl phthalate	5.0	AUG 1 2 1992	
1,3-Dichlorobenzene (met		A00 1 2 1002	
1,2-Dichlorobenzene (ort 1,4-Dichlorobenzene (par	(ho) 5.0		
3,3-Dichlorobenzidene	24.0	DIV. OF ENVIRONMENTAL	
2,4-Dichlorophenol	4.0	RESPONSE AND REMEDIATION	
2,4-Dimethylphenol	6.0	•	
Diethyl phthalate 2,4-Dinitrophenol	4.0	700	
Dimethyl phthalate	3.U x 2000	<u> </u>	
2,4-Dinitrotoluene	14.0		—
2,6-Dinitrotoluene	10.0		
Di-n-octyl phthalate 1,2-Diphenylhydrazine	8.0		
Fluoranthene	3.0	CHAIN OF CUSTODY	
Fluorene	2:0		
Hexachlorobenzene	6.0		
Hexachlorobutadiene	4.0		
Hexachloroethane Hexachlorocyclopentadien	2.U ne 21.U	U - Analyzed for but not	
Ideno(1,2,3-c,d)pyrene	16.0	detected. J - An estimated value for a	=
Isophorone	3.0	tentatively identified cmpd	ŌR
2-Methyl-4,6-dinitropher	101 24.U V	a value less than the detec-	_
2-Methyl naphthalene 2-Methyl phenol (o-creso	3-8- 160 OC	tion limit but greater than	
3-Methyl phenol (m-creso	1) 10.U 1540	<u>∞.</u> (Ozero.	
4-Methyl phenol (p-creso		∞ . B - Found in the blank.	
	7,27,00	*** ~	

Cost Code:	EPA METHOD	624 (GC/MS)	Laby 🕈	MSZ003827
	Purgeab	108		
send Report To: DEQ-	DERK	Uta	h State De	pt of Health
$\Delta \gamma \gamma$	Lasan Know ! IU!	44 1	Medical Dr	ive
1950 W	N. Temple UT 84116	Sal	t Lake Cit	y, UT 84113
5.6.6.	77 8776	1/1/02 1421)	Sample Ma	trix Oil
Field # EC-SC-OI Date Collected By Jason Ka Exact Description of S	/Time Collected	Bite Escex (poact	
Collected By Jason Kn	ampling Point w	. Drum Storag	d'	
	Date Recid 6/16	do Data an	alyzed	1/21/92
Analyst McMAmt. Purged .020	Date Rec a - TV	Durge vol.)	Dilution	150
Amt. Purged .02 a (F	Mr Dased on ami			
ug/L or(v	ig/Kg		`•	
X Name	MDL/RESULTS			
Acetone	10.0			
Acrolein Acrylonitrile	10.0			
HANZANA	1.0			
Bromodichloromethal	ne 1.0 1.0			•
Bromotorm Bromomethane	- 2 :0			
Z-Butanone (MEK)	4.0			
Carbon Disulfide	2.0			
Carbon Tetrachiori	de 1.U			
Chlorobenzene Chloroethane	2:0		_	
2-Chloroethylvinyl		5.U X 250	<u> </u>	
Chloroform		5.0		
Chloromethane		2.0		
Cyclohexane Dibromochlorometha	ne	1.0		
7-Dichlorobenzen	e (ortho)	1.0		
- 1 3-Dichlorobenzen	е (шеса)	1.0		
1 4-D) chlorobenzen	e (para)	1.0	— U - Ana	lyzed for but
1.1-Dichloroethane		1.0	_ not	detected.
- Dichloroethene		1.0	<u></u>	estimated .
frans-1.2-Dichioro	etnene	3.0	value f	or a tentativ-
1,2-Dichloropropan cis-1,3-Dichloropr	Opene	1.0	- elv ide	ntified cmpd
trans-1,3-Dichloro	propene	1.0	OR a va	lue less than ection limit
Tehul Benzene	<u></u>	1.U 3.U	but are	ater than zero
2-Hexanone (Methy)		5.0	_	
Methylene Chloride 4-Methyl-2-Pentano	Dichloromethar	ie) 1.U	B - Fou	nd in the
4-Methyl-2-Pentano	one (MIBK)	2.0	L bla	nk.
Cturana		1.0	 	
1,1,2,2-Tetrachlor Tetrachloroethene	Oethane	1.0		
Toluene		1.0		
- 1 1-Trichloroet	nane (Methyl Chlo	roform) 1.U	+	
- 7 7 7 Trichloroet	nane	1.0	+-	
Trichloroethene (thane (Freen II)	2.0	<u> </u>	
Vinyl Acetate		4.0	•	
Vinvi Chloride		2.0	√k' .	
Total Xylenes				
Tentatively Identifi	ed Compounds			
Name Sc	an # Results			
			_	
			OHAIN O	C OHOTODY
			CHAIN O	F CUSTODY
				
			-t'.	2001
Preparation and Anal	ysis By:		. تال	Date 2/2/
			17.	Date
T hoisimum	lar •		, C	

	EPA METHODS <u>608</u>	8140 8150	
	For Gas Chro		Jun 1892003627
			B NO.
608-PCB'S and Organochl	orine Pesticides	210	
8140-Organophosphorous	Pesticides	ኖ ሞአሞክ በክ	UTAH, DEPT OF HEALTH
	EASE PRINT)		OF LABORATORY SERVICES
Send Report To Name or Agency: <u>OEQ-</u>	AFOR ALL Trees	V 16 North	MEDICAL DRIVE
Name or Agency: UE/1-	DEKK ATM. JEGI.	And Ton 40 North	e City,Utah 84113
Address: 1950 W. A	1. Jemple 84116	Saic Eak (801)584	-
City, State, Zip: 5./.	·	(801)304	COST CODE
Phone Number: 536 - 4	1100	CAMPLE	MATRIX Oil
SAMPLE USED FOR: Site	Investigation	SAMPLE	-lock) /470
Field # <u>EC-SG-OI</u> Date (Collected 6/3/92	Time Collected(24nr.	Property Plant
Collected By Jason Know	<u>/fon</u> Sampling Site	Essex Copper	D 12
Exact Description of Sam	pling Point W. Ucu	im Storage Are	20 - Drum #13
=======================================			Analyzed 6/19/92
Analyst J. Oman	Date Re	c'dDate	Analyzed Girlia
Aliquot Sampla Extracted	O. Na Final Vol	ume Extract	-
(MDL based on 1 L extrac	tion and 10 ml final	Volume)	
=======================================	=======================================	=======================================	
XAnalyze for Method 60	8 Analytes (PCB only,		or Method 8140 Analytes
Analyze for Method 81	50 Analytes	Analyze fo	or PCB'S Only
Analyze only those An	alytes Indicated(X)		
608 in ug/		8.	140 in ug/L
X Name	MDL/RESULTS	X Name	MDL/RESULTS
Aldrin	0.004U	<u>Ethyl Parathio</u>	
alpha-BHC	0.003U	Diazinon	
beta-BHC	0.00U	<u> Malathion</u>	nd
delta-BHC	0.009U		
gamma-BHC (Lindane)	0.000		
Chlordane	0.014U		
4,4'-DDD	0.011U		
4,4'-DDE	0.004U		
4,4'-DDT	0.012U	<u>8</u>	<u>150 in ug/L</u>
Dieldrin	0.002U	X Name	MDL/RESULTS
Endosulfan I	0.014U	2,4-D (2,4Dich	lorophenoxyacetic acid)
Endosulfan II	0.004U		1.00
Endosulfan Sulfate	0.066U	2,4,5-TP (SILV	EX) 0.1U
Endrin	0.006U		
Endrin Aldehyde	0.023U		
Endrin Keytone	nd		
Heptachlor	0.003U		
Heptachlor Epoxide	0.083U		
	0.24U		
Toxaphene	V I II I		
EUS DUBIG	in-ug/I- PPM		•
	MDL/RESULTS	U - Analyzed	for but not detected
X Name	nd	J - A value l	ess than the detection
Aroclor 1016			greater than zero

Aroclor 1221 nd Aroclor 1232 0.065U Aroclor 1242 nd Aroclor 1248

Aroclor 1254

Aroclor 1260

nd

nd

B - Found in the blank

nd - Not Determined

	17	Date 6/24
Analysis Certified By	2 14 15 16	17 18 10 20 71 -22 -23 -24 -25 -26 -27 -28
LAB USE ONLY: 1-2-3-4-5-6-7-8-9-10-11-12-1	3-14-15-10	47 40 40 50-51-52-53-54-55-56-57
29-30-31-32-33-34-35-36-37-38-39-40-41-42-	43-44-45-40	-4/-40-49-50-51-52-55-55-6

BOTTLES REQUIRED: FOR 608-8140-8150: (1) one gallon glass AMBER bottle FOR PCB'S: Water:same as above/ SOIL: (1) 4 oz GLASS BOTTLE/

OIL: (1) 1.5 DRAM GLASS VIAL(VERY SMALL) ALL LIDS MUST BE LINED WITH TEFLON

EPA METHODS 608, 8140, 8150 For Gas Chromatography

608-PCB'S and Organo	chlorine Pesticides	LAB NO	•
8140-Organophosphoro			1092003628
	PLEASE PRINT)		H, DEPT OF HEALTH
Send Report To		DIVISION OF	LABORATORY SERVICES
Name or Agency: OFQ	-DERR Attn. Jason	Knowlton 46 North MED	
Address: 1950 W. A	I. Temple	Salt Lake Ci	ty,Utah 84113
City.State.Zip: 5.4	.C. UT 84116	(801)584-840	_
Phone Number: 536	-4100		COST CODE
	e Investigation	SAMPLE MAT	RIX_0;/
		Time Collected(24hr.cloc	k) 1520
Collected By Jason Kn	ewiten Sampling Sit	e Essex Copper	
Exact Description of Sa	ampling Point E. To	ansformer Area	
_			
		=======================================	
Analyst . Omar		Rec'd Date Anal	yzed 6/19/92
Aliquot Sample Extracte	ed O.M. Final Vo	olume Extract 10 ml	, ,
(MDL based on 1 L extra		l Volume)	
=======================================		=======================================	=======================================
Analyze for Method		Analyze for Me	thod 8140 Analytes
Analyze for Method		Analyze for PC	B'S Only
	Analytes Indicated(X)		
<u>608 in u</u>	•		n ug/L
X Name	MDL/RESULTS	X Name	MDL/RESULTS
Aldrin	0.004U	Ethyl Parathion	nd
alpha-BHC	0.003U	Diazinon	0.6U
beta-BHC	0.00U	<u> Malathion</u>	nd
delta-BHC	0.009U		
gamma-BHC (Lindane)	0.000		
Chlordane	0.014U		
4,4'-DDD	0.0110		
4,4'-DDE	0.004U	9150 :	/T
4,4'-DDT	0.012U		n ug/L
<u>Dieldrin</u>	0.002U	X Name	MDL/RESULTS
Endosulfan I	0.014U	2,4-D (2,4Dichlorop	1.0U
Endosulfan II	0.004U 0.066U	2,4,5-TP (SILVEX)	0.10
Endosulfan Sulfate	0.006U	2,4,5-IF (SILVEX)	0,10
Endrin Nidohada	0.0000 0.023U		
Endrin Aldehyde Endrin Keytone	nd		
Heptachlor	0.003U		
Heptachlor Epoxide	0.083U		
Toxaphene	0.24U		
TOXADMENE	V.240		
608 PCB'	S in ug/L - ppm		-
X Name	MDL/RESULTS	U - Analyzed for b	ut not detected
Aroclor 1016	nd	J - A value less t	
Aroclor 1221	nd /	limit but grea	ter than zero
Aroclor 1232	nd None	detected B - Found in the b	lank
Aroclor 1242	0.065U	nd - Not Determined	
Aroclor 1248	nd <11 px	2W	
Aroclor 1254	nd		
Aroclor 1260	nd)	CHA	IN OF CUSTODY
Analysis Certified By_			9
LAB USE ONLY: 1-2-3-4-	5-6-7-8-9-10-11-12-13	-14-15-16-17-18-19-20-21-2	2-23-24-25-26-27-28
29-30-31-32-33-34-35-3	6-37-38-39-40-41-42-43	3-44-45-46-47-48-49-50-51-	52-53-54-55-56-57
BOTTLES REQUIRED: FO	R 608-8140-8150: (1)	one gallon glass AMBER bot	tie
FOR PCB'S: Water:sa	me as above/ SOIL: (1) 4 oz GLASS BOTTLE/	
OIL: (1) 1.5 DRAM G	LASS VIAL(VERY SMALL)	ALL LIDS MUST BE LINED W	IIH IRKUM

ا بدارا	n	91	0	03	6	2	C
	,		_		_		

coo papia l	To our the	LAB NO.	
608-PCB'S and Organo		2.1.5 1.01	
8140-Organophosphoro	us Pesticides	STATE OF HTAH.	DEPT OF HEALTH
8150-Pesticides (PLEASE PRINT)		BORATORY SERVICES
Send Report To	MEAD AN T V.		
Name or Agency:	- MERR, Atta: Jason Knowl	Salt Lake City	
Address: /930 W. N.	Temple .C. UT 84116	Sait Lake City (801)584-8400	,ocan ouis
City, State, Zip:			OST CODE
Phone Number: 536-	4100	SAMPLE MATRI	
SAMPLE USED FOR: 3/7	te Investigation	SAMPLE MAIKI	1500
Field # EC-SC-O3 Dat	e Collected 63/42	Time Collected(24hr.clock)	<u> </u>
Collected By Vason Kno	Witton Sampling Site	Essex Copper	
Exact Description of S	Sampling Point W. / Tans	Former Area	
			.======================================
			ed 6/19/92
Analyst	Date Reced_O.10ay Final Vol	ume Extract 10mg	
Aliquot Sample Extract	action and 10 ml final	Volume)	
	action and io mi linar	_=====================================	
	soo > 1 har (NCA Cal)	Analyze for Meth	od 8140 Analytes
Analyze for Method	608 Analytes (PCB Only	Analyze for PCB	
Analyze for Method	8150 Analytes	Analyze for FCB	5 Only
Analyze only those		8140 in	ng/I
<u>608 in t</u>			MDL/RESULTS
X Name	MDL/RESULTS	X Name	
Aldrin	0.004U	Ethyl Parathion	0.6U
alpha-BHC	0.003U		
beta-BHC	0.000	Malathion	nd
delta-BHC	0.0090		
gamma-BHC (Lindane)	0.00U		
Chlordane	0.014U		
4,4'-DDD	0.011U		
4,4'-DDE	0.004U		
4,4'-DDT	0.012U	<u>8150 in</u>	_
Dieldrin	0.002U	X Name	MDL/RESULTS
Endosulfan I	0.014U	2,4-D (2,4Dichlorophe	
Endosulfan II	0.004U		1.00
Endosulfan Sulfate	0.066U	2,4,5-TP (SILVEX)	0.10
Endrin	0.006U		
Endrin Aldehyde	0.023U		
Endrin Keytone	nd		
Heptachlor	0.003U		
Heptachlor Epoxide	0.083U		
Toxaphene	0.24U		
608 PCB	's in wort PPm 1.0.		•
X Name	MDL/RESULTS	U - Analyzed for bu	t not detected
Aroclor 1016	nd	J - A value less th	an the detection
Aroclor 1221	nd	limit but great	
Aroclor 1232		B - Found in the bl	ank
Aroclor 1242		nd - Not Determined	
Aroclor 1248		OL.	MIN OF OUGTOR
Aroclor 1254		UF.	IAIN OF CUSTODY
Aroclor 1260	- 10 40		
lumination Combission De	•	$\frac{7}{14.15.16.17.18.10.20-21-22}$	<u>Y</u>
" ONT N. 1 2 2 A	5.6.7.X.Q.10-11-12-13-	14-13-10-1/-10-13-40-21-42	- 20 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2
LAB USE UNLI: 1-2-3-4	36_37_38_39_40_41_42_43	_44_45_46_47_48_49_50_51_5	2-53-54-55-56-57
29-30-31-32-33-34-35-	OP 608_8140_8150: (1) o	ne gallon glass AMBER bott	le
BOLLINES KEGOIKEN: E	same as above/ SOIL: (1)	4 oz GLASS BOTTLE/	
KOK KCR.2: Macer:	OUNG GD COAC, DOTTO (T)		THE PERION

OIL: (1) 1.5 DRAM GLASS VIAL(VERY SMALL) ALL LIDS MUST BE LINED-WITH TEFLON

CHAIN OF CUSTODY

Appendix I.

Dow Chemical

Material Safety Data Sheets



Dow U.S.A.

Material Safety Data Sheet

The Dow Chemical Company Midland Michigan 48674 Emergency 517 636-4400

Product Code: 23586 Page: 1

Product Name: DOWFROTH (R) 250 FLOTATION FROTHER

Effective Date: 06/19/90 Date Printed: 12/23/92 MSDS:002010

1. INGREDIENTS: (% w/w, unless otherwise noted)

Polypropylene glycol methyl ether CAS# 037286-64-9 98%

This document is prepared pursuant to the OSHA Hazard Communication Standard (29 CFR 1910.1200). In addition, other substances not 'Hazardous' per this OSHA Standard may be listed. Where proprietary ingredient shows, the identity may be made available as provided in this standard.

2. PHYSICAL DATA:

BOILING POINT: 473F, 245C VAP PRESS: <0.01 mmHg @ 20C

VAP DENSITY: Low

SOL. IN WATER: Completely miscible.

SP. GRAVITY: 0.98 25/25 APPEARANCE: Amber liquid.

ODOR: Not available.

3. FIRE AND EXPLOSION HAZARD DATA:

FLASH POINT: 300F, 149C METHOD USED: Setaflash

FLAMMABLE LIMITS LFL: Not determ. UFL: Not determ.

EXTINGUISHING MEDIA: Water fog, alcohol resistant foam, CO2, dry chemical.

FIRE & EXPLOSION HAZARDS: No data available.

FIRE-FIGHTING EQUIPMENT: Wear positive pressure self-contained

(Continued on page 2)

(R) Indicates a Trademark of The Dow Chemical Company

Product Code: 23586 Page: 2

Product Name: DOWFROTH (R) 250 FLOTATION FROTHER

Effective Date: 06/19/90 Date Printed: 12/23/92 MSDS:002010

3. FIRE AND EXPLOSION HAZARD DATA: (CONTINUED)

breathing apparatus.

4. REACTIVITY DATA:

STABILITY: (CONDITIONS TO AVOID) Will not decompose under ordinary conditions of use and storage.

INCOMPATIBILITY: (SPECIFIC MATERIALS TO AVOID) Oxidizing material.

HAZARDOUS DECOMPOSITION PRODUCTS: On burning, carbon monoxide and carbon dioxide are expected.

HAZARDOUS POLYMERIZATION: Will not occur.

5. ENVIRONMENTAL AND DISPOSAL INFORMATION:

ACTION TO TAKE FOR SPILLS/LEAKS: (Use appropriate safety equipment): Contain, do not allow to contaminate ground water. Absorb if possible.

DISPOSAL METHOD: Dispose in accordance with all federal, state and local regulations. Incineration is preferred.

6. HEALTH HAZARD DATA:

EYE: May cause moderate eye irritation. May cause moderate corneal injury.

SKIN CONTACT: Prolonged or repeated exposure not likely to cause significant skin irritation.

(Continued on page 3)
(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

Product Code: 23586 Page: 3

Product Name: DOWFROTH (R) 250 FLOTATION FROTHER

Effective Date: 06/19/90 Date Printed: 12/23/92 MSDS:002010

6. HEALTH HAZARD DATA: (CONTINUED)

SKIN ABSORPTION: A single prolonged exposure is not likely to result in the material being absorbed through skin in harmful amounts. The dermal LD50 has not been determined. Repeated exposure to large amounts of some components in this mixture may cause narcotic effects (drowsiness).

INGESTION: Single dose oral toxicity is low. The oral LD50 for female rats is between 1260 and 2520 mg/kg. Amounts ingested incidental to industrial handling are not likely to cause injury; however ingestion of larger amounts may cause injury. Observations in animals include tremors and convulsions.

INHALATION: Excessive exposure may cause irritation of the eyes, upper respiratory tract, and lungs. Signs and symptoms of excessive exposure may be anesthetic or narcotic effects.

SYSTEMIC & OTHER EFFECTS: Signs and symptoms of excessive exposure may be anesthetic or narcotic effects. Repeated excessive exposures may cause liver and possibly kidney effects. Birth defects are unlikely from the tripropylene glycol methyl ether component. Exposures having no adverse effects on the the mother should have no effect on the fetus. Results of in vitro mutagenicity studies on tripropylene glycol methyl ether have been negative.

7. FIRST AID:

EYES: Irrigate with flowing water immediately and continuously for 15 minutes. Consult medical personnel.

SKIN: Wash off in flowing water or shower.

INGESTION: Induce vomiting if large amounts are ingested.

Consult medical personnel.

(Continued on page 4)

(R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

Product Code: 23586 Page: 4

Product Name: DOWFROTH (R) 250 FLOTATION FROTHER

Effective Date: 06/19/90 Date Printed: 12/23/92 MSDS:002010

7. FIRST AID: (CONTINUED)

INHALATION: Remove to fresh air. If not breathing, give mouthto-mouth resuscitation. If breathing is difficult, give oxygen. Call a physician.

NOTE TO PHYSICIAN: No specific antidote. Supportive care. Treatment based on judgment of the physician in response to reactions of the patient. Repeated excessive exposure may aggravate preexisting liver and kidney disease.

8. HANDLING PRECAUTIONS:

EXPOSURE GUIDELINE(S): None established.

VENTILATION: Good general ventilation should be sufficient for most conditions.

RESPIRATORY PROTECTION: When respiratory protection is required for certain operations, use an approved air-purifying respirator.

SKIN PROTECTION: No precautions other than clean body-covering clothing should be needed.

EYE PROTECTION: Use chemical goggles.

9. ADDITIONAL INFORMATION:

SPECIAL PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE:
Practice reasonable care and caution to avoid eye and skin contact.

MSDS STATUS: Revised section 9 and regsheet.

For information regarding state/provincial and federal regulations see (R) Indicates a Trademark of The Dow Chemical Company

* An Operating Unit of The Dow Chemical Company

Product Code: 23586 Page: R-1

Product Name: DOWFROTH (R) 250 FLOTATION FROTHER

Effective Date: 06/19/90 Date Printed: 12/23/92 MSDS:002010

REGULATORY INFORMATION: (Not meant to be all-inclusive—selected regulations represented.)

NOTICE: The information herein is presented in good faith and believed to be accurate as the effective date shown above. However, no warranty, express or implied, is given. Regulatory requirements are subject to change and may differ from one location to another; it is the buyer's responsibility to ensure that its activities comply with federal, state or provincial, and local laws. The following specific information is made for the purpose of complying with numberous federal, state or provincial, and local laws and regulations. See MSD Sheet for health and safety information.

U.S. REGULATIONS

SARA HAZARD CATEGORY: This product has been reviewed according to the EPA "Hazard Categories" promulgated under Sections 311 and 312 of the Superfund Amendment and Reauthorization Act of 1986 (SARA Title III) and is considered, under applicable definitions, to meet the following categories:

An immediate health hazard

CANADIAN REGULATOINS

The Workplace Hazardous Materials Information System (W.H.M.I.S.) Classification for this product is:

D2B

The Transportation of Dangerous Goods Act (T.D.G.A.) classification for this product is:

(Continued on page R-2)

- (R) Indicates a Trademark of The Dow Chemical Company
- * An Operating Unit of The Dow Chemical Company

Product Code: 23586 Page: R-2

Product Name: DOWFROTH (R) 250 FLOTATION FROTHER

Effective Date: 06/19/90 Date Printed: 12/23/92 MSDS:002010

REGULATORY INFORMATION (CONTINUED)

Not regulated

⁽R) Indicates a Trademark of The Dow Chemical Company
The Information Herein Is Given In Good Faith, But No Warranty,
Express Or Implied, Is Made. Consult The Dow Chemical Company
For Further Information.

^{*} An Operating Unit of The Dow Chemical Company

Appendix J.
American Cyanamid
Material Safety Data Sheets



801 359 8853;# 7



MATERIAL SAFETY DATA

MSDS NO. 0617-04 DATE: 08/14/89

PRODUCT
IDENTIFICATION

PRODUCT NAME:	AEROFLOAT® 25 Promoter	
SYNONYMS:	None	
CHEMICAL FAMILY:	Aryl dithiophosphoric acid	
MOLECULAR FORMULA:	Mbdure	
MOLECULAR WGT.:	Mixture	-

WARNING

DANGERI CAUSES BURNS OF EYES AND SKIN HARMFUL IF ABSORBED THROUGH SKIN OR SWALLOWED

OSHA
REGULATED
COMPONENTS

COMPONENT	CAS. NO.	%	TWA/CEILING	REFERENCE		
Cresylic acid (cresol)	001319-77-3	15	5 ppm (skin)	OSHA/ACGIH		
(cresol)						

NFPA HAZARD RATING

FIRE: Material that must be preheated Fire 1 Reactivity

Special

before ignition can occur. HEALTH: Materials which on short exposure could cause serious temporary or residual injury even though prompt medical treatment were given.
REACTIVITY: Materials which in themselves are normally

stable, but which can become unstable at elevated temperatures and pressures or which may react with water with some release of energy

but not violently.

HEALTH HAZARD **EFFECTS OF** INFORMATION OVEREXPOSURE:

The acute oral (rat) and the acute dermal (rabbit) LD50 values are 250 mg/kg and between 200 mg/kg and 1000 mg/kg, respectively. Direct contact with this material may cause severe eye and skin irritation.

Contact with water may cause liberation of hydrogen sulfide. Hydrogen sulfide has a strong rotten-egg odor, however, some people are unable to smell the gas and exposure will deaden the sense of smell. Therefore odor is an unreliable indicator of exposure. Overexposure to hydrogen sulfide gas may cause severe eye or respiratory tract irritation, rapid development of coma and respiratory failure. Low levels of hydrogen sulfide may cause headache, dizziness, staggering galt, neurological damage and

Toxicology information on regulated components of this product is as follows:

The acute oral (rat) and acute dermal (rabbit) LD50 values for cresol are 1454 mg/kg and 2000 mg/kg, respectively. Cresol is corrosive to all tissues; therefore, the liquid may cause severe eye or skin initation. Prolonged or repeated dermal contact to low concentrations of cresol may produce a skin rash. Ingestion or skin absorption may cause headache, dizziness, blurred vision, ringing of ears, rapid breathing, mental confusion, muscular weakness, loss of consciousness and liver and kidney

EMERGENCY PHONE: 201/835-3100

MSDS NO. 0617-04

PAGE Z UP 4

AEROFLOAT® 25 Promoter

damage. Prolonged or repeated contact by any route may produce the following signs: vomiting, difficulty in swallowing, salivation, diarrhea, loss of appetite, headache, faintness, dizziness, mental disturbances, skin rash and liver and iddney damage.

FIRST AID:

In case of skin contact, remove contaminated clothing without delay. Wear impervious gloves. Cleanse skin thoroughly with soap and water. Do not omit cleaning hair or under fingernalis if contaminated. Do not reuse clothing without laundering. Do not reuse contaminated leatherware.

In case of eye contact, immediately irrigate with plenty of water for 15 minutes. Obtain medical attention without delay.

EXPOSURE CONTROL METHODS

Utilize a closed system process where feasible. Where this material is not used in a closed system, good enclosure and local exhaust ventilation should be provided to control exposure. Food, beverages, and tobacco products should not be carried, stored, or consumed where this material is in use. Before eating, drinking, or smoking, waish face and hands with soap and water. Prevent eye and akin contact. Wear the special protective equipment specified below for operations where eye or skin contact can occur. Prevent contamination of skin or clothing when removing protective equipment. Provide eyewash fountain and safety shower in close proximity to points of potential exposure. Where exposures are below the PEL, no respiratory protection is required. Where exposures exceed the PEL, use respirator approved by NIOSH or full protective suit with air supply appropriate for the material and level of exposure. See "GUIDE TO INDUSTRIAL RESPIRATORY PROTECTION" (NIOSH). Special protective equipment - To prevent skin contact wear skin protection, such as impervious gloves, apron, workpants, long sleeve workshirt, or disposable coveralls. To prevent eye contact wear eye protection such as chemical splash proof goggles or face shield.

FIRE AND EXPLOSION HAZARD INFORMATION FLASH POINT: >200 F (>93.3 C)
METHOD: Setaflash Closed Cup

FLAMMABLE LIMITS
(% BY VOL): Not Available

AUTOIGNITION TEMP: Not Available

DECOMPOSITION TEMP: Not Available

FIRE FIGHTING:

Use carbon dioxide or dry chemical to extinguish fires. Contact with water liberates toxic and flammable hydrogen sulfide gas. Wear self-contained, positive pressure breathing apparatus and full firefighting protective clothing. See Exposure Control Methods for special protective clothing. Use water to keep cool containers but avoid letting it contact this product. Do not flush to sewers. Sulfur oxides and/or toxic and flammable hydrogen sulfide may be formed under fire conditions.

REACTIVITY DATA

STABILITY: Stable CONDITIONS TO AVOID: Avoid contact with water, acids, and excessive heat (175 F, 79.4 C).

CONDITIONS TO AVOID: Avoid contact with water, acids, and excessive near (1737, 75.4 C

POLYMERIZATION: Will Not Occur CONDITIONS TO AVOID: None known

INCOMPATIBLE MATERIALS:

Contact with water or water solutions liberates toxic and fiammable hydrogen sulfide. Strong acids and/or oxidizing agents may react violently.

MSDS NO. 0617-04 PAGE 3 OF 4

A	FRC)F1	STAC	25 1	Promoter
			4 7		

AEROFLOAIS 25 I	LIGHTORE	
•	HAZARDOUS DECOMPOSITION PRODUCTS:	Thermal decomposition or combustion may produce carbon monoxide, carbon dioxide, sulfur oxides and/or hydrogen sulfide.
PHYSICAL PROPERTIES	APPEARANCE AND ODOR:	Dark amber to black liquid with tarry cresole odor
	BOILING POINT:	Not Available
	MELTING POINT:	Not Available
	VAPOR PRESSURE:	Negligible
	SPECIFIC GRAVITY:	1.19
	VAPOR DENSITY:	Not Available
	% VOLATILE (BY VOI	L): <1
	OCTANOL/H2O PARTITION COEF.:	Not Available
	pH:	Not Applicable
	SATURATION IN AIR (BY VOL):	Not Available
	EVAPORATION RATE	: Negligible
	SOLUBILITY IN WAT	ER: Slight soluble
		addition to the protective dothing/equipment in Exposure Control Methods, wear impervious boots. Cover spills with some inert absorbent material; sweep up and place in a waste disposal container. Flush area with water.
WASTE DISPOSAL	Disposal must be made regulations.	in accordance with applicable governmental
SPECIAL PRECAUTIONS	HANDLING AND STORAGE/OTHER:	This product contains a dithloacid. Contact with water liberates toxic and flammable hydrogen sulfide gas. Do not mix with water or aqueous solutions of any other reagents since evolution of poisonous hydrogen sulfide gas could result. This precaution does not apply to addition to flotation pulps in amounts normally used in flotation. Store in a dry place out of sun and away from heat.
D.O.T. SHIPPING INFORMATION	PROPER SHIPPING NAME:	CORROSIVE LIQUID, N.O.S.
	HAZARD CLASS:	CORROSIVE MATERIAL
	UN/NA:	UN1760
	D.O.T. HAZARDOUS SUBSTANCES:	(Reportable Quantity of Product) CRESOL (6,666 lbs-15%)

D.O.T. LABEL REQUIRED: Corrosive

MSDS NO. 0617-04

PAGE 4 OF 4

AEROFLOAT® 25 Promoter

TSCA INFORMATION This product is manufactured in compliance with all provisions of the

Toxic Substances Control Act, 15 U.S.C.

ENVIRONMENTAL INFORMATION

The following components are defined as toxic chemicals subject to reporting requirements of Section 313 of Title III and of 40 CFR 372 or subject to other EPA regulations.

SARA TITLE III

COMPONENT	CAS. NO.	%	TPQ (lbs.)	RQ (lbs.) 5313	RCRA	TSCA 12B	
Cresylic acid (cresol)	001319-77-3	15	NONE	1000	YES	U052	NO	_

PRODUCT CLASSIFICATION UNDER SECTION 311 OF SARA

ACUTE (Y) CHRONIC (N) FIRE (N) REACTIVE (Y) PRESSURE (N)

Marvin A. Friedman, Ph.D., Director of Toxicology and Product Safety

88012953073 P. 02

05/23/1990 08:31 FROM AMER. CYANAMID CHEMICALS TO



MATERIAL SAFETY DATA



PACE 1 OF 3

REFERENCE

MSDS NO. 0299-02

PRODUCT
IDENTIFICATION

PRODUCT NAME:	AERO® 412 Promoter, Aqueous	
SYNONYMS:	None	•
CHEMICAL FAMILY:	Dithiophosphate	
MOLECULAR FORMULA:	(C5H11O)2P(S)S.Na	
MOLECULAR WCT.:	292	1

%

WARNING

DANGER CAUSES BURNS OF EYES AND SKIN

CAS. NO.

OSHA REGULATED COMPONENTS

No Permissible
Exposure Limits
(PEL/TLV) have
been established
by OSHA or ACGIH.

COMPONENT

NFPA HAZARD RATING

Fire

Health 2 0 Reactivity

Special

FIRE: Material that must be preheated

before ignition can occur.

HEALTH: Materials which on intense or continued exposure could cause temporary incapacitation or possible

TWA/CEILING

residual injury unless prompt medical treatment is given.

REACTIVITY: Materials which in themselves are normally

stable, even under fire exposure conditions, and which are not reactive with water.

HEALTH HAZARD INFORMATION

EFFECTS OF OVEREXPOSURE:

Liquid may cause severe skin irritation and severe eye irritation. Repeated or prolonged dermal contact also may cause allergic skin reactions. Overexposure to hydrogen sulfide gas may cause severe eye or respiratory tract irritation, rapid development of come and respiratory failure. Low levels of hydrogen sulfide may cause headache, dizziness, staggering gait, neurological damage gastritis. While hydrogen sulfide has a strong rotten-egg odor, some people are unable to smell the gas and hydrogen sulfide deadens the sense of smell.

FIRST AID:

In case of skin contact, remove contaminated clothing without delay. Wear impervious gloves. Cleanse skin thoroughly with soap and water. Do not omit cleaning hair or under fingernails if contaminated. Do not reuse clothing without laundering. Do not reuse contaminated leatherware.

In case of eye contact, immediately irrigate with plenty of water for 15 minutes. Obtain medical attention without delay.

EXPOSURE CONTROL METHODS

Where this material is not used in a closed system, good enclosure and local exhaust ventilation should be provided to control

; 9-11-92 11:30AM ;

U5/23/1990 08:31 FROM AMER. CYANAMID CHEMICALS TO

801 359 8853;#12 68012953073 F.03

AERO® 412 Promoter, Aqueous

MSDS NO. 0299-02

PAGE 2 OF 3

exposure. Food, beverages, and tobacco products should not be carried, stored, or consumed where this material is in use. Before eating, drinking, or smoking, wash face and hands with soap and water. Avoid skin contact. Protective dothing such as impervious gloves, apron, workpants, long sleeve work shirt, or disposable coveralls are recommended to prevent skin contact. For operations where eye or face contact can occur, wear eye protection such as chemical splash proof goggles or face shield. Eyewash equipment and safety shower should be provided in areas of potential exposure. for operations where inhalation exposure can occur, a NIOSH approved respirator recommended by an industrial hygienist may be necessary. A full facepiece respirator also provides eye and face protection.

THE AND		
FIRE AND EXPLOSION HAZARD INFORMATION	FLASH POINT: METHOD:	>200 F (>93.3 C) Setaflash Closed Cup
	FLAMMABLE LIMITS (% BY VOL):	Not Available
	AUTOIGNITION TEMP:	Not Available
	DECOMPOSITION TEMP	Not Available
	FIRE FIGHTING:	Use water spray, carbon dioxide or dry chemical to extinguish fires. Use water to keep containers cool. Wear self-contained, positive pressure breathing apparatus and full fire-lighting protective clothing. See Exposure Control Methods for special protective clothing.
REACTIVITY DATA	STABILITY: CONDITIONS TO AVOID	Stable: None known
	POLYMERIZATION: CONDITIONS TO AVOID	Will Not Occur : None known
	INCOMPATIBLE MATERIALS:	Product reacts with acids to liberate hydrogen sulfide.
	HAZARDOUS DECOMPOSITION PRODUCTS:	Thermal decomposition or combustion (of dried solids) may produce carbon monoxide, carbon dioxide, sulfur oxides and/or hyrogen sulfide.
PHYSICAL PROPERTIES	APPEARANCE AND ODOR	Light straw to amber liquid; no odor
	BOILING POINT:	217 F(103 C)
	MELTING POINT:	48 F; 8.8 C(freezing point)
	VAPOR PRESSURE:	Not Available
	SPECIFIC GRAVITY:	1.156 @ 25 C
	VAPOR DENSITY:	Not Available
	% VOLATILE (BY VOL):	65 (water by weight)
	OCTANOL/H2O PARTITION COEF.:	Not Available
	pH:	11.0 minimum
	SATURATION IN AIR (BY VOL):	Not Available
	EVAPORATION RATE:	Not Available
	SOLUBILITY IN WATER:	Complete

8012953073→

801 359 8853;#13

WOY ZOY I YOU WE: SZ FRUM AMER. CYANAMID CHEMICALS TO

88012953073 P.04

AERO® 412 Promoter, Aqueous

MSDS NO. 0299-02

PAGE 3 OF 3

SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:

Where exposure level is not known, wear NIOSH approved, positive pressure, self-contained respirator. Where exposure level is known, wear NIOSH approved respirator suitable for level of exposure. In addition to the protective clothing/equipment in Exposure Control Methods, wear rain suit. Cover spills with some linert absorbent material; sweep up and place in a waste disposal container. Flush area with water.

WASTE DISPOSAL

Disposal must be made in accordance with applicable governmental regulations.

SPECIAL PRECAUTIONS

HANDLING AND STORAGE/OTHER:

This product should not be mixed with acids since evolution of toxic and explosive hydrogen sulfide gas could result. This precaution does not, of course, apply to addition of this reagent to flotation pulps in amounts customarily used in flotation.

D.O.T. SHIPPING INFORMATION

PROPER SHIPPING
NAME:

HAZARD CLASS:

CORROSIVE
MATERIA

HAZARD CLASS: CORROSIVE MATERIAL
UN/NA: NA1719

D.O.T. HAZARDOUS (Reportable Quantity of Product)
SUBSTANCES: NONE

D.O.T. LABEL REQUIRED: Corrosive

TSCA INFORMATION This product is manufactured in compliance with all provisions of the Toxic Substances Control Act, 15 U.S.C.

ENVIRONMENTAL INFORMATION

The following components are defined as toxic chemicals subject to reporting requirements of Section 313 of Title III and of 40 CFR 372 or subject to other EPA regulations.

SARA TITLE III

COMPONENT

CAS. NO.

%

TPQ (16s.) RQ (16s.) 5313

RCRA


TSCA 128

This product does not contain any components regulated under these sections of the EPA

PRODUCT CLASSIFICATION UNDER SECTION 311 OF SARA

ACUTE (M) CHRONIC (N) FIRE (N) REACTIVE (N) PRESSURE (N)

Marvin A. Friedman, Ph.D., Director of Toxicology and Product Safety



Aqueous AERO° 412 promoter

MC 10

AERO 412 promoter is an aqueous solution of a two component collector based on alkyl dithiophosphate, for use in the flotation of the sulfides of copper, lead, zinc and nickel for metallic copper and for the iron sulfides in acid circuit.

ADVANTAGES

Aqueous solution — improved handling, mixing and feeding characteristics. Although generally fast acting, it is sometimes advantageous to add part or all of the collector to the grinding circuit. Unlike xanthates this product is stable in acid circuit.

APPLICATION

AERO 412 promoter as sold can be fed directly, or can be diluted to any desired strength. For ease of metering it is usually diluted 5 to 10 times. This product has practically no frothing properties.

TYPICAL PROPERTIES

PRINCIPAL USES

Flotation of copper, silver, lead and activated zinc sulfides; as well as metallic copper in alkaline circuits; copper sulfides, metallic copper and iron sulfides in acid circuit, particularly suited in conjunction with amyl xanthate for the flotation of nickel sulfides, such as pentlandite, and nickelferous pyrrhotite, in acid and sodium carbonate circuits. Recommended for slow floating and tarnished sulfides. This product can be used alone or in conjunction with xanthates.

TREATMENT LEVEL

Dosage rates are usually in the range 0.01—0.20 lb. promoter/ton (5 to 100 grams/metric ton). For maximum selectivity and effectiveness stage addition can be helpful.

Appearance

pH (as is)

pH (as 10% solution)

Specific Gravity

Freeze-thaw stability

Boiling Point

Freezing Point

Viscosity (centipoise)

Variable colored green to amber liquid

13

12

1.2 at 30°C (86°F)

Good

103°C (217°F)

Ppt Forms

Danaga Bawashia

None

Reagent Pourable

9°C (48°F)

Reagent Solidifies Below

9°C (48°F)

15 at 9°C (48°F) 7 at 30°C (86°F)

ENVIRONMENTAL PROPERTIES

BOD₆ (gms of BOD/gm of Reagent) less than .01 COD (gms of COD/gm of Reagent)

HANDLING

The aqueous AERO promoters are corrosive to a greater or lesser extent to most metals. It is recommended that the storage of either the strong or diluted solution of the product be in 316 stainless steel or in mild steel tanks equipped with a phenolic liner. Plastic or phenolic type pipe is suitable for transfer of the product in either the strong or diluted form.

TECHNICAL SERVICE

Technical service and information for making 50/55 the best use of this product are available Net 525 lbs., Gross 573 lbs., F.O.B. Warners, N.J. through your Cyanamid representative.

TOXICITY

Prolonged contact of the strong solution with the skin should be avoided. Where contact has been made, water in copious quantities should be used to cleanse. Alkali burns of the skin may result if protective gloves and goggles or face shields are not used during handling. In case of eye contact, wash eye in eye bath immediately for 15 minutes. If taken internally, vomiting should be induced, although the material is considered to be only mildly toxic.

SHIPPING

gallon non-returnable steel drums.

IMPORTANT NOTICE

The information and statements herein are believed to be reliable but are not to be construed as a warranty or representation for which we assume legal responsibility. Users should undertake sufficient verification and testing to determine the suitability for their own particular purpose of any information or products referred to herein. NO WARRANTY OF FITNESS FOR A PARTICULAR PURPOSE IS MADE.


Nothing herein is to be taken as permission, inducement or recommendation to practice any patented invention without a license,

Appendix K.
Ground Water Utilization Printouts

UTAH DIVISION OF WATER RIGHTS WATER RIGHT POINT OF DIVERSION PLOT CREATED TUE, MAY 26, 1992, 1:37 PM PLOT SHOWS LOCATION OF 99 POINTS OF DIVERSION

PLOT OF AN AREA WITH A RADIUS OF 21120 FEET FROM A POINT N 2000 FEET, W 1300 FEET OF THE SE CORNER, SECTION 34 TOWNSHIP 27S RANGE 11W SL BASE AND MERIDIAN

PLOT SCALE IS APPROXIMATELY 1 INCH = 10000 FEET



MAP		WATER	QUANTI CFS AND/C	TY		SOURCE DES	SCRIPTION O	r WELL	. INF	0	POI	NT (OF DIV	VERSI	ON DI	SCRIP	TION	, now	JA	PTEE	S	UPR GTE
CHAR 0	71	79/7	.0000 WATER USE(S): OTHE Noranda Exploratio		2 00	10	250	1041	ы	ы	1450	F	2250	SU	23	275	110	SI	X			* P U K
1	71	1444	.0000 WATER USE(S): IRRI Sullivan Land & Li	GATION	.00 L STOCK	Jnderground							160	S4 PRIO	29 RITY		10W 09/00	SL /1917		X	:	ĸ
2	71		.0000 WATER USE(S): IRRI Milford, City of					ι		N	10	W	240	PRIO	RITY	27S DATE: rd	06/21	/1940				K
3	71		1.5000 WATER USE(S): OTHE Toledo Mining Comp	R			d Water Wel 322 Newhou							PRIO	RITY	DATE:	02/21	/1957				K
			.7540 WATER USE(S): MINI Birch Ranch and Oi	NG il Compa	ny		427 West 5	th Str	eet					PRIO	RITY os Ai	DATE: ngeles	10/08	1/1947 C/	4			
5	71	3583	.0000 WATER USE(S): IRRI Bradshaw, Neil	IGATION	1.50 DOMEST	6 TIC STOCKWA	500 ATERING P.O. Box #	182		N	1480	W	1385	SE PRIO M	35 RITY ilfo	27S DATE: rd	11W 00/00	SL 1/1931 U1	r 8	x 4751	:	K
6	71	3785	.0000 WATER USE(S): IRRE Smith, Paul M. & 1		1.00	6	301	1988	Y	N	1225	W	886	NE	2 RITY	28\$ DATE: rd	11W 00/00	SL /1931		X		K
7	71	459	.0000 WATER USE(S): IRRI Sherwood, Jimmy M.	8 IGATION	7.31	14	200 P. O. Box	592		S	1420	W	1080	PRIO	RITY	28S DATE: rd	05/00	/1921				K
7	71	3644	.0000 WATER USE(S): IRR Smith, Paul M. & 1	IGATION Frudy L.	1.00 DOMEST	6 TIC	500 P. O. Box	969		S	1480	W		PRIO	RITY	28s DATE: rd	00/00	/1931				K
			.0000 WATER USE(S): STOO Sullivan Land & L	CKWATERI i vestock	NG Co.									PRIO M	RITY	DATE:	00/00	/1917 U	r 8	4751		
9	71	3686	.1500 WATER USE(S): OTHI Quality Market Co	ER rporatio	.00 n	6	100 - 200 P.O. Box #	699		S	558	E	267	W4 PRIO D	5 RITY elta	28S DATE:	10W 07/30	SL) 1/1984 U1	κ Γ 8	4624		K
A	71	2180	.0000 WATER USE(S): STOC Kirk, Nettie W.			Underground	d Water Wel	l		N	1370	E	970	PRIO	5 RITY ilfo	DATE:	10w 07/21	/1958		X 4751		K
В	71	565	.5010 WATER USE(S): IRR Board of Education				d Water Wel Beaver Cou						1160	PRIO		DATE:				X 4713		x
В	71	498	1.1140 WATER USE(S): MUN Milford, City of	ICIPAL	.00	12	439			s	1285	W	1160	PRIO		DATE:	10W 00/00	/1903		X 4751		X
В	71	500	1.0030 WATER USE(S): MUN Milford, City of	ICIPAL	.00	12	439			s	1285	W	1160	PRIO		DATE:	10W 00/00	/1929		X 4751		x
В	71	499	1.0030 WATER USE(S): MUN Milford, City of	ICIPAL	.00	12	439			s	1285	W	1160	PRIO		DATE:	10W 00/00	/1921	τ 8	X 4 7 51		x

MAP CHAR	W. R	ATER IGHT	QUANTITY CFS AND/OR AC-I	S FT D	OURCE DES	SCRIPTION C	YEAR LOG	FO NO	POI RTH	NT EA	OF DIV	VERSION CNR SE	DESCRIP C TWN	TION RNG B&	U N M	AP1 PEE PRF	SI	JPR GTE WPC
В	71	1226	.5880 WATER USE(S): MUNICIPAL Milford, City of	.00	12	439		s	1285	W	1160	E4 PRIORI	6 28S TY DATE: ford	10W S	SL 1946	X	2	(
В	71		1.7035 WATER USE(S): MUNICIPAL Milford, City of		12	439		S	1285	W	1160	PRIORI	6 28S TY DATE: ford	11/22/1	946			(
В	71		.5815 WATER USE(S): MUNICIPAL Milford, City of		12	439		s	1285	W	1160	PRIORI	6 28S TY DATE: ford	04/07/1	950			(
C	71	2826	.0150	.00 Un	derground	d Water Wel	. l	N	294	Ε	995		5 28s				,	K
			WATER USE(S): STOCKWATERIN Handley, Rozetta K.	4G		631 South	500 West						TY DATE: ford					
С	71	3606	.0000 WATER USE(S): IRRIGATION Handley, Rozetta K.	1.00	5	69		N	294	E	995	PRIORI	5 28S TY DATE: ford	10/01/1	920			(
С	a12		.0000 WATER USE(S): IRRIGATION Handley, M. E.		-			N	294	Ε		PRIORI	5 28S TY DATE: ford	09/21/1	981			(
D	71	922	.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family	.00	16			N	115	E		SW PRIORI	5 28S TY DATE: ford	10w s	L 927	x)	(
D	71		.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family			146		N	115	Ε		PRIORI	5 28S TY DATE: ford	06/00/1	927			(
D	71		.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family			146		N	115	E		PRIORI	5 28S TY DATE: ford	00/00/1	926			(
D	71		.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family			146		N	115	E		PRIORI	5 28S TY DATE: ford	06/00/1	927			(
D	71		.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family			146 P. O. Box		N	115	E		PRIORI	5 28S TY DATE: ford	06/00/1	927			(
E	71	922	.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family			145		s	1315	E	1380	PRIORI	8 28S TY DATE: ford		927	X 84751		(
Ε	71	924	.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family	.00 Trust)	16	145		S	1315	Ε	1380	PRIORI	8 28S TY DATE: ford	10W S 06/00/1	927	X 84720	,	(
E	71	1441	.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family	.00 Trust)	16	145		S	1315	£	1380	PRIORI	8 28S TY DATE: ford	10W S 00/00/1	926	X 84750)	(
Ε	71	923	.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family	.00 Trust)	16	145		s	1315	Ε	1380	PRIORI	8 28S TY DATE: ford	10W S 06/00/1	927	X 84751)	(
Ε	71	925	.0000 WATER USE(S): IRRIGATION Sullivan, Gary E. (Family	.00 Trust)	16	145 P. O. Box		s	1315	E	1380	PRIORI	8 28S TY DATE: ford	10W S 06/00/1	927	x 8475 l	,	(

CHAR	R	LIGHT	CFS	AND/OR	AC-FT	DIAMETER	DEPTH	YEAR LOG	NORT	Н	EA	ST	CNR	SEC	TWN	RNG	в&м	N I		U (GTI
F	71	3368	.0000 WATER USE(S): Sullivan, Gar	: IRRIGATI	200.00	16	640		S	40	Ε	1320	N4 PRIO	12 RITY	28S DATE:	11W 10/20	SL 0/1948	3	X	3	X
F	71	1646	.0000 WATER USE(S): Dalton, Stan	: IRRIGATI	ION STOCK	WATERING			s	40	Ε	1320	PRIO	RITY	28S 'DATE: 'sville	08/30	/1948	3			‹
G	71	3368	.0000 WATER USE(S): Sullivan, Gar	: IRRIGATI	I ON	16	420		S	50	E	70	PRIO	RITY	28s 'DATE: ord	10/20	/1948	3			(
G	71	1646	.0000 WATER USE(S): Dalton, Stan	: IRRIGAT	ION STOCK	WATERING			s	50	Ε	70	PRIO	RITY	28S DATE: sville	08/30	/1948	3			(
н :	71		.0000 WATER USE(S): Milford Indus	: IRRIGATI	ION DOMEST	TIC	nd Water Wel	ι	s	110	W	2020	PRIO	RITY	28S DATE:	05/00	/1912	<u> </u>			(
I	71		1.1140 WATER USE(S): Milford, City	: MUNICIPA		16	467		S	690	W	590	PRIO	RITY	28s DATE: ord	00/00	/1903	;			(
I	71		1.0030 WATER USE(S): Milford, City	: MUNICIPA		16	467		S	690	W	590	PRIO	RITY	28S DATE: ord	00/00	/1929)			(
1	71		1.0030 WATER USE(S): Milford, City	: MUNICIPA		16	467		S	690	W	590	PRIO	RITY	28S DATE: ord	00/00	/1921				(
I	71	1226	.5880 WATER USE(S): Milford, City	: MUNICIPA		16	467		S	690	W	590	PRIO	RITY	28S DATE: ord	10/14	/1946	•			(
1	71	1227	1.7035 WATER USE(S): Milford, City	: MUNICIPA		16	467		S	690	W	590	PRIO	RITY	28S DATE: ord	11/22	/1946	,			(
I	71		.5815 WATER USE(S): Milford, City	: MUNICIPA		16	467		S	690	W	590	PRIO	RITY	28S DATE: ord	04/07	7/1950)			(
1	71	498	1.1140 WATER USE(S): Milford, City	: MUNICIPA	.00 AL	12	110		s ·	930	W	275	PRIO		28S DATE: ord		/1903	,	X 84751)	(
1	71	500	1.0030 WATER USE(S): Milford, City		.00 AL	12	110		s ·	930	W	275	PRIO		DATE:	10W 00/00	/1929		X 84751)	(
1	71	499	1.0030 WATER USE(S): Milford, City		.00 AL	12	110		s '	930	W	275	PRIO		28S DATE: ord	10W 00/00	/1921		X 84751)	(
I	71	1226	.5880 WATER USE(S): Milford, City		.00 AL	12	110		s	930	W	275	PRIO		28S DATE:	10W 10/14	/1946		X 84751)	(
i	71	1227	1.7035 WATER USE(S) Milford, City	_	.00 AL	12	110		s !	930	W	275	PRIO		28S DATE:	10W 11/22	/1946		X 84 7 51)	(

MAP CHAR	WAT RIG		CFS	QUANTITY AND/OR	AC-FT	SOURCE DES DIAMETER	CRIPTION O	WELL INFO	O NOR1	H POII	NT O	F DI\	VERSION CNR SE	DE:	SCRIPT	TION RNG E	N	P	PT EE RR	ÚG	T
I 7	1 4		.5815 WATER USE(S) Milford, Cit	: MUNICIPA	.00 L	12	110		S	930	W	275		TY	DATE:	10W 04/07/	1950			X	
ı 7	1 4		.0890 WATER USE(S) Jefferson Me	: DOMESTIC	OTHER	Underground	Water Wel	ι	s '	1000	W	330	NE PRIORI Mil	TY	DATE:	10W 05/00/	1912			X	
J 7	'1 4		1.1140 WATER USE(S) Milford, Cit	: MUNICIPA		16	589		S	821	W	830		TY	DATE:	10 ₩ 00/00/	1903			X	
J 7	'1 5		1.0030 WATER USE(S) Milford, Cit	: MUNICIPA		16	589		s	821	W	830	NE PRIORI Mil	TY	DATE:	10W 00/00/	1929			X	
J 7	'1 4		1.0030 WATER USE(S) Milford, Cit	: MUNICIPA		16	589		s	821	W	830		TY	DATE:	10W 00/00/	1921			Х	
J 7	1 12		.5880 WATER USE(S) Milford, Cit	: MUNICIPA	.00 NL	16	589		s	821	W	830		TY	DATE:	10₩ 10/14/	1946			X	
J 7	71 12		1.7035 WATER USE(S) Milford, Cit	: MUNICIPA		16	589		s	821	W	830		TY	DATE:	10W 11/22	1946			X	
J 7	71 4		.5815 WATER USE(S) Milford, Cit	: MUNICIPA	.00 AL	16	589		S	821	W	830		TY	DATE:	10W 04/07,	1950			X	
J 7	71 4		1.1140 WATER USE(S) Milford, Cit	: MUNICIPA	.00 AL	7	102		S	830	W	780		TY	28S DATE: d	10W 00/00,	1903			X	
J 7	71 5		1.0030 WATER USE(S) Milford, Cit	: MUNICIPA	.00 AL	7	102		S	830	W	780		TY		10W 00/00,	1929			×	(
J 7	71 4		1.0030 WATER USE(S) Milford, Cit	: MUNICIPA	.00 AL	7	102		S	830	W	780	NE PRIORI Mil	TY	DATE:	10W 00/00	/1921			×	(
J	71 12		.5880 WATER USE(S) Milford, Cit	: MUNICIPA		7	102		s	830	W	780		I TY	28S DATE: d	10W 10/14	/1946		X 751	*	(
J	71 13	227	1.7035 WATER USE(S) Milford, Cit	: MUNICIPA	.00 AL	7	102		S	830	w	780		7 ITY Ifor	DATE:	10W 11/22,	/1946		X 751	>	(
J i	71 4	497	.5815 WATER USE(S) Milford, Cit	: MUNICIPA	.00 AL	7	102		s	830	W	780			DATE:	10W 04/07	/1950		X 751	>	(
J	71 -	498	1.1140 WATER USE(S) Milford, Cit): MUNICIPA	.00 AL	14	533		N	1250	W	1035		7 ITY I for	DATE:	00/00	SL /1903 U)	(
J	71	500	1.0030 WATER USE(S) Milford, Cit): MUNICIP	.00 AL	14	533		N	1250	W	1035		7 ITY lfor	DATE:	10W 00/00	/1929		X 751)	(

IAP CHAR		TER GHT		QUANTITY AND/OR A			SCRIPTION or DEPTH	WELL INF					VERSION DI CNR SEC			U N B&M N	PEE		
J 7	'1		1.0030 WATER USE(S): Milford, City	MUNICIPAL		14	533		N	1250	W	1035	E4 7 PRIORITY Milfor	DATE:	10W 00/00	/1921	X 84751		X
J 7	'1 1		.5880 WATER USE(S): Milford, City	MUNICIPAL	.00	14	533		N	1250	W	1035	E4 7 PRIORITY Milfor	DATE:			X 84751) I	K
J 7	'1 1		1.7035 WATER USE(S): Milford, City		.00	14	533		N	1250	W	1035	E4 7 PRIORITY Milfor	DATE:					K
J 7	'1		.5815 WATER USE(S): Milford, City	MUNICIPAL	.00	14	533		N	1250	W	1035	E4 7 PRIORITY Milfor	DATE:					K
K 7	'1		.4460 WATER USE(S): Union Pacific	IRRIGATIO	N DOMES	TIC STOCKW	ATERING OTHE	R	s	1315	Ε		NW 8 PRIORITY Omaha			SL /1916 NE		>	K
L 7	1 1		.0000 WATER USE(S): USA Bureau of	STOCKWATE	RING		nd Water Well 324 South S					1380	E4 10 PRIORITY Salt I	DATE:	08/30	/1948	X 84111) 1-23	
м 7	1 3		.0000 WATER USE(\$): Sullivan, Gar	RRIGATIO	N	16	. 660		s	2600	W	1330	NE 12 PRIORITY Milfo	DATE:		/1948	X 8475	1	K
м 7	'1 1		.0000 WATER USE(S): Dalton, Stand	IRRIGATIO	N STOCK	WATERING	660 P. O. Box 1		s	2600	W	1330	NE 12 PRIORITY Miners		08/30	/1948			K
N 7	′ 1	-	1.5600 WATER USE(S): Union Pacific	: IKKIGALIO	N DOMES	IIC OINCK	nd Water Well 1416 Dodge		S	50	W	740	E4 7 PRIORITY Omaha			SL 7/1909 NE)	X
0 7	71 2		.0000 WATER USE(S): Davie, Victor	STOCKWATE		6	79		S	1520	W	200	E4 7 PRIORITY Milfo	DATE:	11/22	SL 1/1946 UT		1	X
P 7	7 1		1.1140 WATER USE(S): Milford, City	: MUNICIPAL	.00	16	605		N	60	W	3390	SE 7 PRIORITY Milfo	DATE:	00/00		X 8475		X
Р 7	71		1.0030 WATER USE(S): Milford, City	: MUNICIPAL		16	605		N	60	W	3390	SE 7 PRIORITY Milfo	DATE:	00/00				X
P 7	71		1.0030 WATER USE(S): Milford, City	: MUNICIPAL		16	605		N	60	W	3390	SE 7 PRIORITY Milfo	DATE:	00/00				X
Р 7	71 1	1226	.5880 WATER USE(S): Milford, City	: MUNICIPAL	.00	16	605		N	60	W	3390	SE 7 PRIORITY Milfo	DATE:	10/14				X
Р 7	71 1	1227	1.7035 WATER USE(S) Milford, City	: MUNICIPAL	.00	16	605		N	60	W	3390	SE 7 PRIORITY Milfo	DATE:	11/22				X
P 7	71	497	.5815 WATER USE(S) Milford, City	: MUNICIPAL	.00	16	605		N	60	W	3390	SE 7 PRIORITY Milfo	DATE:	04/07				X

	R	ATER IGHT	CFS	QUANTITY AND/OR			DEPTH	YEAR	LOG	NOR			DF DI\ ST	VERS I CNR		ESCRIP TWN			JAP IPE IPR	ΕU	GT
		1648		0): IRRIGAT el Lee & S	.00 ION usan E.	16	351			s	60	E	290	PRIO M	RITY ilfo	28s DATE: ord	11w 08/30	7/1948 U	X 1 847 1 847	51	X
Q	71	1647	.0000 WATER USE(S Mayer, Russo Mayer, Richa): IRRIGAT el Lee & S	usan E.	16	351			s	60	E	290	PRIO M				/1948 U1	X 1 847: 1 847:	51	X
R	71		.0000 WATER USE(S Meyer, Russo Meyer, Richa): IRRIGAT el Lee & S	usan E.		370			S	1600	Ε	365	PRIO M			08/30	/1948 U1		51	X
R	71	1647	.0000 WATER USE(S) Mayer, Russo Mayer, Richa): IRRIGAT el Lee & S	ION usan E.	Underground	d Water We	lls		S	1600	Ε	515	PRIO M	RITY ilfo	28S DATE: rd rd	08/30	/1948 U1	X 847! 847!	51	X
s	71	1936	.0000 WATER USE(S; Milford City): IRRIGAT		Underground	d Water We	ιι		s	160	E		PRIO		28S DATE: rd		/1954	X 847		X
T	71	1808	.0000 WATER USE(S) Mayer, Leo 8): IRRIGAT		Underground WATERING	d Water We	l l		s	60	Ε		PRIO		285 DATE: rd			X 8475		X
U	71	103	.0000 WATER USE(S) Western Fari): STOCKWA	TERING	Underground ny (c/o Sa		ιι		N	810	W		PRIO		28S DATE: rd		/1903	X 8475		X
v	71		.0000 WATER USE(S) USA Bureau o): STOCKWA	TERING	Unnamed Dry					400 301	W		PRIO	RITY	28S DATE: Lake C	06/29	/1945	X 8411		x 303
w :	71		.0000 WATER USE(S) Tangren Fam	: IRRIGAT	ION DOMES	TIC STOCKWA		harlsto	n	s	70	Ε		PRIO	RITY	28S DATE: egas	11w 00/00	/1925	X 8701		x
w	71	1920	.0000 WATER USE(S) Tangren Fami): DOMESTI	C STOCKWA					S	80	E		PRIOF	RITY	DATE:					X
w	71	1921	.0000 WATER USE(S) Tangren Fam): DOMESTI	C STOCKWAT				ston	S	80	E		PRIOF	RITY	28S DATE: egas		/1926	X 8910		X
W	71	1919	.0000 WATER USE(S) Tangren Fami	: IRRIGAT				Charle	ston	S	90	E			RITY	28S DATE: egas	11W 10/00	/1926	X 8910		X
w	71	1807	.0000 WATER USE(S) Tangren Fami	: IRRIGAT				Charle	ston	s	90	E			PTTS	28S DATE: egas	11W 00/00	/1925	X 8910		X
W i	71	1408	.0000 WATER USE(S) Tagren Famil	: IRRIGAT			200 TERING			S	90	E		W4 PRIOF		28S DATE:	11W 10/00		x		X
W	71	1919	.0000 WATER USE(S) Tangren Fami	: IRRIGAT				Charle	ston	S	150	Ε			RITY	28S DATE: egas	11W 10/00	/1926	X 8910		X

MAP CHAR	WAT RIG	 QUANTITY SOURCE DESCRIPTION OF WELL INFO CFS AND/OR AC-FT DIAMETER DEPTH YEAR LOG			NT OF		VERS I		ESCRIPT	ION RNG	i	N I	A P T : P E E ! P R R !	U G	T E
W	71 18	.0000 .00 14 275 WATER USE(S): IRRIGATION DOMESTIC STOCKWATERING Tangren Family Trust (R. Tangren, Truste 3114 East Charleston		150	E	60	PRIC		28S DATE: egas	11W 00/00	/1925		X 89104	X	
W	71 14	.0000 .00 14 275 WATER USE(S): IRRIGATION DOMESTIC STOCKWATERING Tagren Family Trust, (R. Tangren, Truste	s	150	E	60		23 RITY	28S DATE:	11W 10/00			x	x	
x	71 19	.0000 .00 Underground Water Well WATER USE(S): DOMESTIC STOCKWATERING Tebbs, D. Ray P.O. Box #205 Rasmussen, Roger	S	330	W 1	030	P	RITY	28S DATE: itch ore	11 ₩ 00/00	/1926 U	Τ 8	X 84759 84631	x	
x	71 1	.0000 .00 Underground Water Well WATER USE(S): DOMESTIC STOCKWATERING Tangren Family Trust (R. Tangren Trustee 3114 East Charleston		330	W 1	030	PRIC		28S DATE: egas	11W 00/00	/1926		X 89104	x	

UTAH DIVISION OF WATER RIGHTS WATER RIGHT POINT OF DIVERSION PLOT CREATED TUE, MAY 26, 1992, 1:34 PM PLOT SHOWS LOCATION OF 9 POINTS OF DIVERSION

PLOT OF TOWNSHIP 26S RANGE 10W SL BASE AND MERIDIAN

PLOT SCALE IS APPROXIMATELY 1 INCH = 6000 FEET

	NORTH	
*	0 *	
*		
*	1	
*		
*		
*	2 *	
*		
*	*	
*	*	
*	· *	
*	*	
*	· *	
*	· *	
*	**	
*	· *	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*		
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	*	
*	* .	
*	*	
*	*	
*	*	

					APT	٠	
MAP CHAI		WATER RIGHT	QUANTITY CFS AND/OR AC-FT		PEE	U	GTE
0	71	2668	.0000 .00 I WATER USE(S): STOCKWATERING Seven Springs Ranch, Inc. The Plateau Partnership	eaver River	85936		x
0	71		.0000 .00 WATER USE(S): STOCKWATERING Seven Springs Ranch, Inc. The Plateau Partnership	PRIORITY DATE: 00/00/1860	X : 85936 : 85936		X
1	71		.0000 .00 WATER USE(S): STOCKWATERING Hatch, William C. & Hatch, Gard	eaver River PRIORITY DATE: 00/00/1860			X
1	71	2666	.0000 .00 WATER USE(S): STOCKWATERING Hatch, Frank & Hatch, Lottie	eaver River PRIORITY DATE: 00/00/1860 Scipio UI	X 84656		X
2	71	2667	.0000 .00 WATER USE(S): STOCKWATERING Hatch, William C. & Hatch, Gar	PRIORITY DATE: 00/00/1860			X
2	71	2666	.0000 .00 WATER USE(S): STOCKWATERING Hatch, Frank & Hatch, Lottie	leaver River PRIORITY DATE: 00/00/1860 Scipio U		••	X
2	71	2665	.0000 .00 WATER USE(S): STOCKWATERING Seven Springs Ranch, Inc. The Plateau Partnership	PRIORITY DATE: 00/00/1860	85936	ı	X
3	71	2664	.0000 .00 WATER USE(S): STOCKWATERING PEARSON, RALPH	P. Comp. Prince			X
4	71	2664	.0000 .00 WATER USE(S): STOCKWATERING PEARSON, RALPH	PRIORITY DATE: 00/00/1860	x r 84752		X

UTAH DIVISION OF WATER RIGHTS WATER RIGHT POINT OF DIVERSION PLOT CREATED TUE, MAY 26, 1992, 1:33 PM PLOT SHOWS LOCATION OF 23 POINTS OF DIVERSION

PLOT OF TOWNSHIP 25S RANGE 10W SL BASE AND MERIDIAN

PLOT SCALE IS APPROXIMATELY 1 INCH = 6000 FEET

NORTH

0

1
2 3

4 5

7 6

8

9

A

B

C

D


E

F

IAP CHAR	WATER RIGHT	QUANTITY CFS AND/OR AC-FT	SOURCE DESCRIPTION OF WELL INFO POINT OF DIAMETER DEPTH YEAR LOG NORTH EAST	DIVERSION DESCRIPTION N	PΕ	E	U G	
0 7	1 2613	.0000 .00	Beaver River		X		X	X
		WATER USE(S): STOCKWATERING		PRIORITY DATE: 00/00/1860				
		Carter, Lloyd C. & Mary Alice			847			
		Kristy Enterprises, Inc.	Box 325		847			
		Young, William R.			847	70		
		Weiss, Carl S.	2263 37th Avenue	San Francisco CA				
		Warthen, Merrill & Janice		Las Vegas NV				
		Ely, Bobby Lee		UT				
		Hafen, Norman		UT				
		Fortner, Herschell & Emma Trus	t (c/o Emm 4055 Vahe Circle	Las VEgas NV				
		Orcutt, James & Doris		UT UT				
		Taufiq, Farook & Sheerin	474/ 6 1					
		Powell, Richard L.	1314 E. Jessica		852	25		
		Cardon Investments	15 East Comstock Drive, Suite 1	Chandler AZ	652	رے		
. ,	4 2/47	0000 00	Beaver River		х		x	Х
1 /	1 2613	••••	peaver kives	PRIORITY DATE: 00/00/1860	••		•	
		WATER USE(S): STOCKWATERING Carter, Lloyd C. & Mary Alice	P. O. Box 2727		847	71		
		Kristy Enterprises, Inc.	Box 325		847			
		Young, William R.	50X 3E3		847			
		Weiss, Carl S.	2263 37th Avenue	San Francisco CA				
		Warthen, Merrill & Janice	2200 37 111 11141140	Las Vegas NV				
		Ely, Bobby Lee		UT				
		Hafen, Norman		UT				
		Fortner, Herschell & Emma Trus	t (c/o Emm 4055 Vahe Circle	Las VEgas NV				
		Orcutt, James & Doris	(0,0 2,1111 1022 12112 21112 21112	UT				
		Taufiq, Farook & Sheerin		UT				
		Powell, Richard L.	1314 E. Jessica	Las Vegas NV				
		Cardon Investments	15 East Comstock Drive, Suite 1	Chandler AZ	852	25		
					.,		.,	.,
27	1 2612	.0000 .00	Beaver River		Х		Х	Х
		WATER USE(S): STOCKWATERING	70/ 0 1 0 1 0 1 0 1704	PRIORITY DATE: 00/00/1860	841	11_	220	זר
		USA Bureau of Land Management	324 South State, Suite #301	Salt Lake City UT	041	11-	25	,,
, ,	4 2/12	0000 00	Beaver River		х		х	х
2 1	1 2612		beaver kiver	PRIORITY DATE: 00/00/1860	-			
		WATER USE(S): STOCKWATERING	324 South State, Suite #301		841	11-	230	J3
		USA Bulleau OI Laird Hanagement	SET BOUCH States but 100.					
7 7	1 2611	.0000 .00	Beaver River		Х		X	X
, ,	. 2011	WATER USE(S): STOCKWATERING		PRIORITY DATE: 00/00/1860				
		Daum, W. H. (and Staff)	600 East 8th Street	Los Angeles CA				
		buan, we no carre						
4 7	1 2611	.0000 .00	Beaver River		X		X	X
		WATER USE(S): STOCKWATERING		PRIORITY DATE: 00/00/1860				
		Daum, W. H. (and Staff)	600 East 8th Street	Los Angeles CA				
		•						
5 7	71 2578	.0000 .00	Beaver River		Х		Х	Х
		WATER USE(S): STOCKWATERING		PRIORITY DATE: 00/00/1860	0/1	4 4	27	0.7
		USA Bureau of Land Management	324 South State, Suite #301	Salt Lake City UT	841	11-	230	JS
				•	х		v	·
6 7	71 2608		Beaver River	PRIORITY DATE: 00/00/1860	^		^	
		WATER USE(S): STOCKWATERING			846	37		
		Watts, Wilford W.		Kanosii	040	,		
		2000 00	Beauer Biver		x		x	х
6	71 2608		Beaver River	PRIORITY DATE: 00/00/1860			••	-
		WATER USE(S): STOCKWATERING			846	37		
		Watts, Wilford W.		110110011	•			
, .	71 2404	.0000 .00	Beaver River		х		Х)
•	71 2609	WATER USE(S): STOCKWATERING	DOGTO, RITOI	PRIORITY DATE: 00/00/1860				
					0/4	11.	23	nτ
		USA Bureau of Land Management	324 South State, Suite #301	Salt Lake City UT	841	11-	~	~~

IAP CHAR	k R	JATER RIGHT	CFS	QUANTITY AND/OR AC-	-FT	SOURCE DIAMET	DESCRIP ER DE	PTION C	YEAR LOG	POINT OF NORTH EAST	DIVERSI CNR	ON DES	CRIPT	ION RNG B&M	N	P E P R	E (U G R W	i T ! P
7	71	2609	.0000)	.00	Beaver	River									X		X	X
			WATER USE(S)	: STOCKWATERI	ING						PRIO	RITY DA	ATE: (00/00/18	60				
			USA Bureau o	: STOCKWATERI of Land Manage	ement		324	South	State, Suit	e #301	S	alt La	ke Ci	00/00/18 ty	UT	841	11-	230	3
8	71	2681	.0000)	.00	Beaver	River					•							
-			WATER USE(S)	: STOCKWATERI	ING						PRIO	RITY DA	ATE: (00/00/18	60				
			Daum, W. H.	: STOCKWATERI (and Staff)			600	East 8	Bth Street		L	os Ang	eles		CA				
9	71	2681	.0000)	.00	Beaver	River									х		X	х
			WATER USE(S)	: STOCKWATER	ING						PRIO	RITY DA	ATE: (00/00/18	60				
			Daum, W. H.	: STOCKWATER! (and Staff)			600	East 8	3th Street		L	os Ang	eles		CA				
A :	71	2680	.0000)	.00	Beaver	River									х		X	Х
	•										PRIO	RITY D	ATE: (00/00/18					
			USA Bureau d	: STOCKWATERI of Land Manage	ement		324	South	State, Suit	e #301	S	alt Lal	ke Ci	ty	UT	841	11-	230	3
В	71	2680	.0000)	.00	Beaver	River									х		Х	Х
	• •			: STOCKWATERI							PRIO	RITY DA	ATE: (00/00/18	60				
			USA Bureau d	of Land Manage	ement		324	South	State, Suit	e #301	S	alt Lal	ke Ci	ty	UT	841	11-	230	3
С.	71	2679	.0000)	.00	Beaver	River									х		Х	х
			WATER USE(S)	: STOCKWATERI	ING						PRIO	RITY DA	ATE: (00/00/18	60				
			Daum, W. H.	: STOCKWATERI (and Staff)			600	East 8	3th Street		L	os Ange	eles		CA				
c :	71	2679	.0000)	.00	Beaver	River									x		х	X
			WATER USE(S)	: STOCKWATERI	ING						PRIO	RITY DA	ATE: (00/00/18	60				
			Daum, W. H.	: STOCKWATERI (and Staff)			600	East 8	3th Street		L	os Ange	eles		CA				
D :	71	2678	.0000)	.00	Beaver	River									X	2	X	X
			WATER USE(S)	: STOCKWATERI	ING						PRIO	RITY DA	ATE: (00/00/18	60				
			USA Bureau o	of Land Manage	ement		324	South	State, Suit	e #301	S	alt La	ke Cit	ty	UT	841	11-7	230	3
Ε :	71)			River									X	:	X	X
			WATER USE(S)	: STOCKWATER1	ING						PRIO			00/00/18					_
			USA Bureau o	of Land Manage	ement		324	South	State, Suit	e #301	S	alt Lai	ke Cit	ty	UT	841	11-7	230	3
F	71	2677	.0000)	.00	Beaver	River									X	;	Х	X
			WATER USE(S)	: STOCKWATERI (and Staff)	ING						PRIO	RITY DA	ATE: (00/00/18	60				
			Daum, W. H.	(and Staff)			600	East 8	Sth Street		L	os Ange	eles		CA				
F	71	2677	.0000)	.00	Beaver	River									X	:	X	X
			WATER USE(S)	: STOCKWATERI	ING									00/00/18					
			Daum, W. H.) : STOCKWATERI (and Staff)			600	East 8	3th Street		L	os Ange	eles		CA				
3	71	2676	.0000)	.00	Beaver	River									X	2	X	X
			WATER USE(S)	: STOCKWATER!	ING						PRIO			00/00/18					
			USA Bureau o	of Land Manage	ement		324	South	State, Suite	e #301	S	alt Lai	ke Cit	ty	UT	841	11-3	230	3
G .	71)												X			
			WATER USE(S)	: STOCKWATERI	ING					e #301	PRIO	RITY DA	ATE: (00/00/18	60				_
					_														

Appendix L.
Utah Division of Water Rights,
Selected File Information



220' with my pump have a Test From the collage d and send iF you will Lear Monk you Horman & Thompson

Form 114 25M 4-63 from Sec. 29

IN THE ____FIFTH ___JUDICIAL DISTRICT COURT, IN AND FOR THE COUNTY OF ___IRON _____ STATE OF UTAH

OI SU AR AL WA	THE MATTER OF THE GENERAL DETERMINATION F RIGHTS TO THE USE OF ALL THE WATER, BOTH RFACE AND UNDERGROUND, WITHIN THE DRAINAGE EA OF THE BEAVER RIVER-ESCALANTE VALLEY AND L TRIBUTARIES IN MILLARD, BEAVER, IRON SHINGTON, KANE AND GARFIELD COUNTIES IN UTAH. OTE: This blank is sent to you in accordance with Utah Law. The information called for herein will be used in concition with the adjudication of water rights on the above mentioned drainage area. All questions applicable to your claim ast be answered fully, and one copy of this form must be filed with the Clerk of the District Court at
	Name of Claimant Jimmy M. Sherwood
	P. O. Box 592 Interest Claimed full
	Address Milford, Utah 84751
3.	Name of particular moting making most parternax well, manusch sandrain from which water is diverted is
4.	Priority date claimed
	Date when work on diverting system was first begun Date when diverting system was completed
	Nature of work14 inch well, 200 ft. deep
5.	Class of Right (Indicate by X):
	(a)Right to surface water initiated by beneficial use before 1903 Claim No
	(c)Right decreed by court, cite title of case
	(d) xx. Application filed, State Engineer's Office No
	(e) Right acquired by adverse use prior to 1939
6.	Nature (Indicate by X), Amount, and Annual Period of Use (by month & day):
	(a).XXIrrigation
	(b)tototototototototototototo
	(c)Domestic Sec. Ft
	(d) Municipal Sec. Ft. (both dates incl.)
,	(e)
•	(a) Point of diversion from spring exempting exemptions, well, managed with a
	S. 1420 ft. and W. 1080 ft. from the NE Cor. Sec. 2, T288, R11W, SLB&M.
	(b) Description of spring area
	(c) Point of rediversion or point of return to natural channel
	(d) If flow is intermittently diverted, list by number or description, all rights involved
	(d) It now if intermittently diverted, fix by number of description, and rights involved
	Where water is used for irrigation purposes:
٠.	(a) Area irrigated in legal subdivisions of land by 40-acre tract. (All sources of water for same land or lands must
	be described in each instance by name or claim number).W.U.C459,218,1853on;
	39.00.acsNeknek, 40.00.acsNWknek, Sec. 2, I28S, R11W, SLB&M, or a
	total of 79-0 acres.
	Water.User's Claim. 459 is limited to the irrigation requirements of 21.8275 acres
	Water.User!s.Claims.459,218.and1853.arelimitedto.the.irrigationrequirements
	Diversion-any,-each,-or-all-claimsTotal-yearly-diversion-under-all-claims
	mentioned 286:51-acre-feetv
	(b) Do you get water under a ditch owned by several users
	divisions of interest
9.	Where water is used for Stockwatering:
•	(a) Number of each kind of stock watered
	(b) All sources of water for same stock. (Describe by mame or claim number)
10.	Where water is used for Domestic:
	(a) transport of tennered of mice education """"

(Describe by name or claim number)

	where water is used for municipal		
	(a) Name of city or town supplied		Population
	Number of families	Quantity of	of water
12.	Where water is used for a purpose	not above enumerated;	
	(a) Nature of Use	Extent of	i Use
,			
13.	Appropriation for Storage Purposes		
	(b) Location of reservoir by legal s	ubdivisions described by 40-acre tracts	
	(c) Maximum capacity of reservoir	in acre feet : Year construction	on commenced
	Completed: Wat	er first used Is reservoir locat	ed on or off stream
		to (both dates incl.).	
		. Maximum area in acres inundated	
		. Is reservoir drained each year Ma	
		for equalizing purposes	
			er canal is used, give maximum
	carrying capacity in sec. ft	***************************************	
14.	Diverting Works:		
		aterial composed of	
	Max. length M	ax. height	m
	at top		
	(b) Underground water diverting v	vorks: Is well flowing or pump	. Depth of well
	Diameter of well Le	ngth of drain	Depth of drain
	Diameter of drain, Length	of tunnelWidth of tunnel	Height of tunnel
	Type of pump Capac		
	(c) Surface and underground water	conveying works: Length of ditch to first place	of use
		dth of ditch at bottom Depth of	
		rial through which ditch passes	
		Diameter of pipe line	
	1000 feet	· · · · · · · · · · · · · · · · · · ·	Grade or pipe mae per
15		ppearance and waives service of summons or oth	her brocest
•	and another metal, the a	presence and warres service or summons of ou	ret process.
STA	TE OF UTAH		
3211	12 01 01	SS. (To be used if claimant is an individua	15
COL	INTY OF Beaver	So. (10 be used it claimain is all individual	'
		being first duly sworn, upon oath deposes	and says that he is the claimant
		read the foregoing statement of his claim and l	•
he h	125 signed the same, and that the ans	wers set forth therein are true to his best know	ledge and belief.
		Q. (\mathcal{F} . \mathcal{F}
		Signature	Mercioso
		() Signature	of Claimant
Subs	cribed and sworn to before me this	15th day of February	19 80
	,	()	1 11111 .
		Air)	no 17 XX ans
		NOTAR	Y PUBLIC
		-77	
CTA'	TE OF UTAH	\mathcal{O}	
JIM	IL OI OIMI	SS (To be used if also are to a surroute	
	IN TOTAL CON	SS. (To be used if claimant is a corporation	or an estate)
	NTY OF	,	•
		, being first duly sworn, upon oath deposes an	
		, of the above claimant, that he makes this	
		tatement of claim and knows the contents thereof,	
of sa	id claimant to said statement, that th	e answers set forth therein are true to his best	knowledge and belief,
Subsc	ribed and sworn to before me this .	day of	
			*
		•••••	
	,	NOTARY	

- Con to (log 71-35.

Examined . . REPORT OF WELL DRILLER Recorded: B. C. T. B. . Claim No. (2/ STATE OF UTAH Inspection Sheet Coordinate No. Co. GENERAL STATEMENT: Report of well driller is hereby made and filed with the State Engineer, in accordance with the laws of Utah. (This report shall be filed with the State Engineer within 30 days after the completion or abandonment of the well. Failure to file such reports constitutes a misdemeanor.) (1) WELL OWNER ... (12) WELL TESTS: Drawdown is the distance in feet the water level is low-ered below static level. Name Till Bulken Was a pump test made? Yes | No | If so, by whom?........ gal./min. with . feet drawdown after...... hours Yield: •• (2) LOCATION OF WELL: County Beauty Ground Water Basin


S. 1392 H. A W. Byre blank!

Some Start Star .. Bailer test .. gal/min with . feet drawdown after..... bours Arterian flowg p.m. Date_... Was a chemical analysis made? No 📋 Yee 🗆 Diameter of well. nf Section & (13) WELL LOG: Depth drilled 510 feet. Depth of completed well 510 feet. out viola not needed) NOTE: Place an "X" in the space or combination of spaces needed to designate the material or combination of materials encountered in each depth interval. Under REMARKS make any desirable notes as to occurrence of water and the color, size, nature, etc., of material encountered in each depth interval. Use additional sheet if needed. (3) NATURE OF WORK (check): New Well Replacement Well [] Decpening [] Repair [] Abandon [If abandonment, describe material and procedure:..... MATERIAL REMARKS (4) NATURE OF USE (check): Clay Sult Sand Gravel Cobbles Boulders Domentic St. Industrial Municipal | Stockwater [] Irrivation [] Mining [] Other 🔘 (5) TYPE OF CONSTRUCTION (check): Due Due Π Rotery 103133 Driven Bored 53 30 (6) CASING SCHEDULE: Threaded | Welded | 30000 6. " Diam. from 24 Cleet to 5 Wood Gage 48 Skenned " Dlam. from ... feet tofeet Gage ... " Dlam, from feet tofeet Gage ... Reject 🛘 New [] (7) PERFORATIONS: perforated t yes No [Type of perforator used . perforations from feet to ... perforations from feet to perforations from _____feet to_____ perforations from _____feet to _____ (8) SCREENS: Well acreen installed? Yes

No Model No..... Type Set from Slot size Dine (9) CONSTRUCTION: Did any atrata contain unusable water? Yes ... No G Type of water: Depth of strata_ 10- 12 18 Completed 10- 20 (14) PUMP: Manufacturer's Name Was it comented in place? Yes Depth to pump or bowles. feet (10) WATER LEVELS: Well Driller's Statement: feet below land surface Date This well was drilled under my supervision, and this report is true to the best of my knowledge and belief.

Name (Person, firm, or corporation) (Type or print) feet above land surface Date __ _ LOURCEIVED: (11) FLOWING WELL: (Type or print) ((() t) 1981 Controlled by (check) Valve Address Lease (Signed) Tompla RECEIVED Plus No Control CLIDAR CITY Poes well lesh around casing? Yes COLT 2 2 1982 No D License No. 1. 2 6 Date 10 - 20

Form 113-5M-12-60



REPORT OF WELL, DINILLER STATE OF UTAH 1988 Architetine 10, 77.9 25.5 (A. C.	7						7	1		;	Vı	• • • •	41.10					Term 113-3M-11-60
STATE OF UTAIL 1988 Chee In Proceedings of the Control Control Chee In Proceedings Chee In Proceedin	1914242	3785 1	. 7/-	1		41		t	.ISI	ILL	DR	ا را	YEL)F 1	T	'REPORT		
Consideration of the Control of the		•							8	138	11	πÌΛ	or (VTE	ST	1		
CINNEIRAL STATEMENT: Report of well driller is hereby made and filed with this State Englaver, in accordance with line is a complete or a shared with the State Englaver in accordance with a 20 days after the completion or a shared more of the well. Failure to it reports constitutes a misberneous constitute to it is a constitute of the completion or a shared more of the well. Failure to it is a constitute to it is a constitute to it is a constitute of the completion or a shared more of the well. Failure to it is a constitute to it is a constitute or it is a constitute to it is a constitute or it is a constitute to it is a constitute or it is a constitut															-	_	· · · · · · · · · · · · · · · · · · ·	Inspection Sheet
(This report shall be will the state of guide within the state of guide emptication of middle will be state of guide the property constitution of middle will be state of the																		
Home Part Second Secon	to file such	ell. Failure	cordinaco L the we	in i	er,	z Ine unde	En;	or	Sta Lion	the	toi:	ed ' live	nd fil fter l	ido n nys r	30 c	ller is hereby incer withIn 3	illicit with the State wolling	(This report shall be
Comparison Com	re Josef to Jose-	n feet the wate	distance in	h th	** (w days helo	Dia		S:	ST	TI	IJ	WE	12)	T		HER:	(I) WELL OWN
The continue of the continue									i en	. T	mad	test	pittnp !	/a= =	. .		5mith	Hame Paul S
(2) LOCATION OF WELL: County Cockes Grower West West Falling (Interplating County of Cockes) First Falling Control (Interplating County of Cockes) First Falling Cockes Grower West Cockes C	heers	wn elter	t diamdon					with	ıln.	a1./m				1-14 :	<u>.</u> ,	<u> </u>		
Country Coun												••••					OF WELL:	(2) LOCATION
State 1/2	heurs	own after	eal drawdo					n. v	l./mi			*****	aat	aller i	٠,		Ground Water Basin	• • •
Seath A T. 28 to 1															1.		(leave blank)	
of Brethe 2 T 28	U 100 U	madet lin	1 analysis	hem	•	1 V e e					ater	1 %	sture :	ciulisi	' ·	ALI=Corner	TTO feet fram.	Booth
Tree April Construction Cons	Inches	6 "	-11							16.	1.0	1.1.	WE	17)	. :	SLIIM		2
(3) NATURE OF WORK (check): Replacement Well December Decembe															Ί.	M, REH	T	
If shandament, describe material and precedure.																	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
If shandament, describe material and precedure.	i material ea-	nature, etc. a l.	interval. der, size, if meeded.	i her	nnd	1.		[~/	ent erne	relate Cogni	me!	, of	Ination e mate			, .		
(4) NATURE OF USE (check): Dimettle X Industria! Nundelpal Stechwater U (5) TYPE OF CONSTRUCTION (check): Ratur Dimetel Diver Dimetel U (6) CASING SCHEDULIS: Threaded Wader Market U (6) CASING SCHEDULIS: Threaded Wader Market U (7) PERFORATIONS: Threaded Wader Market U (8) CASING SCHEDULIS: Threaded U (9) CASING SCHEDULIS: Threaded Wader Market U (10) CASING SCHEDULIS: Threaded Wader Market U (11) PERFORATIONS: Threaded U (12) PERFORATIONS: Threaded U (13) Particular and Market U (14) PURITY Market Market U (15) SCREENS: Well several hatalised X (16) CASING SCHEDULIS: Threaded U (17) PERFORATIONS: Threaded U (18) SCREENS: Well several hatalised X (18) SCREENS: Well several hatalised X (19) CONSTRUCTION: (10) CONSTRUCTION: (10) CONSTRUCTION: (10) CONSTRUCTION: (10) CONSTRUCTION: (11) Particular and packed Y (12) Perforation from Cet U (13) Particular and packed Y (14) PUNIP: (14) PUNIP: (14) PUNIP: (15) PROPERTOR PROPERTOR PROPERTOR (14) PUNIP: (15) PROPERTOR PROPERTOR (16) PROPERTOR PROPERTOR (17) PERFORATION PROPERTOR (18) PROPERTOR PROPERTOR (18) PROPERTOR PROPERTOR (18) PROPERTOR PROPERTOR (18) PROPERTOR PROPERTOR (19) PROPERTOR PROPERTOR (19) PROPERTOR PROPERTOR (10) PROPERTOR (10) PROPERTOR (10) PROPERTOR (10) PROPERTOR (11) PROPERTOR (12) PROPERTOR (13) PROPERTOR (14) PUNIP: (14) PUNIP: (15) PROPERTOR (16) PROPERTOR (17) PROPERTOR (17) PROPERTOR (18) PROPERTOR (19) PROPERTOR (10) PROPERTOR (10) PROPERTOR (10) PROPERTOR (11) PROPERTOR (12) PROPERTOR (13) PROPERTOR (14) PUNIP: (14) PUNIP: (15) PROPERTOR (16) PROPERTOR (17) PROPERTOR (18) PROPERTOR (18) PROPERTOR (19) PROPERTOR (19) PROPERTOR (10) PROPERTOR (10) PROPERTOR (10) PROPERTOR (10) PROPERTOR (11) PROPERTOR (12) PROPERTOR (13) PROPERTOR (14) PROPERTOR				-11-											[]			
(4) NATURE OF USE (check): Description Moning Other Text Well Other Text Well Other Text Well Other Other Text Well Other O				-	7		<u>-</u> ,		T		_	-,		DE	. .			A. The state of th
(4) NATURE OF USE (check): Dementic X Industrial U Mondreal U Stockwater U Stockwa		9FW1888				3							- 1		<u>:</u>			
TYPE OF CONSTRUCTION (clack): Aging X		HEMANAS	1		اپ	ğ	1	5		_							F USE (check):	(A) NATURE OF
TYPE OF CONSTRUCTION (cluck): Relaty Mark Date Jetted						ž.	3	pp.o.	4		#	3	,	8	,	Stockwater []		<u>.</u>
(6) TYPE OF CONSTRUCTION (check): Ratary & Date Jetted J. 16				- -	-	_		[<u>-</u>	<u> </u>	" "	-	븨		l•• :	. ي	Feet Well U		
Relief U Diriem D Bleered U 54 8-7		, Deil	160	- -	- .	_ .	-1		- -	_ _	- 1	_		<u>0</u>	٦,	k):		
Cobble U Driven U Bloved U Steel U Ste				- -	- -	-1-	-1			_ X	X.	-		_2	, ر	retted []		
(6) CASING SCHEDULE: Threaded Westerd 24, 27, 19 6. "Diam. from				- -	- -	- -	-	-	<u> </u>	- -	싀	-			- 1			
Blam. from 24 feet to Geet Gaes 54				- -	- -	~ -		-		- -	- -	Š			<u>.</u> .			
"Dlam. from feet to feet Gas. "Dlam. from feet to Gas. Miled Miled Type of preferations // Inches by Jacks by Jest to 2.24 feet to 12.50 perforations from from feet to feet to gas. Perforations from from feet to feet to perforations from feet to feet to gas. Perforations from from feet to feet				- -	-[-	- -	-	-	-	- -	-1	1 1					HISDUINS: Threaded	(6) CVBING SC
Piem Relect Used Used							_		-	- -	-1	^_	الميور]	Casa	gay leet toleet to	
Reject				_ -	_	_ .	_	_							_ [
(7) PEHFORATIONS: Preferentedly Yee No				- -	-1	_ -	-	_	- -	_ _	_	_			<u>.</u>	Uard []		
Type of perferations with				- -	- -	- -	-	-	- -	- -	-	-			- -		TONG	
Blee of perferations 198 Inches by 2 Inches 1280 perferations from 304 feet to 224 feet		1		- -	- -	- -	-	-	- -	- -	-	-			. .	D 110 D	milled	\'
Descriptions from SOY Seet to Seet				- -	- -	-1	-	-	1-	- -	-	-			. -	lnehee	1/8 Inches br 3	at a standing
perforations from				_ _	_[.									_	۱ ا	124 100	10m 304 Jeel to 20	128 Uperforations f
Diam. feet to feet fee				- -]	_[.	_	_	- -	_ _	_	_					fromfeet lo	perforations f
Description from				- -	- -	-1	-		- -	- -	_	-			- I -		remfeet to	perforations f
(8) SCREENS: Well acreen installed I Yes 10 U Manufacturer's Name 10 to size 10 U Diam. 10 to size 10 U 10 Diam. 10 to size 10 U 10 U Was well grarel packed I Yes 10 U 10 U To what depth 20 feet 10 U 10 U Type of water 10 under 10 under				- -	- -	-1	~		- -	- -	-	-					rem feet lo	perforations f
Model No. Diam. Slot size Set from IL to Size of search Set from III to Size of gravel set in Set from III to Size of gravel set in Set from III to Size of gravel set in Set from III to Size of gravel set in Set from III III III III III III III III III I				-11-	-	-	-	-	-	- -	-	-			=			
Diam. Slot size Set from IL to Size of search Sear					-[_	1-	- -	- -	-	-			1	□ 10 £	Well screen Installed Yes	(8) SCREENS:
Diam. Slot size				_ -	_					_ _		_			-			
Disam				_∥.	_	_	_	_	- -	_ _	_	_			-			
(D) CONSTRUCTION: Was well gravel packed? Yes A 10 Bise of gravel. 36 Gravel placed from 304 feet to 20 feet To what depth? 20 feet Material used in seals Been honite Did any strata contain unusable water? Yes D 210 X Type of waters. Method of sealing strata off: Was surface ensing used? Yes U 20 X Was surface ensing used? Yes U 20 X Type? Manufacturer's Name. Type? Manufacturer's Name. Type? Manufacturer's Name.				- -		-1	_	-	- -	- -	-1	_			_			DiamRiot ele
Was a surface seal provided 1 Yes of 210 To what depth 1				- -	-	-1	-	-	- -	- -	-	-			=			
Was a surface scaling strata affi Was surface casing strata affi Was surface casing strata affi Was surface casing strata Type of water 1 Was surface casing strata affi Was surface casing strata Type of water 2 Type of water 2 Was surface casing strata Type of water 2 Type of water 2 Was surface casing strata Type of water 2 Type of water 2 Was surface casing strata Type of water 2 Type					-	-1	-	-	- -	- -	-	-				3/5	AIUN:	(0) CONSTRUC
Was a surface and provided? Yes \$\infty\$ 110 \\ To what depth!				_ -		_}	_			_ _		_				Ofeet	1 Yes 10 11 10 11 10 20	17aa well gravel packed
To what depth 1				- -	-1	_		_	- -	_ _	_	_				0	ided 1 Yes M 210	Gravel placed from
Haterial weed in seals				- -	-		-	-	- -	- -	-	-	<u> </u>		1		a o	m -1.1 death1
Did any strata contain unusable water? Yes U 10 X2 Type of water! Depth of strata Weith started				- -	-1	-	-	╁	-	- -	-	-			-		Ben tonite	Material waed. in sents
West author conting weed! Was swifted conting weed! Was swifted conting weed! Was swifted conting weed! Type: Type: Was swifted conting weed!						-	-	┢	- -	- -	-	-					unnantis water i Yes U	Did any strata contain
Was surface earling weed! Tes U No D Manufacturer's Name	88.11_	7-18-5	leted	Co			8	8	3 ~	7-1					-	stratu		
Was entined enting weed! Yes U No N Manufacturer's Name					<u> </u>		<u>:-</u>	-							_		1 eli	Method of scaling strate
West swifted casing world to U No D Types														٠.	_			
TW It assessed in place 1 100 U 100 U		N. F							•		iami	• }	acturer			(11 Yes [] No	Was surface earling word
Was It comented in pince										rtes	 r ha	 T			=	, ()	cel Yes U Ha	Was It comented in plac
(10) WATER LEVELS: Well Driller's Statement:																	EVELS:	(10) WATER L
	ort la true lo	nd this repo	delon, ar	upe	y e	r m	ıde										feet below land ourface. Date	Blatle level
Attrolous pressure	11. u. T	.11 2-	111		١.	clie	d b		edg	owle	, ki	m	cat of	the l	<u></u>		feet alove land surface Itala .	Astrolan pressure
LOG RECEIVED: (11) FLOWING WELL: Name (7:2: mrthyw & Song Well Ville) (Type or p (Freen, flim, or corporation)	or poldi	<u> </u>	ω_{ϵ}	بدي	.5	/ len 1	/ ·	7.4	114	35		7 · Z		Nam	_			· · · · · · · · · · · · · · · · · · ·
LOG RECEIVED (11) PLOTITION IT DOD. (Person, them, or corporation) = Certary City Ut	U 847	City L	Cedar	Ē	1	10	عر کے	F	Ü	4	•••• 5-7/	4		A ,1.1.	İ			
RECENTED to rebeck) Valva U Addican 4514 0 670 Cap U Plus U No Control U (Slened)							1	N/	7	- []	Je.	E		/61	ا ن			RECE
Cap U Flug U No Control U (Signed)		e &	riller)	Well	(····				, 34° . 3	ica)	(91K)	ן ט	•		
AUG 1 1988 No U Licensa No. 5/4 Date 7-28-85	, 15	88	-28-			nte	. D			4	<u>51</u>) .	nn No	Mee	u			· Alig 1

WATER RIGHTS CEDAR CITY

USE OTHER BIDD FOR ADDITIONAL REMARKS

corrent

MICROFILMED

Form 113--5M--12-60

Examined 15-22-67 / FD Recorded: B. C. J. 22-47 V. ACT. B. L. C.
Inspection Sheet J. 22- 67 B. W.
Copied J. J. 67 B.

REPORT OF WELL DRILLER STATE OF UTAH

	1	4-19178	,
Application	No.	a _5084	(71-1918)
Claim No			· · · · · · · · · · · · · · · · · · ·
Coordinate	Noll	二-28-/1人	34 db2

GENERAL STATEMENT: Report of well driller is hereby made and filed with the State Engineer, in accordance with the laws of Utah. (This report shall be filed with the State Engineer within 30 days after the completion or abandonment of the well. Failure to file such reports constitutes a misdemeanor.)

(1) WELL OWNER:	(12)	WE	LI	T	ES	TS	3:		Dre	awde d be	wn low	is the distance in static level.	feet the water level i
Name Birch Ranch & Oil Company Addres 27 W. 5th St. Los Angoles												so, by whom?	
					-	./m	in.	w I (.)	h			[eet drawdow!	
(2) LOCATION OF WELL:												 .	
County Braver Ground Water Basin (leave blank)													n after
North 2254 Feet 1720 feet from SE Corner Skiph												g.p.m. Date	
SAUCH West							-		=				
of Section 34 T 27 N R 11 X SLBM (strike	(13)	WE	L	. I. 591	OC 3	÷:			•	Dia	nete	r of well	593
out words not needed)													
(3) NATURE OF WORK (check): New Well D Replacement Well December Repair Abandon	or com desirab	binatio le note	n o	f me	eteri	als curr	ence	oun	tere	d In iter	and	h depth interval. L the color, size, no	d to designate the moinder REMARKS male sture, etc., of materi
Replacement Well Decement Repair Abandon Life abandonment, describe material and procedure:			eacr	ı aeı	ptn					a a a i	Liona	I sheet if needed.	
		PTH	-		1		ATE	LKI	<u>.</u> .		-	-	
										rate		l.	REMARKS
(4) NATURE OF USE (check):	_					-		Ę	Den	lome	뉳	.	REMARKS
Domestic Industrial Municipal Stockwater	From	£	Ä	Sit	Sand	Srev	opp	Boll	Hard	Cong	e d		
Irrigation Mining Other Test Well			F	-	М	-	Ŭ	_	_	-	-	<u> </u>	
(5) TYPE OF CONSTRUCTION (check):	<u>0</u> 140	140 163	-	X.	x	X	\vdash	-			+	-}	
Rotary Dug Jetted		241	<u> </u>	\vdash	x	y.		^		П			
Cable Driven Bored D		250	x							П	\Box	-	
(6) CASING SCHEDULE: Threaded Welded		25/4	-	Н	x					\dashv	-		
10 " Diam. from 0 feet to 374 feet Gage 250 8 " Diam. from 376 feet to 503 feet Gage 250	25/1	270 283	X	Н	\vdash	x		x	\dashv	\dashv	+		
"Diam. fromfeet tofeet Gage	270 283	304			x	x		_			J		
New 🖸 Reject 🗆 Used 🖸	304	320	x	匚	П	x	\Box		\Box		\bot	4	
(7) PERFORATIONS: Perforated? Yes No		321	L		Н	_	$\vdash \vdash$	×	\dashv	\dashv	+		
Type of perforator used Forch	327	329	-	Η,	x	×	\vdash	x	-	\dashv	+	 	
Bize of perforations 12 inches by 4 inches	300	335	×	-		x	Ħ	^		7	+	1	
perforations from 190 feet to 191 feet	335	365			х								
perforations from 170 feet to 503 feet	365	372	L			x	_	х		_	_	- 	
perforations fromfeet tofeetfeetfeetfeetfeetfeetfeetfeet	372	373	-		x	x	-	\dashv	-		+	_	
perforations fromfeet tofeet	373 375	275 401	×	Н	Н	x	\dashv	Х	-	\dashv	\dashv	1	
	401	453				x							
(8) SCREENS: Well screen installed? Yes	453	50/1	x			x		_	_	_	_ _		
Type Model No	504	540	 -	Н	X	$\overline{}$	-	\dashv	\dashv	-			
DiamSlot size Set fromft. to	540 550	550 563	×	-	×	X	\dashv	-	7	-	+		
Diam. Slot size Set from ft. to	563		×	-	<u> </u>	^	\exists				_		
(9) CONSTRUCTION:							\Box			_	4		
Was well gravel packed? Yes 🗆 No 🗵 Size of gravel:			-		Н	-	\dashv		-	-	\dashv	-	
Gravel placed fromfeet tofeet			-	Н	\vdash			-	-	-	+	-	
Was a surface seal provided? Yes													
Material used in seal:						_		_	_	_	_	-	
Did any strata contain unusable water? Yes No			-	Н	Н		\dashv	-	-		+		
Type of water: Depth of strata		لــــا	L	لـــا	<u></u>	4	L!						
Method of sealing strata off:	Work s			_		_	<u> </u>	-		. 19		Completed	
	(14)												
Was surface casing used? Yes \(\bar{\Delta} \) No \(\Bar{\Delta} \) Was it comented in place? Yes \(\Bar{\Delta} \) No \(\Bar{\Delta} \)	Manufs Type	icturer'	• 1	lame	•	•				· - · ·			п. Р
Was it cemented in place? Yes No 💆	Depth	to pum	ро	r bo	wles							feet	<u></u>
(10) WATER LEVELS:	Well	Drille	r's	Sta	iter	ner	ıt:						
Static level 295 feet below land surface Date	Т	his w	ell	wa	ıs d	ril	led					upervision, and	this report is tru
Artesian pressure . feet above land surface Date	the be	est of	m	kr	now	led	lge	and	d b	elie	ſ.	any	
LOG RECEIVED (11) FLOWING WELL:	Name	(Per	юπ,	fire	n, o	or co	гро				<u></u>	(Type or print)
Controlled by (check) Valve	Addre	ss M	ili	:4	<u>'d,</u>	يا	Ita	h	†A	/		f	
Plus No Control	(Sign			Ų.,	: Z	7.		Þ	(fr	n	1	Vell Driller)	
			//	,	,								
Then well leak around caning? Yes	Licens	an Na	_	(ℋ				1),,	LC			19

Milford, Utoh.

87161 ON NOITASILAGA

man property of the property of the party of

KEY MAP 5006 3000 5 | "

5#

isted on well record		•		₩.	• •
Justed by counties	V-5-24-48				Report No6163.
oral Copy checked 19	4.6-1-18	PAGI	(Lenve Blank)		Rec. By
Plated Ello Acama no i mgh. 432	-48 R	port of Wel	l and T		Ret'd
erited MT eritetti velitto .C:27~11)04 da b. 1	STAT	TE OF UT	cah	riiiei.
	GENERAL INFOR		shall be filed for each	well or tunnel)	
	Report of well with Sec. 100-3-22.	or tunnel driller is herel Utah Code Annotated, er the completion or aba			
	1. Name and addr	ess of person, comp any	or corporation	boring or drillin	g well or-tunnel.
	Archie (. Myers - 2	117 Ban	words not needed)	Kers Field, Calic
	2. Name and addr	ess of owner of well or-	tunnel-		
	Metal	Ltoducers	COrp. /	Villow	Man
	3. Source of supply	is in Bealler		·	County
	(Lenve	drainag	çe area ;	(Leave blank)	artesian basi
		approved application to			
<i>N</i> . 1	N.G. Sec. 3 - 7	lor-mouth of tunnel is	situated at a p	ointN65-L, LN.	4850FT. 1-you

		rectangular co-ordinates or by one Corner — Copy description fro Vork on Well or-tunnel w	vas begun	10-23	Jovernment Survey — 47
		vork on well or-tunnel v	(Strike w	vords not necded)	2-15-47
	8. Maximum quant	ity of water measured a	Strike w Siflowing, pump Strike w	vords not needed) Ocd or NG ACC	ent at on completion o
	well o r tunnel in	sec.=ft. ?	; or in gals. per	· minute?	Date
	DETAIL OF COLLE	CTING WORKS:			_
		illed, dug, flowing or pun	(Strike w	ords not needed)	r
	(a) Total depth	of well is500	2ft. below gro	ound surface.	
	(b) If flowing w	ell, give water pressure	(hydrostatic he	ead) above grou	nd surface NA ft
	(c) If pump well	, give depth from groun	d surface to wa	iter surface befo	re pumping 2.74
	Pumling		; during [pumping?	
	(d) Size and kin	d of casing 341 Ft.	oF 16"X %	3 1621	T. E 14"XX
	(e) Depth to wa	ter-bearing stratum4	28Ft	;;	
	(f) If casing is p	erforated, give depth fr	om ground surf	ace to perforation	ons 380 Ft.
	(g) Log of well.	0-82 Lar	a Flow E	F;://- 82'-	85 Bouldors
	85-11c	Gravel & Boul	ders 110'-	-160 Clay	1-Gravel
	160-/6.	5 Boulders 16. 15 Boulders	5-210 (lay + Gra	zvel
	<10-2	15 Doulders	K15-25	7 Cours	e sandy Clay
	(see remark	06 Clay + Gx	avel 306	2-3540	onglomerate
	(h) Well was equ	1.5 Doulders 2 206 Clay + Gr ipped with cap, valve, or	OF X (Strike w	ords not needed)	to control flow.

(Over)

	(a) Dimensions; total length; temperature of water°F.
	(b) Position of water bearing stratum or strata with reference to mouth of tunnel
	(c) Log of tunnel
/	
11.	GENERAL REMARKS: (Note any general or detailed information not covered above).
	continued hog of Hole
	354- 389' Course sandy Clay
	389'- 478 SOFT CONZLONIErate
	478-481 SAND (Wet)
	481-497' De COMPased Granite 497'-500' Granite
	•
	· ·
STAT	E OF UTAH, ss.
	TY OF NEW AND THE
staten	eby certify that I am the driller of the aforesaid well or tunnel who furnished the foregoing tent of facts; that I have read said statement and each and all of the items therein contained up to the best of my knowledge and belief.
	By V. T. Piccao forman
s	ubscribed and sworn to before me this
(SEA	() Notary Public
Му Со	ommission Expires:

i